

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>1</b>	<b>3</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>6</b>	<b>1</b>	<b>6</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 10.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	leeza	Mitta Doddy	33KV	Gadwal	23.30	23.50	00.20	O/L	Due to Pin Insulator failed		Alternate Supply Arranged from 33KV Gattu feeder at 23.50 hrs

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 10.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Chinnarevelly	11KV	Jadcherla	12.05	15.40	03.35		11Kv Phase To Phase Sarojini Poultry Back Side.	-
1	NLG	Keethavarigudem	Kothagudem	11KV	Huzurnagar	07.20	09.10	01.50	E/L	11Kv Line Snapped	-
2		Voligonda	Voligonda	11KV	Choutuppal	05.05	07.38	02.33	EL/OL	11 kv Line snapped at Rajiv Gandhi chowrsta voligonda town	-
1	RR N	Chintal	Ganesh Nagar	11KV	Medchal	13.45	14.08	00.23	BD	Backfeeding arranged from HMT SS to Ganesh Nagar feeder(UG Cable failed)	-
2		Nuthankal	Bharathi	11KV	Medchal	09.10	10.10	01.00	BD	11KV Line Cut & Replaced at Goshala, Nuthankal	-
1	HYD S	C.R.P.F	Omar Colony	11KV	Charminar	00.05	01.15	01.10	EL,OL	Cable fault at Allahamdulla Hotel	Arranged B/F on 11KV Anwar Mirchi feeder