

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		4		4		4			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		1		1		1			
3	MDK	107	933	2		2		2				
4	SDPT			2	5	2	5	2	5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>8</b>	<b>4</b>	<b>8</b>	<b>4</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>4</b>	<b>16</b>	<b>4</b>	<b>16</b>	<b>4</b>	<b>16</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 10.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Pashamailaram	EPIP II	33KV	Sangareddy	08.55	10.45	01.50		B/D Due to Conductor Snapped	EPIP II	-
2		Pashamailaram	Manjeera	33KV	Sangareddy	13.07	13.45	00.38		B/D Due to Insulator Failure	Manjeera	-
1	SDP	Hubshipur	Pothareddyoet	33KV	Siddipet	00.45	05.40	04.55	B/D	B/D ( Tripped On EL )	Pothareddyoet	-
2		Hubshipur	Khajipur	33KV	Siddipet	00.00	07.50	07.50	B/D	B/D ( Tripped on EL )	Khajipur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 10.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Manthangoud	Katrevpally	11KV	Narayanapet	12.30	13.00	00.30		Breakdown due to disc failure	-
2		Perapally	Perapally AGL	11KV	Narayanapet	07.05	09.45	02.40		Due to Loose Line contact, Jumper cut touched to the V Crossaram	-
1	NLG	Gondiryala	Gondiryala-2	11KV	Huzurnagar	03.00	07.00	04.00	EL	11 KV LINE SNAPPED	-
1	SDP	Thadkapally	Thadkapally	11KV	Siddipet	03.30	08.10	04.40		B/D due to Conductor cut	-
2		Mallaram	Sikindlapur	11KV	Siddipet	09.40	11.29	01.49		B/D 11kv line cut	-
3		Mirdoddy	Mirdoddy AGL	11KV	Gajwel	07.57	17.30	09.33		B/D Insulator failed	-
4		Erraveely SS	Police station Feedre	11KV	Gajwel	19.18	10.43	15.25		Disk File and Cupur patti burnt	-
5		Ramchandrapur	Varikolu	11KV	Husnabad	11.10	13.50	02.40		Jumper cut	-
1	RR N	Petbasheerabad	Satyam Enclave	11KV	Medchal	13.30	14.25	00.55		No Fault	-
2		Athiwelly	PHI	11KV	Medchal	12.20	13.25	01.05		11KV Jumper Cut & Replaced at Rekula Bhavi	-
1	RR E	Cherlapally	Rampally	11KV	Keesara	17.00	18.15	01.15		Tree branches fallen on 11KV line near Telephone Exchange	-
2		Singapur	IT Park	11KV	Keesara	11.50	13.00	01.10		11KV Cable fault near Shobha Construction	-
1	HYD N	Road No.22	Road No.5	11KV	X	10.48	12.45	01.57	EL	Breaker fault at SS & Pin Insulator flash over at Karur Vysya Bank	Arranged B/F on 11KV UCO Bank fdr
2		Road No.22	Road No.5	11KV	X	20.40	22.32	01.52	EL,OL-Rph	Cable End Kit fault at ICICI Bank	-----
1	HYD S	Osm. Hospital	Puranapool Cable	11KV	IX	14.10	16.37	02.27	EL,OL-Bph	RMU Cable fault	Arranged B/F on 11KV Gyanbagh Colony fdr
1	HYD C	Chilalguda	44 Bus Stop	11KV	II	19.35	21.09	01.34	EL	Tree branches on lines at MCH Park	20:35 Hrs partial feeder charged