

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	8	0	8	0	8	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	1	2	1	2	1			
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933	1		1		1				
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	10	4	10	4	10	0	0	
	Grand Total	1082	6468	4	18	4	18	4	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Amarchintha	Atmakur	33KV	Wanaparthi	13.10	16.58	03.48	EL	Pin banding fallen on the line & Tree fallen on the line near by 132KV SS	Atmakur	-
2		Achampet	Uppunuthala	33KV	Nagarkurnool	01.55	06.45	04.50	EL	Insulator failed near Kamsanpally	Uppunuthala	-
1	NLG	Munagala	Bethavolu	33KV	Huzurnagar	09.10	10.50	01.40	OL	Tree Fallen the Line	Bethavolu	-
1	MDK	Sadasivpet	Jogipet	33KV	Sangareddy	14.12	15.55	01.43		BD due to Pin Binding failed	Jogipet	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 12.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jaklair	Jaklair	11KV	Narayanapet	08.20	08.50	00.30		Cable cut at AB sitch	-
1	NLG	Arlagaddagudem	Chinna Suraram	11KV	Nalgonda	09.10	10.10	01.00	EL	Jumpet cut	-
2		Thatipamula	Thatipamula	11KV	Suryapet	09.00	12.10	03.10	EL	Conductor Snapped	-
3		IDA	Bommaipally	11KV	Bhongir	06.00	09.10	03.10	EL/OL	11 kv Line snapped at Subhash reddy thota near Bommaipally village,	-
4		Bollepally	Jampally	11KV	Bhongir	02.40	09.00	06.20	EL/OL	11 kv Insulator failed at Govardan well near Jampally village.	-
1	SDPT	Anajipur SS	Manthure	11KV	Gajwel	15.04	16.48	01.44		11KV Jumper cut	-
2		Gurralasofa SS	Waddepally	11KV	Gajwel	16.15	17.50	01.35		11KV Jumper cut	-
3		Akunoor	Dommeta	11KV	Husnabad	17.05	18.05	01.00		LT/HT	-
4		Guruvannapet	Guruvannapet	11KV	Husnabad	11.15	12.55	01.40		Insulator fail	-
5		Guruvannapet	Tapaspally	11KV	Husnabad	08.47	10.15	01.28		Line snapped	-
1	RR N	Kandlakoya	Saigeetha Ashramam	11KV	Medchal	09.05	09.50	00.45	BD	100KVA T/F failed at 108	-
2		Ravalkole	IDA Ganapathi	11KV	Medchal	10.25	11.16	00.51	BD	Tree fallen on the 11KV Line at Crusher, Rock Sand	-
3		Devarayamjal	Kottapet	11KV	Medchal	15.00	19.00	04.00	BD	11KV Jumper cut and replaced at Thurkoni Kunta	-
1	RR E	Moula-Ali	Mirjalguda	11KV	Sainikpuri	08.20	09.02	00.42		11Kv Cable failed at Butbuilding Company (due to AB Switch Open at Railwayees Traffic Police Station)	-
2		Narapally	Parvathapur	11KV	Keesara	13.06	15.02	01.56		11KV pin Insulator failed near Rohith Mill	-
1	HYD N	Chinna Thokatta	Panchavati Colony	11KV	VI	13.43	15.20	01.37	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Chandana Hospital fdr
1	HYD C	Industrial Area	Azamabad Key SS	11KV	II	03.20	05.25	02.05	EL,OL-Rph	Cable fault at Opp: Bus Bhavan	----
2		Z.P.Office	Seven Temple	11KV	I	04.31	06.30	01.59	EL,OL	I/C Cable fault at Tiwari Building	Arranged B/F on 11KV H.P Sabha feeder