

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	5	1	5	1	5			
2	NLG	144	988		1		1		1			
3	MDK	107	933		2		2		2			
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	9	2	9	2	9	0	0	
	Grand Total	1082	6468	3	12	3	12	3	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	leeza	Mitta Doddy	33KV	Gadwal	00.20	07.30	07.10	E/L&O/L	No Visible Fault		NO
1	SDPT	Gajwel	KDA	33KV	Siddipet	09.27	14.10	05.15		BD (Line Patrolling done , phase to phase to clearance done)		-
1	RR N	132KV Medchal	33KV Steel Mill	33KV	Medchal	11.30	16.55	05.25	BD	33KV Pin Insulator Failed at Steel Mill(Idle Charged)		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 17.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Thangadi	Thangadi	11KV	Narayanapet	05.00	08.35	03.35		Due to Tree Branch fallen on 11KV Line	-
2		Kankurthy	Damargidda	11KV	Narayanapet	13.48	15.09	01.21		Due to Disc Failure	-
3		Kothamolgara	Kothamolgara	11KV	Jadcherla	10.15	11.46	01.31		11KV Jumper cut near Pathamolgara	-
4		Kothamolgara	Madigatla	11KV	Jadcherla	11.30	12.50	01.20		Tree Fallen the line near Nallagutta	-
5		Donur	Crushier	11KV	Jadcherla	00.00	07.48	07.48		Phase to Phase near Crushier	-
1	NLG	Jalalpuam	MK Thanda	11KV	Suryapet	11.00	13.10	02.10	E/L	11Kv Insulator failed	-
1	MDK	EPIP-II	Marigold	11KV	Sangareddy	15.35	16.40	01.05		BD due to Tree branches fallen on line	-
2		SOL	IDA-II	11KV	Patancheru	11.05	15.00	03.55		BD due to Jumper cut	-
1	SDPT	Irkode	Irkode	11KV	Siddipet	00.10	07.00	06.50		B/D (Insultor Failure)	-
1	HYD N	Gymkhana	Mud Fort	11KV	Bowenpally	03.30	05.10	01.40	EL,OL-Rph	Disc Insulator flash over at Akber Road	-
2		Clock Tower	Railway Reservation	11KV	Sec-Bad	12.28	14.15	01.47	EL,OL-Rph	Cable fault at Metro Rail	Arranged B/F on 11KV H.H.Kala Bhavan feeder
1	HYD C	Indira Park	Indian Bulls (Dedicated)	11KV	Saifabad	04.32	07.30	02.58	EL,OL-Bph	I/C Cable End Kit fault	Arranged B/F on 11KV Gagan Mahal feeder