

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	2	2	2	2	2			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			1		1		1				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>4</b>	<b>3</b>	<b>4</b>	<b>3</b>	<b>4</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 18.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Balanagar	Dilip Rolling Mills	33KV	Jadcherla	10.02	19.15	09.13	EL	Due 33KV HT Out going cable damage	Dilip Rolling Mills	-
2		Achampet	Uppunuthala	33KV	Nagarkurnool	03.25	07.30	04.05	EL	No Visible fault	Uppunuthala	Allternate supply arranged from 33KV Veltoor feeder at 7:30Hrs
1	SDP	Gajwel	Mulugu	33KV	Gajwel	05.40	05.50	00.10		B/D (End Cable Kit Failed)	Mulugu	( Altenate Supply 132KV Thunikibollaram-33KV Markook)

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 18.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Dorepally	11KV	Narayanapet	12.07	13.10	01.03		LC Taken By LM Due to 11KV Disc fail	-
2		Nancherla	Nancherla	11KV	Narayanapet	11.43	13.08	01.25		BREAKDOWN DUE TO 11KV Line cut	-
1	NLG	Chedella	Noorjahan Peta	11KV	Suryapeta	09.05	11.45	02.40	EL	Jumper cut	-
2		Nakkalapally	Shapally	11KV	Nalgonda	12.45	13.45	01.00	EL	Insulator failed	-
1	RR E	Kushaiguda	Saibaba Temple	11KV	Sainikpuri	15.50	16.55	01.05		Bird fall on 11Kv line at Saibaba Temple (L Insp Prathap Reddy)	-
2		P&T colony	Chengicherla	11KV	Keesara	14.10	15.40	01.30		Insulator fail at Kamala nagar	-
1	HYD C	Chilkaiguda	Bholakpur	11KV	I	12.30	14.00	01.30	OL-Rph	Conductor snapped at Devuni Thota	-