

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	1	0	1	0	1	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		1		1		1No. 33KV Still
2	NLG	144	988									
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	0	2	0	1	0	1	0	
	Grand Total	1082	6468	3	0	3	0	2	0	1	0	

TSSPDCL - LMRC / Corporate office

Date: 19.11.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Peddamandadi	33KV	Wanaparthy	22.45	01.05	02.20		LV's Pull out Break down	Peddamandadi	Alternate supply Arranged form 132KV Thirumalaipally to 33KV Veltoor
2		Wanaparthy	Buddaram	33KV	Wanaparthy	22.45				Back clamp melted		
1	RR N	132KV Medchal	Petbasheerabad	33KV	Medchal	15:00	17:05	2:05		Bird fallen on the 33KV Line at Kompally Bridge	Petbasheerabad	No

TSSPDCL - LMRC / Corporate office

Date: 19.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Karkonda (T)	11KV	Jadcherla	06.00	07.00	01.00		11KV Jumper cut near Karkonda	No
2		Annasagar	Annasagar (T)	11KV	Jadcherla	06.14	06.50	00.36		11KV Jumper cut near Annasagar	No
1	NLG	Manaikunta	Veldevi	11KV	Bhongir	6:30	8:40	2:10	EL	11KV Disc failed	No
1	SDPT	Ganeshpally SS	Angadikistapur	11KV	Gajwel	10:17	11:51	1:34		Tripped on EL	No
2		Dom mata SS	Dom mata	11KV	Gajwel	08.55	11.01	02.06		Tree branches fallen	No
1	RR N	ICICI	SP-I	11KV	Medchal	2:46	11:40	8:54		Incoming Cable failed at SP-I Company (Internal problem)	No
1	RR E	Balaji Nagar	Santhosh Nagar	11KV	Keesara	11:03	11:45	0:42		11KV Brass patti cut near KLM Water Plant at BJR Nagar	No
2		Narapally	Parvathapur	11KV	Keesara	14.05	15.05	01.00		Snake fallen on 11KV Line & Jumper cut at Sathi Reddy AGL T/F	No
1	HYD C	Industrial Area	Vidya Nagar	11KV	II	14.25	16.25	02.00	EL,OL-Rph	No Visible Fault	Arranged B/F on 11KV Azamabad I.E feeder