

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT			2	2	2	2	2	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>2</b>	<b>9</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 21.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1		GAJWEL	Express Feeder	33KV	SIDDIPET	13.12	13.12	1hr		SPARK ON Y Phase BREAK DOWN		NO
2	SDPT	HUSANABAD	Thothapally	33KV	HUSANABAD	20.11.2020 3.30	07.12	9hr		TREE FALLEN ON LINE AT AKKANAPET SUBSTATION		KATKOOR FEEDER

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 21.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gudeballore	sathya sai	11KV	Narayanpet	07.00	08.30	01.30		11KV Line cut venkateshwara swamy temple in gudeballore(V)	-
1	NLG	Thoragal	T.G.Gudem	11KV	Nalgonda	02.30	09.20	06.50	E/L	Tree branches fallen on 11KV line	-
2		Eduloor	Kurumarthy	11KV	Nalgonda	07.30	11.10	03.40	E/L	11KV Jumper cut	-
3		Baironibanda	N.G.K.Pally	11KV	Nalgonda	14.30	16.40	02.10	E/L	HT/ LT wires melting at SS-1	-
4		B Chandupatla	VK Pahad	11KV	Suryapet	07.10	11.40	04.30	E/L	11Kv Conductor snapped	-
5		Anthagir	V.R.Puram	11KV	Huzurnagar	08.45	10.30	01.30	E/L	11Kv Conductor snapped	-
1	SDPT	Thigul SS	Thigul AGL LC:19383 Raghu JLM	11KV	Gajwel	13.16	13.56	00.40		Bird Fallen On 11 KV Line	-
2		Lingapur SS	Lingapur Feeder LC: 20041 Rajesham LM	11KV	Gajwel	13.20	15.09	02.49		11 KV wire Cut	-
1	HYD C	ITI Mallepally	Afzal Sagar	CEN	VII	11.09	15.45	04.36	EL,OL-Bph	Disc Insulator flash over at Pani Ground	-