

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	9	1	9	1	9	0	0	
	Grand Total	1082	6468	1	12	1	12	1	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.11.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Wadapally	Mission Bhagiratha	33KV	Miryalaguda	12:22	17:10	4:48	EL	33 KV Jumper cut at near yard	Mission Bhagiratha	No

TSSPDCL - LMRC / Corporate office

Date: 23.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Marikal	Theelair	11KV	Narayanapet	10.32	11.11	00.39		Pin binding failed	No
1	NLG	Eduloor	Munukuntla	11KV	Nalgonda	0:00	9:40	9:40	EL	11 KV Insulator Failed	No
2		Devarakonda	K.B.Pally	11KV	Devarakonda	10.10	10.45	00.35	EL	Movementary fault	No
3		Devarakonda	Mynampally	11KV	Devarakonda	14.50	17.30	02.40	EL	B/D of HT/LT	No
4		Siripuram	Vallapuram	11KV	Huzurnagar	02.30	07.30	05.00	EL	11KV Line snnaped	No
5		B.Ramaram	Jalalpur	11KV	Bhongir	13.05	14.10	01.05	EL	11KV Line snapped near Rangapuram Village	No
6		Juloor	Peddagudem	11KV	Choutuppal	12:25	13:00	0:35	EL	11KV Insulator failed near Peddagudem Village	No
1	SDPT	CHITYAL	CHITYAL	11KV	Husnabad	12:10	13:30	1:20		Tree fallen on conductor	No
2		RAIPOLE SS	THIMMAKKAPALLY	11KV	Gajwel	13.50	16.15	02.05		HT/LT	No
1	RR N	Madinaguda	B K Enclave	11KV	Kukatpally	15:30	17:00	1:30	EL/OL	Iran Rod fallen on the 11kv line	No
1	HYD N	Clock Tower	Railway Reservation	11KV	V	09.35	11.25	01.50	EL,OL-Rph	5way RMU Cable fault at Archana Arcade	No
2		Osm. University	Keshava Nagar	11KV	V	21:20	23:50	2:30	No Indication	No Visible Fault	Arranged B/F on 11KV Mettuguda fdr