

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	6	1	6	1	6			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		7		7		7			
	Total	606	3055	1	17	1	17	1	17	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	4	3	4	3	4			
2	NLG	144	988		8		8		8			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	16	4	16	4	16	0	0	
	Grand Total	1082	6468	5	33	5	33	5	33	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Jaknalapally	33KV	Nagarkurnool	00.29	02.05	01.36	E/L	No Visabule Fault Due to Heavy Wind & Rain	Jaknalapally	-
2		Kalwakurthy	Rachoor	33KV	Nagarkurnool	20.07	23.30	03.23	E/L&O/L	33KV Line Problem	Rachoor	Alternate Supply Arranged to 33KV Veldanda Feeder at 23:30Hrs
3		Kothur	P&G	33KV	Shadnagar	01.02	06.25	05.23	E/L&O/L	No Visabule Fault Due to Heavy Wind & Rain	P&G	-
1	MDK	Gummadidala	Dundigal	33KV	Patancheru	16.30	18.00	01.30		B/D Due to Conductor Snapped		-
1	RR N	132KV Medchal	33KV Bandamadaram	33KV	Medchal	03.00	04.45	01.45	EL	33KV Disc failed at Gowdavelly SS	33KV Bandamadaram	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 26.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Jaklair	Jaklair	11KV	Narayanapet	14.00	15.00	01.00		11Kv Disc failure	-
2		Salkarpet	Reddypally	11KV	Narayanapet	10.00	10.42	00.42		Tree branch fallen on 11KV line	-
3		Konded	Konded	11KV	Jadcherla	01.30	09.30	08.00		11 KV Disk fail near Konded town.	-
4		Ponnakal	Rachala	11KV	Jadcherla	05.30	11.15	05.45		11 KV wire cut near Rachala (V)	-
1	NLG	Mukundapuram	Mukundapuram	11KV	Suryapet	03.40	07.30	03.50	E/L	Jumper cut	-
2		Ravulapally	Ravulapally	11KV	Suryapet	03.00	06.40	03.40	E/L	Conductor snapped	-
3		Athmakur(S)	T.Penpahad	11KV	Suryapet	02.40	06.00	03.20	E/L	Disc failed	-
4		Dirshincherla	Yellapuram	11KV	Huzurnagar	01.00	05.00	04.00	E/L	11KV Line Snapped	-
5		Keethavarigudam	Laxmipuram	11KV	Huzurnagar	01.29	06.00	04.31	E/L	11KV Line Snapped	-
6		Gudipally	Gudipally AGL	11KV	Huzurnagar	01.00	05.30	04.30	E/L	11KV Line Snapped	-
7		Chilkuru	Janakinagar Thanda	11KV	Huzurnagar	14.11	17.00	02.49	E/L	11KV Insuletor Failed	-
8		Manikunta	Veldavi	11KV	Bhongiri	05.00	11.00	06.00	EL	11kv Line Snapped near Veldavi village	-
1	MDK	EPIP-I	ORTIN	11KV	Sangareddy	17.20	18.30	01.10		B/D Due to Conductor Snapped	-
1	SDP	REGULAPALLY	CHEELAPUR	11KV	Husnabad	13.40	14.10	00.30		B.D, DUE TO JUMPER CUT	
2		GAGILLAPUR	GAGILLAPUR 24 hrs	11KV	Husnabad	21.58	22.32	00.34		B.D, DUE TO JUMPER CUT	
3		Dharmajipet	Lachapet	11KV	Siddipet	17.10	19.17	02.07		B/D (Jumper open) LCNO. 3460	
1	RR N	Nizampet	Bandrilayout	11KV	Kukatpally	03.30	04.50	01.20	EL/OL	11kv Pin insulator Failure & 11kv jumper Cut at Road-I bandri lay out	-
2		Kompally	Jaibheri	11KV	Medchal	02.35	04.27	01.52	EL	11KV Line Cut & Replaced at near Jaibheri Center Apartment	-
3		Subhash Nagar	Gayatri Nagar	11KV	Medchal	02.25	03.49	01.24	EL	AB Cable failed at Phase College, Gayatri Nagar	-
4		Shameerpet	33KV Leo Meridian	11KV	Medchal	02.15	08.00	05.45	EL	No Fault	-
5		Devarayamjal	Pothaipally	11KV	Medchal	03.30	05.50	02.20	EL/OL	No Fault	-
6		Kandlakoya	KV Reddy Nagar	11KV	Medchal	03.00	03.30	00.30	EL/OL	Pin Insulator Failed at Mypi Villas	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	VP Nagar	RK Puram	11KV	Sainikpuri	02.30	03.23	00.53		Post of Insulator failed at Sec Shopping complex and load added on Brundhavan Colony	-
2		Cherlapally-II	Gajjana Thamara	11KV	Sainikpuri	02.00	03.50	01.50		11Kv Pin Insulator failed at Gajjan Thamara (AE)	-
3		Nacharam Indore	Surana	11KV	Habsiguda	02.07	03.10	01.03		11KV Pin Insulator failed near Surana Wires Company	-
4		Narapally	P.singaram	11KV	Keesara	02.25	03.15	00.50		Tree branches fallen on 11kv line at Balaji nagar	-
1	HYD N	Bhudevi Nagar	Yadamma Nagar	11KV	C-VI	02.40	04.05	01.25	EL,OL	Tree branches fallen on lines at Telecom Colony	-
2		Kalyan Nagar	Rahamath Nagar	11KV	X	18.38	19.46	01.08	EL,OL-Bph	AB Cable fault at Video Gally	-
1	HYD S	Kandikal Gate	Rakshapuram	11KV	III	02.05	04.35	02.30	EL	Double feeding Point Cable fault at Omer Colony	-
2		Kandikal Gate	G.M Chowni	11KV	III	02.08	03.15	01.07	EL,OL-Bph	No Visible Fault	-
1	HYD C	Fever Hospital	Kachiguda Rly Station	11KV	II	02.05	03.45	01.40	EL	No Visible Fault	-
2		Indira Park	Gandhi Nagar	11KV	I	07.53	09.15	01.22	EL,OL	Incoming Sectionaliser Jumper cut at Nala	-
3		Bathakamma Kunta	Saibaba Temple	11KV	II	02.20	03.30	01.10	OL-R&Bph	Tree branches fallen on lines at Saibaba Temple	-