

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933									
4	SDPT				9		9		9			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>21</b>	<b>1</b>	<b>21</b>	<b>1</b>	<b>21</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 30.11.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Haliya	Yacharam	33KV	Miryalguda	10.50	11.20	00.30	E/L	Tree branch fallen on 33Kv line near velmagudem		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.11.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palem	Bopparam	11KV	Nalgonda	04.20	12.25	08.05	E/L	11KV line cut at Bopparam (V) end	-
2		Pamanagundla	Erasanigudem	11KV	Nalgonda	06.32	08.40	02.08	E/L	11KV Jumper cut	-
3		Penpahad	Potlapahad	11KV	Suryapet	03.50	08.40	04.50	E/L	11Kv Conductor snapped	-
4		Paladugu	Duppelly	11KV	Bhongir	05.00	10.00	05.00	EL/OL	11kv Insulator failed near Bokkonigudem.	-
5		Choutuppal	Jublakpally	11KV	Choutuppal	01.25	08.50	07.25	EL/OL	11kv Disc failed near Choutuppal town	-
6		Juloor	Kapraipally	11KV	Choutuppal	00.02	08.15	08.13	EL/OL	11kv Insulator failed near Mukthapur (V)	-
7		Puligilla	Kanchanapally	11KV	Choutuppal	06.30	15.00	08.30	EL/OL	11kv Insulator failed at Milk center backside near Goligudem (V)	-
1	SDPT	Ponnal	Ponnal	11KV	Siddipet	11.00	13.00	02.00		B/D 11 KV Conductor cut LC.No.33807	-
2		Peddagundavally	Peddagundavally	11KV	Siddipet	00.45	06.00	05.15		B/D 11 KV Line cut LC.No.0177	-
3		PREGNAPUR	TOWN FEEDER	11KV	Gajwel	18:10	18:24	0:14		TREE BRACH WAS FALLEN ON THE 11KV LINE	-
4		MARKOOK	AGL FEEDER	11KV	Gajwel	09.00	10.20	01.20		11KV LINE INSULATER FAILED	-
5		MARKOOK	AGL FEEDER	11KV	Gajwel	14.38	17.55	03.17		11KV LINE BREAKDOWN	-
6		GOWRARAM	PATHURE FEEDER	11KV	Gajwel	15.56	18.00	02.04		11KV LINE DISE FAILED	-
7		DOMMATA	GAJULAPALLY	11KV	Gajwel	13.10	15.50	02.40		11KV LINE CUT	-
8		Komuravelly	Kistampet	11KV	Husnabad	11.42	13.25	01.43		Insulator failure, same rectified	-
9		Chityal	Thadoor	11KV	Husnabad	00.00	07.25	07.25		Line snapped, same rectified	-
1	RR N	Jagathgiringutta	IDA	11KV	Medchal	06.50	07.25	00.35	EL	11KV Cable endkit failed at Papireddy Nagar	-
2		Bachupally	SMS	11KV	Kukatpally	14.50	15.50	01.00	EL	11KV Cable kit failure at Bollaram X road	-
1	RR E	Kushaiguda	Sri Ram Nagar	11KV	Sainikpuri	08.35	09.25	00.50		Consumer Tree cut on fall 11Kv line at Gouda Colony near Vijaya High School (AE)	-
1	HYD N	Muffakamza College	Meridian	11KV	X	02.21	04.22	02.01	EL,OL	Cable fault	Arranged B/F on 11KV Namdari fdr
2		Kalyan Nagar	Rahamath Nagar	11KV	X	16.05	18.20	02.15	EL	4Nos. End Kits failed at Video Galli	-