

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	4	1	4	1	4			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT			1	8	1	8	1	8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>2</b>	<b>15</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>17</b>	<b>2</b>	<b>17</b>	<b>2</b>	<b>17</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 01.10.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Oil Seeds	33KV	Gadwal	11.05	12.15	01.10	E/L	Tree Branch Fallen on the line near Jemshed SS	Oil Seeds	No
1	SDPT	Habsipur	Peddachikodu	33KV	Siddipet	10:15	11:30	1:35		Poles broken due to trees fallen on line-now rectified	Peddachikodu	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Khazipur	11KV	Narayanapet	12.15	13.15	01.00		Tree fallen on the line 11KV line	No
2		Kosgi	Bhogaram	11KV	Narayanapet	07.25	09.10	01.45		Due to monitor lizard (Vudumu) between 2 phases	No
3		Mogalmadka	Mogalmadka Rural	11KV	Narayanapet	07.44	09.11	01.27		Insulator failed	No
4		Appakpally	Satyasai	11KV	Narayanapet	5:40	6:30	0:50		Tree fallen on the line	No
1	NLG	Kalmlacheruvu	Ganugabanda	11KV	Huzurnagar	10:00	12:20	2:20	EL	11 KV Line snapped	No
2		Alair	Ch.Kandukur	11KV	Bhongir	04.00	11.55	07.55	EL/OL	11kv Disc failed near Bahupet Main Road	No
3		Peddakandukur	Bahupet	11KV	Bhongir	01.00	07.00	06.00	EL/OL	11kv Disc failed near Kacharam Village	No
1	SDPT	Akkannapet	Pakilnayak Thanda	11KV	Husnabad	7:00	8:30	1:30		Tree fallen on the line	No
2		Akkannapet	Akkannapet Rural	11KV	Husnabad	01.00	11.10	10.10		11 kv line cut	No
3		Akkannapet	Gollakunta	11KV	Husnabad	01.00	15.27	14.27		11 kv line cut & Insulator failed	No
4		Ramchandrapur	Vinjalpally	11KV	Husnabad	13.10	15.55	02.45		Tree fallen on the line	No
5		Thotapally	Devakkapally	11KV	Husnabad	07.20	13.10	05.50		Insulator failed	No
6		Chellapur	Chellapur	11KV	Siddipet	00.00	17.34	17.34		Insulator failed	No
7		Peddachikode	Peddachikode	11KV	Siddipet	00.20	08.20	08.00		Tree branches fallen on the line due to pole broken - now rectified	No
8		Mirdoodi	Mirdoodi	11KV	Siddipet	7:10	11:40	4:30		Tree branches fallen on the line due to pole broken - now rectified	No
1	RR E	AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	14:26	15:23	0:57		Tree branches fall on the line	No
1	HYD N	Hakimpet	Allenby Lines	11KV	C-VI	01.34	02.48	01.14		Tree branches fallen on lines at 4th Pole Structure	No