

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>11</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 06.10.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
<b>NIL</b>												

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 06.10.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kethapally	Chekatigudem	11KV	Nalgonda	23.45	08.15	08.30	E/L	11 KV Insulator Failed	-
2		Cherkpally	Bondagu	11KV	Nalgonda	06.10	07.51	01.41	E/L	SS-4 Insulator Failed	-
3		Pajjur	Pajjur	11KV	Nalgonda	04.00	11.30	07.30	E/L	SS-5 Jumper Cut	-
4		Pamanagundla	Pittampally	11KV	Nalgonda	10.10	12.30	02.20	E/L	11 KV Jumper Cut and Fallen on the X Arm	-
5		Katangoru	Bollepally	11KV	Nalgonda	09.20	12.20	03.00	E/L	Bird Died on 11 KV Line	-
6		Annaram	Kothagudem	11KV	Suryapet	08.25	11.30	03.05	E/L	Insulato flashover	-
1	SDP	KONDAPAKA	VISHVANATHPALLY	11KV	Gajwel	12.40	18.10	05.30		11KVA LINE CUT	-
2		ANAJIPUR	MANTHOOR	11KV	Gajwel	09.10	12.25	03.15		EAGLE TOUCH THE 11KVA LINE	-
1	RR N	Jeedimetla SS III	VSP Organics	11KV	Jeedimetla	10.45	12.40	01.55	EL	11kv AB Cable end kit failure opp pipes Company	-
1	HYD N	Kalyan Nagar	Madhura Nagar	11KV	X	13.08	15.01	01.53	All Indication	Conductor snapped near RMU at Kalyan Nagar X Road	-----
2		Gymkhana	Tadbun Temple	11KV	C-VI	16.12	17.30	01.18	EL,OL	Cable fault near SS	Arranged B/F on 11KV Sick Village feeder