

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044									
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	13	1	13	1	13			
3	MDK	107	933	1		1		1				
4	SDPT				12		12		12			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	25	2	25	2	25	0	0	
	Grand Total	1082	6468	2	28	2	28	2	28	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.10.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Kanagal	Thimmannagudem	33KV	Nalgonda	02.05	10.41	08.36	E/LO/L	Insulator failure	Thimmannagudem	-
1	MDK	Bollaram	Coco-Cola	33KV	Patancheru	17.40	23.50	06.10		B/D due to Jumper cut	Coco-Cola	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 07.10.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Katangur	Dugunelly	11KV	Nalgonda	06.00	10.20	04.20	E/L	11 KV Jumper Cut	-
2		Narketpally	Yedavally	11KV	Nalgonda	07.30	09.20	01.50	E/L	Insulator Failed	-
3		Narsingbalta	Chennugudem	11KV	Nalgonda	07.45	08.45	01.00	E/L	11 KV Polymer Insulator Failed	-
4		Nemmani	Merlakunta	11KV	Nalgonda	09.20	11.20	02.00	E/L	11 KV Jumper Cut	-
5		Nakrekal	Chandanapally	11KV	Nalgonda	09.12	10.41	01.29	E/L	Insulator Failed	-
6		Kamareddy Gudem	Kamareddy Gudem	11KV	Miryalaguda	07.55	09.10	01.15	EL	Insulator failed	-
7		Balemla	Balemla	11KV	Suryapet	06.42	10.05	03.23	EL	Insulator failed	-
8		Keethavarigudem	Laxmipuram	11KV	Huzurnagar	05.25	07.30	02.05	EL	11 KV LINE SNAPPED	-
9		Kalmalcheruvu	Ganganagar	11KV	Huzurnagar	04.20	07.00	02.40	EL	11 KV LINE SNAPPED	-
10		Nadigudem	Ramapuram	11KV	Huzurnagar	14.10	16.30	02.20	EL	11 KV JUMPER CUT	-
11		Bollepally	Bollepally	11KV	Bhongir	13.50	14.20	00.30	EL/OL	11kv Line snapped near Sureypally Road	-
12		Maryala	Mailaram	11KV	Bhongir	10.40	12.45	02.05	EL/OL	11kv Line snaped near Maryala Village	-
13		Golankonda	Golankonda	11KV	Bhongir	09.30	13.10	03.40	EL/OL	11kv Insulator Failed near Golnkonda Village Due to rain	-
1	SDPT	Chowdaram	Yellammajalu	11KV	Siddipet	10.59	19.45	08.46		Insulator failed	-
2		Kammarlapally	Kothapally	11KV	Siddipet	07.40	12.50	05.10		Insulator failed	-
3		Mustabad X Road	Gadicherlapally	11KV	Siddipet	12.30	12.55	00.25		B/D Jumper cut	-
4		Narmetta	Venkatapur	11KV	Siddipet	16.10	16.50	00.40		B/D Jumper Cut & LC.No.22702	-
5		PRAGNAPUR	AAKARAM AGL	11KV	Gajwel	10:20	17:10	6:50		Tree branches as fallen on the 11 kv Line	-
6		NEMTOOR	JABBAPUR	11KV	Gajwel	7:40	9:05	01.25		Bird fallen on the 11 kv Line	-
7		NEMTOOR	JABBAPUR	11KV	Gajwel	12:00	13:00	01.00		AB SWITCHES OPENED FALT NOT CONFORM	-
8		WARGAL	CHOWDERPALLY	11KV	Gajwel	11:55	14:00	02.05		Tree Branches as fallen on the 11 kv Line (11KVA)	-
9		Akkannapeta	Akkannapeta Rural	11KV	Husnabad	13.10	17.40	04.30		Insulator fail	-
10		Ramachandrapur	RC PUR Rural	11KV	Husnabad	15.00	17.00	02.00		Heavy rain& Tree fallen on the line	-
11		Koheda	Kurella	11KV	Husnabad	17.05	17.45	00.40		Insulator fail	-
12		Dhulmitta	Arjunpatla	11KV	Husnabad	06.30	15.20	08.50		Insulator Fail	-
1	RR E	NGRI	Habsiguda	11KV	Habsiguda	01.35	02.56	01.21		Line petrolling done no visiable fault found & B/F to Scientist colony feeder	-
2		NGRI	Kalyanipuri	11KV	Habsiguda	02.40	04.50	02.10		11KV Cable failed of survey of india & 11kv Jumper open	-
3		Anandbagh	PB Colony	11KV	Habsiguda	18.05	20.15	02.10		11Kv line AB Switch opened at PB Colony Due to line petrolling done and 95% feeder charged	-