

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		11		11		11			
	Total	606	3055	0	16	0	16	0	16	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	3	1	3	1	3			
4	SDPT			4	9	4	9	3	9	1		1 No.33KV Still
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	20	6	20	5	20	1	0	
	Grand Total	1082	6468	6	36	6	36	5	36	1	0	

TSSPDCL - LMRC / Corporate office

Date: 19.10.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Bijinapally	33KV	Nagarkurnool	16.00	17.05	01.05	EL	33KV Line Phase to Phase	Bijinapally	-
1	MDK	Gummadidala	GPSS-II	33KV	Patancheru	20.30	22.10	01.40		B/D due to Tree branches fallen on the line	GPSS-II	-
1	SDPT	Chandlapur	Kammarlapally	33KV	Siddipet	18.05	18.43	00.38		BD (33/11 KV SS Allipur LA Failure)	Kammarlapally	-
2		Shanigaram	Koheda	33KV	Husnabad	02.55	04.20	01.25		Isolator open towards koheda to samudrala	Koheda	-
3		Gajwel	KDA	33KV	Gajwel	03.55	00.00	still		B/D due to insulators failed	KDA	No Ulternate
4		Musthyala	Cheriyal	33KV	Husnabad	03.50	07.50	04.00		Tree fall on the line	Cheriyal	132 KV Musthyala 33 KV Dhoolmitta feeder

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 19.10.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bhoothpur	Bhoothpur Rural	11KV	Jadcherla	06.00	08.40	02.40		11KV Disk fail near Pothulamadu	-
2		Midjil	Boinpally	11KV	Jadcherla	04.30	09.00	04.30		11KV Disk & 11KV Insulator fail near Mallapur	-
1	NLG	Turkapally	Turkapally	11KV	Nalgonda	06.10	07.35	01.25	EL	Jumper cut	-
2		Pamangundla	Ismailpally	11KV	Nalgonda	09.41	10.55	01.14	EL	Insulator failed	-
3		Garideapally	Appanapet	11KV	Huzurnagar	05.00	08.25	03.25	EL	11 KV LINE SNAPPED	-
4		Ananthagiri	V R Puram	11KV	Huzurnagar	16.25	17.30	01.05	EL	11 KV Disk failed	-
5		Repala	N S Gudem	11KV	Huzurnagar	15.15	17.00	01.45	EL	11 KV JUMPER CUT	-
6		Pamukunta	Singaram	11KV	Bhongir	05.30	11.00	05.30	EL/OL	11 KV Disc failed near Singaram village.	-
1	MDK	Sangareddy Town-II	Kandi	11KV	Sangareddy	10.30	15.00	04.30		B/D Due to tree Branch fallen on the line at Narayanreddy Colony	
2		Bollaram-I	Kythan	11KV	Patancheru	13.30	15.25	01.55		B/D due to Insulator failed	
3		Bollaram-I	Soubhagya	11KV	Patancheru	13.40	15.26	01.46		B/D Due to Conductor Snapped	
1	SDPT	Irkode	Burgupally	11KV	Siddipet	17.40	17.55	00.15		B/D Tree branch fall on the line & LC.No.11792	-
2		Mallaram	Sikindlapur	11KV	Siddipet	09.40	10.50	01.10		B/D Disk fail	-
3		Thimmapur	Thimmapur	11KV	Siddipet	09.22	09.52	00.30		B/D Disk fail	-
4		Thimmapur	Thimmapur	11KV	Siddipet	10.48	11.05	00.17		B/D DTR Problem	-
5		Raghothampally	Gosanpally	11KV	Siddipet	09.10	09.40	00.30		B/D Due to Bird	-
6		AMDIPUR	THILALPUR	11KV	Gajwel	07.15	09.15	02.00		TREE BRANCH FEL ON 11 KV LINE	-
7		PAMULAPARTHY	EPPALAGUDA	11KV	Gajwel	17:25	18:05	0:40		PEACOCK FELL ON 11 KV LINE	-
8		ERRAVALLY	ERRAVALLY AGL	11KV	Gajwel	12:20	13:36	1:16		INSULATOR FAILED	-
9		KARKAPATLA	JODEJ	11KV	Gajwel	13:00	13:40	0:40		11 KV LINE CUT	-
1	RR S	IIIT	IVRCL	11KV	Gachibowli	14.46	15.55	01.09		Due to Heavy Rain, No Visible Fault.	-
1	RR N	Laxmapur	Narayanapur	11kv	Medchal	01.28	03.00	01.32	BD	11KV Disc failed at Durgamma Temple,Narayanpur Road	-
1	RR E	NGRI	Habsiguda	11kv	Habsiguda	13.24	14.09	00.45		11KV Disc failed at St.No.01 Habsiguda	-
2		Anandbagh	Vinayak Nagar	11kv	Sainikpuri	12.47	13.30	00.43		Ground Petrolling don but no Visible fault found	-
3		Narapally	Prathap Singaram	11kv	Keesara	12.02	12.42	00.40		Line Patrolling but no visible fault & 11KV line AB Switch opened at Balaji Nagar due to 11KV Disc failed	-
1	HYD N	Tirumalagiri	Mangapuram Colony	11kv	C-VI	12.00	14.20	02.20	EL,OL-Rph	No Visible Fault	-
2		Macha Bollaram	Ayyappa Nagar	11kv	C-VI	13.48	16.24	02.36	EL,OL	No Visible Fault	-
3		Marredpally	Railway Colony	11kv	C-VI	14.10	15.20	01.10	EL,OL	Pin Insulator flash over at Railway Colony	-
4		Prashanth Nagar	Time Tek	11kv	VI	14.10	17.10	03.00	EL,OL	Jumper cut at Prashanth Nagar	-
5		Chilalguda	New Boiguda	11kv	V	14.20	16.04	01.44	EL	Tree branches fallen on LT lines at Kallu Compound	-
6		Road No.22	M.C.R.	11kv	X	16.22	17.45	01.23	EL,OL	Jumper cut at Road No.31	-
1	HYD S	Asmangadh	P&T Colony	11kv	VIII	04.10	05.40	01.30	EL,OL-Yph	Cable fault	Arranged B/F on 11KV Goutham Nagar
1	HYD C	Zamisthapur	Dayara Market	11kv	II	08.33	10.37	02.04	EL	Faulty loads of 11KV Azamabad Key SS feeder	-
2		Mothi Mahal	Zinsi Bazar	11kv	VII	10.35	12.02	01.27	All Indication	AB Cable failed at Mothi Mahal	-
3		Amberpet	Play Ground	11kv	II	12.17	13.38	01.21	EL	Tree branches fallen on lines at Amberpet	-
4		Fever Hospital	Nalla Kunta	11kv	II	12.20	13.50	01.30	EL	Tree branches fallen on lines at Street No.4	-