

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		2		2		2			1 No.11KV Still
6	RR(N)	54	550		8		8		8			
7	RR(E)	168	403		4		4		4			
8	Hyd	194	1044		19		19		19			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>33</b>	<b>0</b>	<b>33</b>	<b>0</b>	<b>33</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	5	3	5	3	5	1		1 No.33KV Still
2	NLG	144	988	2	22	2	22	2	22			
3	MDK	107	933		5		5		5			
4	SDPT			3	21	3	21	3	21			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133		9		9		9			
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>9</b>	<b>62</b>	<b>8</b>	<b>62</b>	<b>8</b>	<b>62</b>	<b>1</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>9</b>	<b>95</b>	<b>8</b>	<b>95</b>	<b>8</b>	<b>95</b>	<b>1</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 21.10.2020

## Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Koilkonda Water Grid	33KV	Narayanapet	15.50	18.30	02.40	O/L	Under ground Y Phase cable burn out		Alternate Supply Arranged from 132KV Mahabubnagar 33KV Machanpally feeder
2		Makthal	Kirshna	33KV	Narayanapet	22.25	07.00 21.10.20	01.35	E/L	Not Rectified Due to Rain		No
3		Kothur	Thimmapur	33KV	Rajendernagar	14.12	18.45	04.33	EL&OL	Insulator failed near LV Prasad Hospital		
4		Kothur	Raghavendra	33KV	Rajendernagar	14.10	16.05	01.55	E/L	Insulator failed near Mahaveer Company		
1	NLG	Marriguda	Gattuppal	33KV	Nalgonda	00.35	07.15	06.40	E/L	33Kv Pin insulator failed at Anthampet thanda		-
2		Marriguda	Marriguda	33KV	Nalgonda	00.45	06.36	05.51	E/L	AB switch open		-
1	SDPT	Gajwel	KDA	33KV	Gajwel	03.55	07.30	03.35		BD ( insulator failure )		-
2		Musthyala	Cheriyala	33KV	Husnabad	03.50	09.05	05.15		Tree fell on line		-
3		Shanigaram	koheda	33KV	Husnabad	02.55	04.20	01.25		EL (cross arm bent on pole)		-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 21.10.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Peddarevelly	Peddarevelly	11KV	Jadcherla	09.23	11.40	02.17		11Kv Insulator Failure Near Lingaram Road.	-
2		Balanagar	Nerellapally	11KV	Jadcherla	11.00	14.24	03.24		11KV Disk fail near Ramji Tanda Gudibanda Cut Point.	-
3		NARAYANPET	YADGIR ROAD	11KV	Narayanapet	15.00	16.00	01.00		INSULATOR FAILED, VEGATABLE MARKET	-
4		KOTAKONDA	BANDAGONDA	11KV	Narayanapet	14.45	15.30	00.45		INSULATOR FAILED,	-
5		MARIKAL	PC KUNTA	11KV	Narayanapet	12.06	13.45	01.39		INSULATOR FAILED,	-
1	NLG	Pamanagundla	Pamanagundla Indl.	11KV	Nalgonda	02.45	08.30	05.45	E/L	11KV Insulator failed	-
2		Narkatpally	Narkatpally Town	11KV	Nalgonda	03.15	08.20	05.05	E/L	11KV wire cut	-
3		Eduloor	Munukuntla	11KV	Nalgonda	03.30	09.48	06.18	E/L	11KV Insulator failed	-
4		Pazzur	Pazzur	11KV	Nalgonda	06.05	09.10	03.05	E/L	11KV Jumper cut	-
5		Kanagal	Parvathagiri	11KV	Nalgonda	06.00	12.30	06.30	E/L	11KV Jumper cut	-
6		Kattangur	Bollepally	11KV	Nalgonda	06.50	09.10	02.20	E/L	11KV Jumper cut	-
7		Palem	Ogodu	11KV	Nalgonda	07.00	09.30	02.30	E/L	Tree branches fallen on line	-
8		Turkapally	Turkapally	11KV	Nalgonda	07.50	12.56	05.06	E/L	Tree branches fallen on line	-
9		Narkatpally	Mandra	11KV	Nalgonda	08.20	09.00	00.40	E/L	11KV Jumper cut	-
10		N.S.Batla	Chennugudem	11KV	Nalgonda	11.48	12.40	00.52	E/L	Line AB switch open	-
11		Nakrekal	Marrur	11KV	Nalgonda	02.20	10.15	07.55	E/L	11KV Jumper cut	-
12		Aitipamula	Ch.Annaram	11KV	Nalgonda	06.00	15.30	09.30	E/L	Tree branches fallen on line	-
13		Aitipamula	Gangadevigudem	11KV	Nalgonda	02.00	15.30	13.30	E/L	Tree branches fallen on line	-
14		Kudakuda	Komatikunta	11KV	Suryapet	08.25	11.47	03.22	E/L	11kv Insulator failed	-
15		D Nagaram	Wardhamanu Kota	11KV	Suryapet	03.00	06.25	03.25	E/L	11Kv Jumper cut	-
16		Ananthagiri	Ameenabad	11KV	Huzurnagar	04.45	07.00	02.15	E/L	11Kv Line Snapped	-
17		Palakeedu	Bothalapalem	11KV	Huzurnagar	06.15	08.00	01.45	E/L	11Kv Line Snapped	-
18		Motakondur	Motakondur Agl	11KV	Bhongir	04.20	10.30	06.10	EL/OL	11kv Insulator Failed near Motakondur (V)	-
19		Anajipur	Dacharam	11KV	Bhongir	05.30	09.00	03.30	EL/OL	11 KV Line snapped near Dacharam (V)	-
20		Choutuppal IPDS	Damera Agl	11KV	Choutuppal	08.30	12.05	03.35	EL/OL	11kv Insulator Failed near Damera (V)	-
21		S.Lingotam	S.Lingotam Agl	11KV	Choutuppal	02.52	10.00	07.08	EL/OL	11kv Insulator Failed near S.Lingotam (V)	-
22		D.Nagaram	D.Nagaram indl	11KV	Choutuppal	02.45	07.49	05.04	EL/OL	11 kv Insulator failed near Nagaram (V)	-
1	MDK	Sadasivpet	TSM	11KV	Sangareddy	05.10	07.40	02.30		BD due to no fault at found	-
2		EPIP-I	GENSINTH	11KV	Sangareddy	05.40	08.30	02.50		BD due to no fault found	-
3		Inole	Bayers Corp	11KV	Patancheru	12.50	17.50	05.00		BD due to Tree fallen on line	-
4		Patancheru Town	MIA-I	11KV	Patancheru	12.35	14.10	01.35		BD due to Conductor snapped	-
5		Anrich Bollaram	Town-II	11KV	Patancheru	21.10	23.45	02.35		BD due to Tree fallen on line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDPT	Nangnoor	Nangnoor agl	11KV	Siddipet	03.30	11.20	07.50		B/D 11kv insulator Faill	-
2		Mittapally	Yellupally	11KV	Siddipet	07.45	12.25	04.40		B/D Jumper Touching	-
3		KODAKANDLA	BURGUPALLY	11KV	Gajwel	15:05	15:16	0:11		11KV JUMPER CUT	-
4		MARKOOK	AGL FEEDER	11KV	Gajwel	3:40	7:46	4:06		11KV INSULATER FAILED	-
5		MARKOOK	BHAVANANDAPUR FEEDER	11KV	Gajwel	11.11	12.00	00.49		11KV LINE CUT	-
6		CHEELASAGAR	ANNASAGAR FEEDER	11KV	Gajwel	12.20	13.00	00.40		AB SWITCH INSULATER FAILED	-
7		DUDEEDA	TOWN FEEDER	11KV	Gajwel	03.30	07.10	04.20		11KV INSULATER FAILED	-
8		DUDEEDA	TOWN FEEDER	11KV	Gajwel	09.30	10.05	00.35		11KV INSULATER FAILED	-
9		GODUGUPALLY	GODUGUPALLY	11KV	Gajwel	06.30	09.30	03.00		11KV INSULATER FAILED	-
10		RAIPOLE	CHOWDARPALLY	11KV	Gajwel	10.10	14.10	04.00		11KV JUPER CUT	-
11		MARPADAGA	KAMMAMPALLY AGL	11KV	Husnabad	12.10	12.25	00.15		11KV DISC FAILED	-
12		Gurjakunta	Gurjakunta AGL	11KV	Husnabad	05.05	09.00	03.55		tree fell line	-
13		Pandilla	Potlapally	11KV	Husnabad	02.30	04.30	02.00		Jumper cut	-
14		Thotapally	Thotapally agl	11KV	Husnabad	03.05	08.25	05.20		tree fell line	-
15		Dharmaram	Dharmaram Rural	11KV	Husnabad	02.30	12.30	10.00		line fault & hg fuse wire problem & line cut	-
16		Husnabad	Madatha	11KV	Husnabad	02.30	10.20	07.50		Disc fail	-
17		Husnabad	Pandilla	11KV	Husnabad	06.40	16.50	10.10		Disc fail	-
18		Koheda	sriramulapally	11KV	Husnabad	07.10	07.50	00.40		insulator failed	-
19		Koheda	Venkateshwarlapally	11KV	Husnabad	08.15	08.45	00.30		Jumper cut	-
20		Shanigaram	Shanigaram rural	11KV	Husnabad	03.30	07.00	03.30		insulator failed	-
21		Shanigaram	Gundareddypally	11KV	Husnabad	03.30	10.00	06.30		insulator failed	-
1	RR S	ESCI	Divyasri NSL	11KV	Gachibowli	14.42		09.18		UG Cable failed at Divyasri NSL	-
2		Ayyappa Society	My Home	11KV	Kondapur	15.30	16.36	01.06		UG Cable failed at Plot no-241, Ayyappa Society	-
1	RR N	Jeedimetla SS II	Uthambiscuite	11KV	Jeedimetla	07.40	10.00	02.20	EL	11kv Disk failure opp Mazeed at DP Colony	-
2		Jeedimetla SS II	NRSA	11KV	Jeedimetla	08.55	10.50	01.55	ELOL	11KV Jumper snaped at Phase I	-
3		Dulapally	IDA-II	11KV	Medchal	04.50	06.37	01.47	EL	100KVA DTR Insulator failed at Murthy Engineering company	-
4		Chintal	Ganseh Nagar	11KV	Medchal	05.40	06.45	01.05	EL	11KV Line AB Switch opened at Kalapana Society (11KV Pin Insulator failed at Ganesh Nagar)	-
5		Kistapur	IDA Hanuman	11KV	Medchal	00.10	08.00	07.50	EL	100KVA T/F Brass Patti Cut & Touched the Channel Exga Company	-
6		Gowdavelly	IDA Gowdavelly	11KV	Medchal	05.20	08.00	02.40	EL	Tree Fallen on 11KV Line at Gowdavelly X Road	-
7		Medchal	Check Post	11KV	Medchal	06.00	07.15	01.15	ELOL	11KV PinInsulator failed at Check Post Medchal	-
8		Thumkunta	Thumkunta	11KV	Medchal	04.30	08.10	03.40	EL	11KV Jumper Cut at Mandaipally Road	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Uppal Kalsa	Swaroop Nagar	11KV	Habsiguda	02.40	04.00	01.20		11KV Pin Insulator failed at Gandhi Nagar ATM	-
2		Sai Nagar	RNS Colony	11KV	Habsiguda	03.15	05.15	02.00		11KV Disc failed at RNS Colony Phase-3	-
3		Polytechnic	PS colony	11KV	Habsiguda	15.47	16.48	01.01		PS colony Cable fail while digging	-
4		Vasanthapuri	Ganesh Temple	11KV	Sainikpuri	02.40	03.48	01.08		11Kv Pin Insulator failed at near Vasanthapuri Library T/F	-
5		Aushapur	Aushapur	11KV	Keesara	07.50	09.20	01.30		11KV line cut at Aushapur village	-
6		Aushapur	Aushapur	11KV	Keesara	13.10	14.20	01.10		Tree fallen on 11kvline at Aushapur village	-
7		Singapur	Annojiguda	11KV	Keesara	05.00	08.30	03.30		Disk fail at SBR Garden	-
8		Keesara	Kadevi & Ankireddypally	11KV	Keesara	12.55	17.55	05.00		220KV line fallen on Kadevi & Anikireddy pally line	-
9		Nagaram	Bandlaguda	11KV	Keesara	11.58	14.20	15.02		Pin insulaotr fail at Prajasai garden	-
10		Nagaram	SN colony	11KV	Keesara	15.08	17.58	02.50		tree fallenon 11kvline at Sn colony	-
11		P&T colony	Chengicherla	11KV	Keesara	04.15	06.13	01.58		Line petroling done no falt found	-
12		P&T colony	Canara nagar	11KV	Keesara	04.30	09.30	05.00		3no Pin insulator fail at P&T colony	-
13		P&T colony	Chengicherla	11KV	Keesara	12.05	19.10	07.05		Pin insulator fail at Kamal nagar	-
1	HYD N	Monda Market	Gurudwara	11KV	V	05.05	06.40	01.35	EL,OL,	No Visible Fault	-
2		Bowenpally	Pipe Lie Road	11KV	VI	05.15	06.25	01.10	EL	Pin Insulator flash over at Nethaji Colony	-
3		Macha Bollaram	Reddy Enclave	11KV	C-VI	11.38	13.00	01.22	EL,OL	HT/LT Line snapped at Laxmi Nagar	-
4		Nehru Nagar	West Marredpally	11KV	C-VI	12.30	13.40	01.10	EL	Pin Insulator flash over at West Marredpally	-
1	HYD S	Laxmi Nagar	Shankeshwara Bazar	11KV	VIII	12.15	13.30	01.15	EL,OL	Pin Insulator flash over at Jaipal Reddy Office	-
2		Madannapet	Ashraf Nagar	11KV	VIII	18.45	20.40	01.55	EL	Tree fallen on lines at Alsafa Dairy	-
3		Asmangadh	Saibaba	11KV	VIII	22.58	00.35	01.37	EL,OL-Yph	No Visible Fault	Arranged B/F on 11KV Tirumala Hills feeder
4		Arundathi Colony	Kummarwadi	11KV	VIII	23.30	01.45	02.15	All Indication	Post type, 2No. Pin & Disc insulators flash over at Kummarwadi Cly	-
1	HYD C	Zamistanpur	Jamai Osmania	11KV	II	03.06	04.56	01.50	EL,OL-Yph	Pin Insulator flash over at Jamai Osmania Railway Station	-
2		Amberpet	Golnaka	11KV	II	04.55	07.14	02.19	EL	Pin Insulator flash over at Paradise Apts	-
3		S.D Hospital	Ahmed Nagar OH	11KV	VII	05.12	06.17	01.05	EL,OL-Bph	No Visible Fault	-
4		Erramanzil	Red Rose	11KV	I	05.20	07.03	01.43	EL,OL-Bph	RMU balisted at Red Rose	Arranged B/F on 11KV Vijaya Hospital fdr
5		Erramanzil	Jaffer Ali Bagh	11KV	I	05.20	06.30	01.10	EL,OL-Bph	No Visible Fault	-
6		Industrial Area	Adikmet	11KV	II	12.20	15.00	02.40	EL	Pin Insulator flash over at Voleti Super Market	-
7		Zamistanpur	Dayara Market	11KV	II	12.25	14.10	01.45	OL-Bph	Jumper cut at Captain Cook Hotel	-
8		Amberpet	Patel Nagar	11KV	II	23.03	00.12	01.09	EL,OL-Rph	Faulty loads of 11KV Prem Nagar feeder	-
9		Vittalwadi	APCO	11KV	II	23.18	02.15	02.57	EL,OL-Rph	CT-PT failed at Colour Lab, tree branches on lines at Narayanguda W.W & RMU fault at Canara Bank	-
10		Mothi Mahal	Balancer	11KV	VII	12.34	13.46	01.12	EL,OL-Rph	Pin Insulator flash over at Rethi Galli	-
11		Toli Chowki	Paramount Hills	11KV	VII	12.38	13.58	01.20	EL,OL-Bph	No Visible Fault	-