

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		8		8		8			
8	Hyd	194	1044		6		6		6			
	Total	606	3055	0	16	0	16	0	16	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		8		8		8			
2	NLG	144	988		6		6		6			
3	MDK	107	933		1		1		1			
4	SDPT				6		6		6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	21	0	21	0	21	0	0	
	Grand Total	1082	6468	0	37	0	37	0	37	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.10.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/132KV SS Palkonda	Janampet	33KV	Mahabubnagar	17.03	19.50	02.47	E/L	Insulator failed near Vemula	Janampet	No
2		Mahabubnagar	Hanwada	33KV	Mahabubnagar	16.05	16.30	00.25	E/L	1Phase Not Showing So Loads are Change Over 132KV SS Maddur	Hanwada	No
3		Maddur	Kothapally	33KV	Narayanapet	00.20	06.55	06.35	E/L	Pin Insulator Damaged at Kothapally	Kothapally	No
4		Maddur	Kankurthy	33KV	Narayanapet	15:15	15:45	0:30	E/L	Due to Fault Line Disconnected	Kankurthy	No
5		Wanaparthly	Peddmandadi	33KV	Wanaparthly	17:45	18:30	0:45	E/L	Insulator failed	Peddmandadi	No
6		Kothur	Raghavendra	33KV	Shadnagar	02.00	10.45	08.45	E/L	Tree Fallen on the Line Near Jagurthy company	Raghavendra	No
1	SDPT	Gajwel	Pregnapur	33KV		0:00	13:25	13:25		Insulator failed	Pregnapur	No
2		Gajwel	KDA	33KV		0:00	00.20	00.20		Insulator failed	KDA	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	PERAPALLA	PERAPALLA	11KV	Narayanapet	01.06	06.36	05.30		Insulator failed	No
2		KONDAPUR	BUDDAMARI THANDA	11KV	Narayanapet	07.00	09.00	02.00		Tree fallen on the line	No
3		KANKURTHY	DAMARGIDDA	11KV	Narayanapet	06.30	07.02	00.32		Insulator failed	No
4		Makthal	Sathya sai	11KV	Narayanapet	3:30	9:00	5:30		Insulator failed	No
5		Lingampally	Madwar	11KV	Narayanapet	4:00	8:00	4:00		2 poles Damaged	No
6		Kavarampet	bandamidipally	11KV	Jadcherla	4:25	7:28	3:03		11 KV line cut near Macharam.	No
7		Kothamolgara	Karvena	11KV	Jadcherla	13:35	14:45	1:10		11 KV insulator fail near chevla thanda.	No
8		Midjil	kothur	11KV	Jadcherla	00.00	12.25	12.25		11 KV insulator fail near Kothur (v)	No
1	NLG	Palem	Ogodu	11KV	Nalgonda	7:50	12:40	4:50	EL	11KV Jumper cut	No
2		Gundepuri	Bandlapally	11KV	Suryapet	03.50	07.45	03.55	EL	Insulator flashover	No
3		Nadigudem	Krishnanagar	11KV	Huzurnagar	07.15	09.00	01.45	EL	11 KV Line snapped	No
4		Akupamula	K R Puram	11KV	Huzurnagar	13.10	15.00	01.50	EL	11 KV Line snapped	No
5		Bollepally	Indriyala	11KV	Bhongir	04.20	10.30	06.10	EL	11kv Insulator Failed near pole no 5	No
6		Choutuppal	Prathista	11KV	Choutuppal	5:30	9:00	3:30	EL	11 kv Insulator failed near Thallasingaram village	No
1	MDK	Kistareddypet	Industrial	11KV	Patancheru	5:30	8:55	3:25		Insulator failed	No
1	SDPT	Guruvannapet	Posanpally	11KV	Siddipet	3:05	6:15	3:10		TREE FALL	No
2		Guruvannapet	Tapaspally	11KV	Siddipet	00.00	06.15	06.15		CONDUCTOR SNAPPED	No
3		GOWRARAM	PATHURE	11KV	Gajwel	17.30	19.00	01.30		11KV LINE CUT	No
4		WARGAL	CHOWDARPALLY	11KV	Gajwel	14.00	17.00	03.00		TREE BRANCH FALLEN ON THE 11KV LINE	No
5		THUNKI KHALSA	SHAKARAM	11KV	Gajwel	13:10	14:25	1:15		TREE BRANCH FALLEN ON THE 11KV LINE	No
6		BANDARAM	DARGA	11KV	Gajwel	10:20	15:05	4:45		11KV DISC FAILED	No
1	RR N	BalajiNagar	Kukatpally	11KV	Kukatpally	6:01	7:40	1:39	EL/OL	Ground Petroling No Foutl 11kv Load Added Ramalayam Feeder	No
2		Kandlakoya	Saigeetha Ashramam	11KV	Medchal	18.10	19.10	01.00	EL	Tree fallen on the 11KV Line at Sunflower School	No
1	RR E	Jana Priya	High Tenison	11KV	Sainikpuri	6:15	7:08	0:53		11Kv Pin Insulator failed at Netaji Nagar (LM Venkatesh)	No
2		AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	06.15	07.26	01.11		HT/LT line cut and Insulator failed at ST No 4 Gandhi Nagar (LM Anjaneyulu)	No
3		Moula-Ali	Kailasagiri	11KV	Sainikpuri	14.45	15.45	01.00		11Kv line cut at near Yadava Reddy T/F Galley (L.Insp Venkateshwarulu)	No
4		Chakripuram	S V Nagar	11KV	Keesara	06.00	08.00	02.00		11Kv Pin Insulator failed at S V Nagar Road No.04	No
5		Keesara	Anki Reddy Pally	11KV	Keesara	06.00	07.00	01.00		11Kv Pin Insulator failed at Peddamma Cheruvu	No
6		P&T Colony	Medipally	11KV	Keesara	05.15	08.05	02.50		11KV 2Nos Insulator failed at Sri homes and Bharathpuri Colony	No
7		P&T Colony	Budda Nagar	11KV	Keesara	05.25	08.10	02.45		11KV Line snapped at Budda Nagar	No
8		P&T Colony	Budda Nagar	11KV	Keesara	11:32	15:40	4:08		11Kv Insulator failed at Budda Nagar Road No.07	No
1	HYD N	Gunrock	Medchal	11KV	C-VI	06.30	07.48	01.18	EL	No Visible Fault	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	Salarjung	Madina	11KV	III	06.45	10.00	03.15	EL,OL-Rph	RMU failed at Foot Wear Show Room (1No. DTR kept off)	No
1		Amberpet	Patel Nagar	11KV	II	06.27	08.10	01.43	OL-Rph	No Visible Fault	No
2	HYD C	N.I.M.S.	Naveen Nagar	11KV	I	09.30	11.10	01.40	EL	Cable fault at A.N.R. Center & O/G Jumper cut at SS	No
3		Hussain Sagar	NTT Marg	11KV	I	15.42	16.45	01.03	All Indication	O/G Jumper cut in SS	No
4		Bathukamma Kunta	Saibaba Temple	11KV	II	18:10	19:50	1:40	EL	Pin Insulator flash over at Andhra Bank	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
------	--------	-----------------------	-------------------------	-----	-------------------------	------	----	----------	---------------------	--------------------	---------------------------