

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	1	2	1	2	1			
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	2	4	2	4	2	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	9	2	9	2	9	0	0	
	Grand Total	1082	6468	4	13	4	13	4	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.10.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Wanaparthi	33kv	Wanaparthi	05.05	09.27	04.22		Due to Jumper Cut	Wanaparthi	-
2		Wanaparthi	Kothakota	33kv	Wanaparthi	05.05	11.40	06.35		Disc Failed & Insulator Damaged	Kothakota	-
1	RR N	132KV Medchal	33KV Athiwelly	33kv	Medchal	11.15	12.55	01.40		33KV Line Phase Sequency Problem at Medchal Bawarchi	33KV Athiwelly	-
2		132KV Medchal	33KV Nuthankal	33kv	Medchal	11.15	12.55	01.40		33KV Line Phase Sequency Problem at Medchal Bawarchi	33KV Nuthankal	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 23.10.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	V.K.Palem	Srinivas Nagar	11KV	Miryalaguda	09.00	10.30	01.30	EL	R phase CT oil crushed at sub-station	-
2		Nadigudam	Ramapuram	11KV	Huzurnagar	10.50	12.00	01.10	EL	11KV Line Snapped	-
3		Alingapuram	Chenaipalem	11KV	Huzurnagar	15.30	17.00	01.30	EL	11KV Line Snapped	-
4		Thungathurthy	Ganugubanda	11KV	Suryapet	10.20	11.25	01.05	E/L	Disk failed	-
5		Juloor	Peddagudem	11KV	Choutuppal	11.45	13.30	01.45	EL	11KV Line Snapped near Ali nagar	-
1	SDPT	Mittapally	Mittapally	11KV	Siddipet	06.20	06.40	00.20		B/D - Bird fallen on S-Ph DTR	-
2		Raghavapur	Raorukula	11KV		03.30	08.35	05.05		B/D - Frog touched to disk	-
3		Dubbak	Chellapur	11KV		12.33	14.48	02.15		B/D - Frog touched to disk	-
4		RAIPOLE	THIMMAKAPALLY	11KV	Gajwel	12.25	13.40	01.15		INSULATOR FAILED	-
1	RR N	Subhash Nagar	Pragha Tools	11KV	Medchal	14.33	15.28	00.55		11KV Disc failed & replaced at GLR	-
1	HYD N	Monda Market	Monda Market	11KV	V	13.40	16.40	03.00	EL,OL-Rph	Bird fault on lines, 2No. Disc Insulators flash over & Conductor snapped at Monda Market	
2		Seethaphalmandi	Namalgundu	11KV	V	14.10	16.00	01.50	EL,OL	-----	
1	HYD C	Golconda	Narayanamma College	11KV	VII	03.10	04.25	01.15	EL,OL-Rph	AB Cable burnt out at Rajiv Nagar	