

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	1	5	0	0	
	Grand Total	1082	6468	1	7	1	7	1	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.10.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kothur	Ennar Steel	33KV	Shadnagar	04.15	10.20	06.05	E/L	Insulator Failed Near High Way Road at Ennar Steel Company		NO

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 24.10.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	B.N.Thanda	Vardhapuram	11KV	Huzurnagar	17.00	18.00	01.00	E/L	11KV Line Snapped	-
2		Venkatapuram	Venkatapuram	11KV	Bhongir	02.00	09.45	07.45	EL/OL	11kv Insulator Failed near Venkatapuram (V)	-
1	SDPT	Ahmedipur SS	Kolgur Feeder	11KV	Gajwel	07.00	08.40	01.40		Jumper Cutting	-
2		Komuravelly	Inapur Agl	11KV	Husnabad	08.45	11.49	03.04		Line fault, same rectified	-
3		Bekkal	Bairanpally	11KV	Husnabad	13.10	14.50	01.40		Insulator failure same rectified	-
1	RR N	Medchal	Check Post	11KV	Medchal	07.30	08.10	00.40	EL	No Fault	-
1	HYD C	Hussain Sagar	RBI Quarters	11KV	Saifabad	16.05	17.10	01.05	EL	Cable fault in between Assembly to Jubilee Hall	-