

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | | 2 | | 2 | | 2 | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | | 1 | | 1 | | 1 | | | |
| | Total | 606 | 3055 | 0 | 3 | 0 | 3 | 0 | 3 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | | | | | | | | | |
| 2 | NLG | 144 | 988 | | 4 | | 4 | | 4 | | | |
| 3 | MDK | 107 | 933 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 0 | 4 | 0 | 4 | 0 | 4 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 0 | 7 | 0 | 7 | 0 | 7 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Date: 31.10.2020

Circle-wise 33KV Breakdowns

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|-----|----------------------|------|----|----------|------------------|--------------------|-----------------------|---------------------------|
| 1 | MBNR | | | | NIL | | | | | | | - |
| 2 | NLG | | | | NIL | | | | | | | - |
| 3 | MDK | | | | NIL | | | | | | | - |
| 4 | RR S | | | | NIL | | | | | | | - |
| 5 | RR N | | | | NIL | | | | | | | - |
| 6 | RR E | | | | NIL | | | | | | | - |
| 7 | HYD | | | | NIL | | | | | | | - |

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 31.10.2020

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|---------------------------|
| 1 | NLG | Nidmanoor | Bankapuram | 11KV | Miryalaguda | 08.10 | 11.30 | 03.20 | EL | 11KV Conductor snapped near village | - |
| 2 | | Penpahad | Anajipuram | 11KV | Suryapet | 03.30 | 06.40 | 03.10 | E/L | Insulator Flash Over | - |
| 3 | | N.B.Gudem | Redlakunta | 11KV | Huzurnagar | 07.00 | 08.45 | 01.45 | EL | 11 KV LINE SNAPPED | - |
| 4 | | Suddala | Theriyala | 11KV | Bhongir | 03.50 | 09.10 | 05.20 | EL/OL | 63 KVA DTR Failed at SS- 24 Near Anantharam Village. | - |
| 1 | RR N | Thumkunta | Thumkunta | 11KV | Medchal | 07.50 | 09.45 | 01.55 | BD | HT/LT Line Phase to Phase at SC Colony | - |
| 2 | | Athiwelly | SPIC | 11KV | Medchal | 13.15 | 14.45 | 01.30 | BD | No Fault | - |
| 1 | HYD C | Narayanguda | Narayanguda | 11KV | II | 23.30 | 01.00 | 01.30 | EL | Disc Insulator flash over at Atchayya Nagar PT | |