

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		3		3		3			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>6</b>	<b>2</b>	<b>6</b>	<b>2</b>	<b>6</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 01.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Achampet	Lingal	33kv	Nagarkurnool	22.50	08.15	09.25	E/L	Due to disc flash over	Lingal	-
2		Amarchitha	Atmakur	33kv	Wanaparthi	21.30	22.00	00.30	E/L	33KV Line Fault & Line Petroing Feeder Stud ok no Visabule Fault	Atmakur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 01.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Madugulapally	Kukadam	11kv	Nalgonda	09.15	11.00	01.45	EL	Insulator failed	-
2		Mupparam	Mupparam	11kv	Miryalaguda	16.05	17.15	01.10	EL	11KV Jumper cut near Vempadu Village Road Agl.DTR area	-
3		Athmakur(S)	Dacharam	11kv	Suryapet	02.00	06.30	04.30	E/L	Insulator flashover	-
4		Mandollagudem	Nelapatla	11kv	Choutuppal	00.15	07.30	07.15	EL/OL	Solid core Insulator failed Thumbaloni bavi.	-
1	SDPT	Indore	Town PS	11kv	Siddipet	06.19	07.14	00.55		B/D for due to bird	-
2		ANAJIPUR SS	MANTHUR FEEDER	11kv	Gajwel	13.42	18.53	05.10		INSULATOR FAILURE	-
1	RR E	Polytechnic	Srinivasapuram	11kv	Habsiguda	12.17	13.20	01.03		11KV Jumper cut & 11KV Disc failed at Babu Rao Hotel	-
1	HYD C	Langer House	Pensionpura	11kv	VII	02.00	03.05	01.05	EL,OL-Rph	AB Cable fault at Azam Kirana Store	Arranged B/F on 11KV Fathe Darwaza fdr
2		Zamistanpur	Balaji Nagar	11kv	II	15.05	16.17	01.12	EL-Yph	Cable fault	Arranged B/F on 11KV Jamai Osmania fdr
1	HYD N	Bowenpally	Gowtham Nagar	11kv	VI	18.43	20.11	01.28	EL	Lines touching near 1st line AB Switch, C.T.E	Arranged B/F on 11KV Akshaya Enclave fdr