

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	9		8		8				1 No. 33K Still
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	9	5	8	5	8	5	0	0	
	Grand Total	1082	6468	9	10	8	10	8	10	0	0	

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	Jadcherla	33KV	Jadcherla	09.07	11.30	02.23	E/L	Jumper Cut at 132KV SS Polepally	Jadcherla	NO
2		Polepally	Gangapur	33KV	Jadcherla	20.18	20.51	00.33	E/L	Due to Rain	Gangapur	Alternate Supply Arranged from 33KV Konded SS at 20:51Hrs.
3		Makthal	Narva	33KV	Narayanapet	19.30	19.50	00.20	E/L	Due to Rain	Narva	Alternate Supply Arranged from 33KV Ekaspur from 132KV Marikal 19:50Hrs.
4		Maddur	Pallerla	33KV	Narayanapet	19.55	Still		E/L		Pallerla	NO
5		Marikal	Kondapur	33KV	Narayanapet	20.05	00.00	03.55	E/L	Jumper Cut at 33KV Marikal SS DP Pole & Jumper connecting at 132KV SS Yard Line Side	Kondapur	NO
6		Gadwal	Oil Seeds	33KV	Gadwal	15.15	19.10	03.55	E/L	insulator Failed at Jammichedu River	Oil Seeds	NO
7		Nagarkurnool	Bijinepally	33KV	Nagarkurnool	14.20	15.15	00.55	E/L	33KV Insulator Failed	Bijinepally	Alternate Supply Arranged from 132KV Ghanapur 33KV Lattupally feeder at 15:15Hrs.
8		Amangal	Mudwin	33KV	Shadnagar	18.30	20.20	01.50	E/L	33KV Insulator Failed at Kadthal Town	Mudwin	NO
9		Amangal	Mudwin	33KV	Shadnagar	20.55	23.50	02.55	E/L	Peacock Died On the Line	Mudwin	NO

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 01.08.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Indloor	DVK Road	11KV	Nalgonda	16.45	17.40	00.55	E/L	Tree branches fallen on 11Kv line at opposite I-Town PS	-
2		Gollaguda	RTC colony	11KV	Nalgonda	16.40	18.05	01.25	E/L	Tree branches fallen on 11Kv line at Maisaiah circle	-
3		Reddygudem	Kothagudem	11KV	Suryapet	02.40	06.30	03.50	E/L	11Kv Conductor snapped	-
4		Pamukunta	Singaram	11KV	Bhongir	10.10	14.40	04.30	EL/OL	11kv Line snapped near Pakunta (V) Airtel Tower	-
5		Mandollagudem	Peddakondur	11KV	Choutuppal	08.43	12.03	03.20	EL/OL	11kv Line Snapped Burugu Kirshna Reddy Poltery form	-
1	RR N	Devarayamjal	Pothaipally	11KV	Medchal	07.40	08.30	00.50		11KV AB Cable failed at NTR Statue, Yamjal Village	-
1	HYD N	Bhudevi Nagar	Yadamma Nagar	11KV	C-VI	01.42	03.10	01.28	EL,OL	Cable fault	Arranged B/F on 11KV Kanajiguda feeder
2		Hakimpet	Risala Bazar	11KV	C-VI	14.50	16.01	01.11	EL,OL-Rph	Disc Insulator flash over at Risala Bazar	-
1	HYD S	Hyderguda	W.S.Colony	11KV	III	15.01	16.02	01.01	A/R tripped	No Visible Fault	-
2		C.R.P.F.	Baba Nagar	11KV	III	19.00	20.10	01.10	EL	Pin Insulator flash over at Omer Colony	-