

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5		5		5				
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	5	4	5	4	5	4	0	0	
	Grand Total	1082	6468	5	7	5	7	5	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.09.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	11.20	12.45	01.25	O/L	Tree Fallen on the line near by RamreddyGuda Water works	Machanpally	No
2		Makthal	Narva	33KV	Mahabubnagar	21.35	23.25	01.50	E/L	2Nos Insulator damaged near Rampur	Narva	No
3		Maddur	Mogalmdaka	33KV	Mahabubnagar	20.40	00.50	04.10	E/L	No Visible Fault due to Heavy Wind Gale & Rain	Mogalmdaka	No
4		Ghanapur	Lattupally	33KV	Wanaparthi	18:32	20:10	1:38	E/L	No Visible Fault due to Heavy Wind Gale & Rain &	Lattupally	No
5		Chinnamaroor	Velgonda	33KV	Wanaparthi	20.10	20.55	00.45	E/L	AB Switch Open at Velgonda SS	Velgonda	No

TSSPDCL - LMRC / Corporate office

Date: 07.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	S.V College	New Bus stand	11KV	Suryapet	6:20	8:15	1:55	E/L	Jumper Cut	No
2		Panthangi	Panthangi Agl	11KV	Choutuppal	07.48	10.07	02.19	EL/OL	11 kv Line snapped near Areygudem village	No
3		Velmagudem	Peddagudem	11KV	Miryalaguda	08.30	11.40	03.10	EL/OL	Jumper cut	No
1	SDPT	Mubharasapur	Mubharasapur	11KV	Doulathabad	5:25	6:50	1:25		100 KVA DTR Copper patti broken	No
1	RR N	Nizampet	Nizampet	11KV	Kukatpally	17:45	19:45	2:00		Pin insulator failed	No
2		Nuthankal	Bharathi	11KV	Medchal	08.40	09.30	00.50		Tree Branch fallen on the 11KV Line at Goshala, Nuthankal Village	No
1	HYD C	Osm. University	Boudha Nagar	11KV	II	17.00	18.26	01.26	EL	Cable fault	Arranged B/F on 11KV Jamai Osmania fdr