

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		4		4		4			
6	RR(N)	54	550		7		7		7			
7	RR(E)	168	403		13		13		13			
8	Hyd	194	1044		14		14		14			
	Total	606	3055	0	38	0	38	0	38	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		19		19		19			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	19	1	19	1	19	0	0	
	Grand Total	1082	6468	1	57	1	57	1	57	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Chinnamaroor	Jetaprol	33KV	Wanaparthi	09.05	10.55	01.50	EL	Pin Binding Failed at Peddamuddanoor (V)	Jetaprol	Chinnamarror lift AB Switch open at Chinnambai

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 12.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Arlagaddagudem	Tatikal	11KV	Nalgonda	01.50	09.50	08.00	E/L	11 KV Insulator Failed	-
2		Palem	Ogodu	11KV	Nalgonda	01.10	08.25	07.15	E/L	Jumper Cut	-
3		Kalimera	Kalimera	11KV	Nalgonda	04.10	10.15	06.05	E/L	Insulator Failed	-
4		Madgulapally	Kukkadam	11KV	Nalgonda	05.20	11.20	06.00	E/L	Jumper Cut	-
5		Pamanagundla	Pittampally	11KV	Nalgonda	04.00	09.45	05.45	E/L	Jumper Cut	-
6		Mushampally	Mushampally AGL	11KV	Nalgonda	05.00	10.00	05.00	E/L	11 KV Disc Failed	-
7		Tadakamalla	Molkapatnam	11KV	Miryalaguda	09.10	11.06	01.56	E/L	Conductor failed	-
8		Haliya	ND Palem	11KV	Miryalaguda	00.00	05.20	05.20	E/L	Conductor failed	-
9		Thirumalagiri	Thonda	11KV	Suryapet	03.40	07.30	03.50	E/L	Insulator Flashover	-
10		Penpahad	Annaram	11KV	Suryapet	04.30	08.40	04.10	E/L	Disc Flashover	-
11		Karvirala	Keshavapuram	11KV	Huzurnagar	00.45	07.15	06.00	E/L	11 KV LINE SNAPPED	-
12		IDA	Singannagudem	11KV	Bhongir	05.05	07.50	02.45	E/L	11 kv Disc failed at teachers colany near Bhongir town	-
13		Anantharam	Hanmapuram	11KV	Bhongir	01.40	09.00	07.20	E/L	11 kv Disc Failed at Poultry farm near Hanmapuram village	-
14		Nandanam	Anajipur	11KV	Bhongir	03.00	09.30	06.30	E/L	2 NO's 11 kv Pin insulators failed at Thurkoni thota near Anajipur village	-
15		Alair	Ikkurthy	11KV	Bhongir	00.50	08.00	07.10	E/L	100 kva DTR Failed at SS-7 near Ikkurthy village	-
16		Sharajipet	Sharajipet	11KV	Bhongir	05.00	06.40	01.40	E/L	11 kv Disc failed near Sharajipet village	-
17		Yellanki	Siripuram	11KV	Choutuppal	02.15	10.10	07.55	E/L	11 KV Insulator failed near Yellanki village	-
18		Choutuppal ipds	Thangedipally	11KV	Choutuppal	00.52	05.20	04.28	E/L	11 kv Disc failed at Balaji function hall near Thangedipally village	-
19		D.Nagaram	D.Nagaram Agl	11KV	Choutuppal	01.30	09.20	07.50	E/L	11 kv Disc failed near Thumbavi thanda	-
1	RR N	Petbasheerabad	GBR Culb	11KV	Medchal	01.36	02.40	01.04	EL	Tree Fallen on the 11KV Line at Police Station	-
2		Petbasheerabad	Vaishnavi Enclave	11KV	Medchal	21.15	23.05	01.50	EL	11KV Jumper cut and replaced at Vaishnavi Enclave	-
3		Ravalkole	Ravalkole	11KV	Medchal	05.16	06.49	01.33	EL	11KV Pin Insulator failed & replacement at Masjid backside,Ravalkole	-
4		Kistapur	IDA Hanuman	11KV	Medchal	04.10	05.30	01.20	EL/OL	Tree Fallen on the 11KV Line at Ravalkole Kaman	-
5		Yellampet	IDA Yellampet	11KV	Medchal	16.20	17.25	01.05	EL	Tree fallen on the 11KV Line at Aruna Godham,Dabeerpur X Road	-
6		Shameerpet	Nalsar	11KV	Medchal	22.20	23.00	00.40	EL/OL	Tree fallen on the 11KV Line at Registration Office	-
7		Prashanthi Hills	Prashanthi Hills	11KV	Kukatpally	22.30	23.55	01.25	EL/OL	11KV Insulator Failed at Balaji water Plant	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	NGRI	Scientist Colony	11KV	Habsiguda	02.52	04.40	01.48		11KV Post Of Insulator failed near Devi Residency at Habsiguda & Half of Load B/F supply taken from 11KV Snehapuri feeder & 11KV Habsiguda feeder	-
2		Anandbagh	PB Colony	11KV	Sainikpuri	12.03	13.20	01.17		11Kv AB Cable fail at Simhadri Nagar (AE)	-
3		Kushaiguda	Sri Ran Nagar	11KV	Sainikpuri	21.22	22.45	01.23		Big Tree fallen on 11Kv line at Gandhi Nagar Govt School (AE)	-
4		Aushapur	Ankushapur	11KV	Keesara	10.30	12.00	01.30		11KV Pin Insulator failed at Aushapur Village Backside	-
5		P&T Colony	Chengicherla	11KV	Keesara	00.30	02.00	01.30		11KV Insulator failed near A V Constructions	-
6		Keesara	Kadevi	11KV	Keesara	20.40	21.40	01.00		11KV Insulator failed at Keesaragutta	-
7		Anandbagh	PB colony	11KV	SAINIKPURI	20.50	22.05	01.15	EL/OL	Due to Rain,11KV Cable Failed at PB Colony	11Kv Chandragiri Colony
8		Cherlapally-2	Gajanana Tamara (Dedicated)	11KV	SAINIKPURI	20.46	23.26	02.40	EL	Due to Rain & Insulator Failed at Itech Hydrolic	
9		Vanasthalipuram	Vanasthalipuram	11KV	CHAMPAPET	00.20	01.45	01.25	EL/OL	Tree fallen on 11KV line at Telephone Quarters	
10		Auto nagar	High court colony	11KV	SAROORNAGAR	06.20	07.50	01.30	EL	LABS open at Deer park	
11		Lenin nagar	Janapriya	11KV	CHAMPAPET	07.15	08.16	01.01	EL/OL	11Kv Line twisted at Janapriya	
12		Nandanavanam	Janardhan reddy	11KV	CHAMPAPET	07.40	08.50	01.10	EL	Disc failed & Jumper snapped at Gayathri nagar	
13		Rajeev Swagruha	Rajeev Swagruha Ph-II (B&C)	11KV	SAROORNAGAR	09.44	16.14	06.30	EL	Cable endkit failed at B-Block	
1	RR south	Mamidipally	Aljabri colony	11KV	KANDUKUR	02.35	04.30	01.55	EL	11KV Disc failed at Estama ground,Aljabri colony	
2		APPA	Darga	11KV	RAJENDRA NAGAR	04.35	05.55	01.20	OL	11KV Disc failed near GVK opposite	
3		Balaji nagar	Balaji nagar	11KV	KONDAPUR	01.20	02.57	01.37	EL/OL	Tree fallen on 11KV line at Ramdev hospital	
4		Manikonda	Dollar hills	11KV	IBRAHIMBAGH	03.35	04.37	01.02	EL	Breaker mechanical problem & Pin insulator failed at Shivaji nagar colony	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Jubilee Hills	Jubilee Hills	11KV	X	00.45	02.30	01.45	EL,OL-Bph	Tree branches fallen on lines	Arranged B/F on 11KV Road No.22 feeder
2		Clock Tower	Station Road	11KV	V	01.03	02.18	01.15	EL	No Visible Fault	-----
3		Macha Bollarum	Chinthal Bazar	11KV	C-VI	01.17	02.24	01.07	EL	Tree branches fallen on lines at Chinthal Bazar	-----
4		Road No.2	E-Seva	11KV	X	01.44	03.30	01.46	EL	Sparking AB Switch at Road No.14	-----
5		Seethaphalmandi	Medibavi	11KV	V	03.00	04.10	01.10	All Indication	No Visible Fault	Arranged B/F on 11KV Seethaphal Mandi feeder
6		I.D.P.L	Wonder Plast	11KV	VI	07.14	12.10	04.56	EL,OL-Bph	Line AB Switch Jumper cut at Canteen Hall & Big Basker HT Service CT PT fault	-----
7		Bowenpally	Akshaya Enclave	11KV	VI	11.10	12.35	01.25	EL,OL-Yph	Sparking line AB Switch at Fish Market	-----
8		Clock Tower	Sangeeth	11KV	V	20.12	21.42	01.30	EL,OL-R&Yph	Cable Fault	Arranged B/F on 11KV St.Merry fdr
9		Pragatools	Giri Nagar	11KV	VI	23.07	03.18	04.11	OL-Rph	Insulator flash over at APHB Colony	-----
1	HYD C	A.S.R Raju Nagar	Golla Basti	11KV	VII	13.04	14.04	01.00	EL	Cable damaged by GHMC at King Palace Hotel	Arranged B/F on 11KV Navodya Colony feeder
2		A.S.R Raju Nagar	GHMC Park	11KV	VII	13.06	14.13	01.07	EL,OL	Cable damaged by GHMC at King Palace Hotel	Arranged B/F on 11KV Sharada Nagar feeder
3		Golnaka	Haraspenta	11KV	II	21.40	23.18	01.38	EL,OL	Cable Fault	Arranged B/F on 11KV Nehru Ngr fdr
4		Amberpet	Play Ground	11KV	II	23.50	03.50	04.00	EL	AB Switch fault at Patel Compound	-----
5		Zamistanpur	Laxmi Nagaryan Nagar	11KV	II	23.53	02.37	02.44	EL,OL-Yph	Tree branches fallen on lines at Parsigutta	-----