

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		16		16		16			
2	NLG	144	988		8		8		8			
3	MDK	107	933	1	4	1	4	1	4			
4	SDPT			7	11	7	11	6	11	1		1 No. 33KV Still
5	RR(S)	58	396									
6	RR(N)	38	114	1		1		1				
7	RR(E)	22	133									
	Total	476	3413	9	39	9	39	8	39	1	0	
	Grand Total	1082	6468	9	50	9	50	8	50	1	0	

TSSPDCL - LMRC / Corporate office

Date: 15.09.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Jharasangam	33KV	Zaheerabad	12:00	13:00	1:00		Tree fallen on the line	Jharasangam	No
1	SDPT	Habsipur	Ragothampally	33KV	Siddipet	1:20	7:55	6:35		Disc Replacement	Ragothampally	No
2		Mustyala	Cheriyal	33KV	Husnabad	00.35	08.05	07.30		Pin insulator failure	Cheriyal	No
3		Gajwel	KDA	33KV	Gajwel	20.10	Still				KDA	
4		Gajwel	Express	33KV	Gajwel	19.55	20.00	00.05		Due to rain	Express	132KV Gajwel - 33KV Medinipur
5		Gajwel	Mulugu	33KV	Gajwel	20.55	21.25	00.30		Breaker Problem	Mulugu	132KV Thunkibollaram - 33KV Yerravelly
6		Thunkibollaram	Markook	33KV	Gajwel	22.12	23.00	00.48		Line Problem	Markook	132KV Thunkibollaram - 33KV Yerravelly
7		Thukkapur	Dommata	33KV	Gajwel	19:30	20:00	0:30		Line Problem	Dommata	132KV Habsipur - 33KV Dommata
1	RR N	132KV Medchal	Kompally	33KV	Medchal	14:46	18:40	3:54	EL/OL	33KV Cable Kit Failed at Aprana Opp.	Kompally	Backfeeding arranged to 33KV Dulapally feeder from 132KV Chintal

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Boothpur	Karvena	11KV	Jadcherla	8:30	10:30	2:00		11 KV Jumper cut near Murthaiha gutta side	No
2		KYATHANPALLY	WATHUGUNDLA	11KV	Narayanapet	02.40	08.32	05.52		Breakdown due to disc failue	No
3		KYATHANPALLY	AYYAWARIPALLY	11KV	Narayanapet	02.40	07.41	05.01		Breakdown due to disc failue	No
4		KYATHANPALLY	KYATHANPALLY	11KV	Narayanapet	19.40	20.43	01.03		Breakdown due to disc failue at agl dtr	No
5		EKLASPUR	IVRCL CANAL	11KV	Narayanapet	07.10	09.20	02.10		Breakdown due to disc failue	No
6		KONDAPUR	KONDAPUR	11KV	Narayanapet	17.00	19.00	02.00		Breakdown due to disc failue	No
7		Mohammadabad	Mohammadabad	11KV	Narayanapet	12.35	13.15	00.40		11KV conductir snapped & cut on LT line	No
8		Mohammadabad	Annareddypally	11KV	Narayanapet	17.46	20.14	02.28		Break Down due to Heavy Wind And Gale	No
9		Mohammadabad	Shaikpally	11KV	Narayanapet	18.14	20.54	02.40		Break Down due to Heavy Wind And Gale	No
10		Gundumal	Amlikuntla	11KV	Narayanapet	05.30	07.30	02.00		Break Down due to 11 KV insulator faile	No
11		Gundumal	Amlikuntla	11KV	Narayanapet	22.00	23.40	01.40		Break Down due to Heavy Wind And Gale	No
12		Salkarpet SS	Pagdiyali	11KV	Narayanapet	17.45	19.00	01.15		Break Down Due to 11 KV line Cut	No
13		Utkoor	Nidugurthy	11KV	Narayanapet	17.45	18.15	00.30		Break Down Due to LT conductor cut	No
14		Gudeballur	Kothapally	11KV	Narayanapet	10.30	14.00	03.30		Break Down due to 11KV Disc failure	No
15		Lingampally	Lingampally	11KV	Narayanapet	05.30	10.30	05.00		11KV Disc failure DTR problem	No
16		Pasupula	satysai	11KV	Narayanapet	11:19	13:10	1:51		Break Down due to 11KV Disc failure	No
1	NLG	Akupamula	Kodndarampuram	11KV	Huzurnagar	01.30	07.30	06.00	EL	11 KV Liine snapped	No
2		Gondiryala	Gondiryala-2	11KV	Huzurnagar	02.10	08.00	05.50	EL	11 KV Liine snapped	No
3		Eduloor	Kurumarthy	11KV	Nalgonda	06.30	11.30	05.00	EL	11 KV Line Jumper Cut	No
4		Kethepally	Korlapahad	11KV	Nalgonda	6:00	12:05	6:05	EL	11 KV Line Jumper Cut	No
5		Settipalem	Vemulapally Agl.	11KV	Miryalaguda	7:35	10:30	2:55	EL	11KV Insulator failed near Vasantha rice mill area	No
6		Nidmanoor	Shakapuram	11KV	Miryalaguda	16:40	17:40	1:00	EL	11KV jumper cut near Marlagadda village	No
7		Thadakamalla	Thadakamalla	11KV	Miryalaguda	13:15	15:12	1:57	EL	11KV conductor snapped	No
8		Paladugu	Duppally	11KV	Bhongiri	06.15	11.00	04.45	EL/OL	11kv Disc Failed near Duppally Village	No
1	MDK	Patancheru Town	Town	11KV	Patancheru	13:25	14:10	0:45		BD due to Cable fault	No
2		Patancheru Town	Town Indl.	11KV	Patancheru	13.25	13.55	00.30		BD due to CT PT failed	No
3		Kistareddypet	Mytri	11KV	Patancheru	08.00	08.25	00.25		BD due to Tree fallen on the line	No
4		Bollaram - II	Rupa	11KV	Patancheru	05.23	09.30	04.07		Conductor Snapped	No
1	SDPT	Komaticheruvu	Housing Board	11KV	Siddipet	7:50	8:40	0:50		B/D 11 KV Jumper wire cut	No
2		Chittapur	Chittapur	11KV	Siddipet	05.37	07.20	01.43		B/D 11 KV Jumper wire cut	No
3		Jangapally	Veerareddypally	11KV	Siddipet	01.00	13.30	13.30		Disc failed	No
4		Peddachepyal	Alwal	11KV	Siddipet	09.04	11.39	02.35		11 KV Lines stringing	No
5		JAGADEVPUR	DOWLAPUR AGL	11KV	Gajwel	18.10	18.45	00.35		Jumper cut	No
6		KODAKANDLA	KODAKANDLA TOWN	11KV	Gajwel	05.00	07.10	02.10		Jumper cut	No
7		SEETHARAMPALLY	SEETHARAMPALLY	11KV	Gajwel	15.34	17.10	02.24		Disc failed	No
8		MARPADAGA	MARPADAGA AGL2	11KV	Gajwel	01.45	06.30	04.45		Due to rain	No
9		THUKKAPUR	INDUSTRIAL FEEDER	11KV	Gajwel	00.30	09.25	08.55		Disc failed	No
10		DOULTHABAD	DOULTHABAD TOWN	11KV	Gajwel	07.47	10.16	02.29		Tree branches fallen on the line	No
11		Chityal	Dommeta	11KV	Husnabad	19:45	20:50	1:05		Jumper problem	No
1	RR N	Kandlakoya	Kandlakoya	11KV	Medchal	2:10	3:00	0:50	EL	11KV Pin Insulator failed at LG Godam Side	No
2		Aliabad	Jaganguda	11KV	Medchal	14.30	15.20	00.50	EL/OL	2 Nos. 11KV Poles damaged by Auto at BV Farm (11KV Jumper Opened, 63KVA DTR Only off)	No
1	RR E	Uppal Kalsa	Shanthi Nagar	11KV	Habsiguda	1:30	3:25	1:55		11KV Pin Insulator failed near Balachandra Apartment at Shanthi Nagar	No
2		Kushaiguda	Sri Ram Nagar	11KV	Sainikpuri	05.35	07.24	01.49		Big Tree fallen on 11Kv line at Gandhi Nagar	No
3		Cherlapally-II	ICCOM	11KV	Sainikpuri	22.27	23.40	01.13		Tripped on EL/OL due to 11Kv Insulator failed at Pooja Boitech Company & Heavy Rain	No
4		Aushapur	NFC nagar	11KV	Keesara	00.50	01.40	00.50		Insulator fail at D1 Gadda	No
5		Aushapur	Aushapur	11KV	Keesara	10:04	11:30	1:26		Insulator fail at SVR Collage	No
1	HYD N	Gymkhana	Picket	11KV	C-VI	01.08	02.35	01.27	EL,OL-Bph	Road Crossing UG Cable damaged at J.B.S Bus Stand	No
2		Bhudevi Nagar	Adarsh Nagar	11KV	C-VI	18:02	19:30	1:28	EL	Disc Insulator flash over at Padmavathi Apts	No
3		R.P Nilayam	Vaisnavi Matha Temple	11KV	C-VI	23:05	0:40	1:35	EL	Cable fault at Vaisnavi Matha Temple	No
1	HYD S	Gosha Mahal	M.J.Market	11KV	IX	01.54	03.30	01.36	EL,OL-Bph	No Visible Fault	No