

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		2		2		2			
2	NLG	144	988		11		11		11			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	14	0	14	0	14	0	0	
	Grand Total	1082	6468	0	21	0	21	0	21	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.09.2020

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
NIL												

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Maddigatla	11KV	Jadcherla	11.00	13.30	02.30		Pin binding failure at Nallagutta Side.	No
2		Narayanpet	Maddur	11KV	Narayanapet	18.00	18.43	00.43		11KV Disc failed	No
1	NLG	Penpahad	Poltlapahad	11KV	Suryapet	9:15	12:00	2:45	E/L	Insulator failed	No
2		Dirsincherla	Yallapuram	11KV	Huzurnagar	02.00	07.30	05.30	EL	11KV Line snapped	No
3		Repala	Repala	11KV	Huzurnagar	09.35	11.00	01.25	EL	11KV Line snapped	No
4		Kannekal	Machinapally	11KV	Miryalaguda	11.15	13.24	02.09	EL	Jumper Cut	No
5		MT.Pally	Dathaipally	11KV	Bhongir	02.00	08.40	06.40	EL	11KV Insulator failed	No
6		Pamukunta	Singaram	11KV	Bhongir	03.00	07.20	04.20	EL	11 kv Insulator failed at Dhaba.Kanakaiah well near Singaram village	No
7		Choutuppal	Thangedipally	11KV	Choutuppal	11.30	14.00	02.30	EL	11 KV Disc failed near Damera village.	No
8		Redlarepaka	Dasireddygudem	11KV	Choutuppal	00.05	08.30	08.25	EL	11 kv Disc failed near Dasireddygudem village.	No
9		Cherukupally	Dindi Rural	11KV	Devarakonda	10.50	16.20	05.30	EL	11 KV Disc failed	No
10		K.M.Pally	C.A.Pally	11KV	Devarakonda	14.20	16.15	01.55	EL	11 KV Line cut	No
11		Velugupally	G.K.Annaram	11KV	Nalgonda	4:00	6:00	2:00	EL	11 KV Line jumpet cut	No
1	MDK	Hathnoora	Town Ind	11KV	Jogipet	13:00	14:00	1:00		Jumper Cut	No
1	RR N	Jeedimetla-I	Shapurnagar	11KV	Jeedimetla	11:40	14:15	2:35		11kv jumper cut near substation	No
2		Aleap	Pragathinagar	11KV	Jeedimetla	11.27	13.00	01.33		11kv Jumper Cut & 11kv Conductor Snapped	No
3		Uddamarry	Usharpally	11KV	Medchal	11.26	15.30	04.04		10KVA T/F failed at Mallanna Temple	No
1	RR E	Cherlapally-IV	Sai Nagar	11KV	Habsiguda	11:15	12:25	1:10		Street light cable touched to 11KV line at KLR Industry	No
2		Peerzathiguda	Shankar Nagar	11KV	HBG	00.50	02.00	01.10		11KV Copper patti cut at at Shankar Nagar	No
1	HYD N	Tirumalagiri	Mangapuram	11KV	C-VI	10.32	11.45	01.13	EL,OL-Rph	Jumper cut at Green field colony	No
2		R.P.Nilayam	Venkatapuram	11KV	C-VI	12:24	13:34	1:10	EL,OL-Bph	Faulty loads of 11KV Kiran Talkies for	No