

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		7		7		7			
8	Hyd	194	1044		14		14		14			
	Total	606	3055	0	25	0	25	0	25	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5		5		3		2		2 No.s 33kv still
2	NLG	144	988		7		7		7			
3	MDK	107	933	1	6	1	6	1	6			
4	SDPT			3	10	3	10	2	6	1	4	1 No.s 33kv still & 4 No.s 11KV Still
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	9	23	9	23	6	19	3	4	
	Grand Total	1082	6468	9	48	9	48	6	44	3	4	

TSSPDCL - LMRC / Corporate office

Date: 25.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SVS Edira	33kv	Mahabubnagar	17.05	17.15	00.10	E/L	Jumper cut at SVS Hospital back side	SVS Edira	-
2		Maddur	Mogalmadka	33kv	Narayanapet	23.40	23.50	00.10	EL	Due to Heavy Rain	Mogalmadka	-
3		Narayanapet	Kotakonda	33kv	Narayanapet	23.20	00.00	00.40	EL	Break Down Not Rectified Due to Heavy Rain	Kotakonda	-
4		Makthal	Jaklair	33kv	Narayanapet	23.40	00.00	00.20	EL	Break Down Not Rectified Due to Heavy Rain	Jaklair	-
5		Shadnagar	Mogiligidda	33kv	Shadnagar	07.15	09.00	01.45	E/L	1Phase Not Showing	Mogiligidda	-
1	MDK	Borapatla	Covalent	33kv	Jogipet	17.27	20.56	03.29		B/D due to Tree branches fallen on the line	Covalent	-
1	SDPT	Palamakula	Rajgopalpet	33kv	Siddipet	18.25	00.00	Still		B/D due to Tree branches fallen on the line	Rajgopalpet	-
2		Gajwel	Pregnapur	33kv	Gajwel	15.15	15.35	00.20		BDDue to Heavy Rain	Pregnapur	Jagadevpur
3		Shanigaram	Koheda	33kv	Husnabad	17.20	17.40	00.20		BDDue to Heavy Rain	Koheda	Husnabad

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 25.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palem	Ogodu	11KV	Nalgonda	10.50	11.50	01.00	EL	Insulator Failed	-
2		Singarajupally	Thowkalapur	11KV	Devarakonda	10.00	14.00	04.00	EL	Tree Flowen	-
3		Singarajupally	Bramanaply	11KV	Devarakonda	10.30	11.30	01.00	EL	11 AB Switch Male Female Probleam	-
4		Athmakur(S)	Dacharam	11KV	Suryapet	03.42	06.16	02.34	E/L	Jumper cut	-
5		Thungathurthy	Pasnoor	11KV	Suryapet	06.40	08.16	01.36	E/L	Insulator failed	-
6		Anajipur	Podichedu	11KV	Bhongir	10.36	11.40	01.04	EL/OL	11kv Line Snapped near Podichedu Village	-
7		Arror	Appareddyally	11KV	Choutuppal	11.00	15.30	04.30	EL/OL	11kv Insulator Failed near Appreddy pally Village	-
1	MDK	Sangareddy Town-I	Friday Market	11KV	Sangareddy	17.05	18.00	00.55		B/D due to Jumper cut	-
2		Sangareddy Town-II	Kosla	11KV	Sangareddy	18.55	19.40	00.45		B/D due to Tree branches fallen on the line	-
3		Sadasivapet Town	Town-II	11KV	Sangareddy	17.08	21.00	03.52		B/D due to Tree branches fallen on the line	-
4		Bollaram-I	Aurobindo	11KV	Patancheru	04.00	08.20	04.20		B/D due to Jumper cut	-
5		Bollaram-I	NCL	11KV	Patancheru	18.05	20.30	02.25		B/D due to Tree branches fallen on the line	-
6		Gaddapotharam-II	Apex	11KV	Patancheru	17.00	18.10	01.10		B/D due to Insulator failed	-
1	SDPT	DR PALLY	DR PALLY	11KV	Gajwel	16.30	18.30	02.00		INSULATOR FAIL	-
2		THIMMAPUR	CHINNA KISTAPUR	11KV	Gajwel	18.57	20.35	01.45		INSULATOR FAIL	-
3		Gandipally	Ramavaram Express	11KV	Husnabad	18.30	00.00	05.30		Heavy gale and wind(Still)	-
4		Ramchandrapur	Vinjapally	11KV	Husnabad	14.30	17.45	03.15		Insulator fail	-
5		Komuravelli	Kadaverugu	11KV	Husnabad	14.45	16.00	01.15		Heavy gale and wind	-
6		Nagapuri	Pothireddyally	11KV	Husnabad	17.10	18.25	01.15		Heavy gale and wind	-
7		Chityala	Chityala	11KV	Husnabad	16.05	00.00	07.55		Heavy gale and wind(Still)	-
8		Chityala	Dhommata	11KV	Husnabad	16.45	00.00	07.15		Heavy gale and wind(Still)	-
9		Chityala	Thadoor	11KV	Husnabad	17.20	00.00	06.40		Heavy gale and wind(Still)	-
10		Bekkal	Kutigal	11KV	Husnabad	16.00	18.00	02.00		Heavy gale and wind	-
1	RR N	Dulapally	KK Society	11KV	Medchal	17.32	20.01	02.29	BD	11KV Pin Insulator failed at Glass Company	-
2		Dulapally	IDA-II	11KV	Medchal	17.33	19.58	02.25	BD	11KV Pin Insulator failed at Steelcity	-
3		Subhash Nagar	Meenakshi	11KV	Medchal	18.52	20.51	01.59	BD	11KV Pin Insulator failed at Metro Back side	-
4		HMT	Qutubullapur	11KV	Medchal	20.10	21.25	01.15	BD	1KV Pininsulator failed at Royal Wines	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Mallapur-2	Surya Nagar	11KV	Habsiguda	05.51	07.38	01.47		11KV Disc failed at Surya Nagar T/F	-
2		Mallapur	Noma	11KV	Habsiguda	18.32	20.15	01.43		11KV Pin Insulator failed at Baba Nagar Ayyappa Temple	-
3		IDA Uppal	Devender Nagar	11KV	Habsiguda	18.01	20.12	02.11		11KV Post Of Insulator failed at Noble Hotel	-
4		IICT	Nacharam	11KV	Habsiguda	18.19	19.52	01.33		Tree branches fallen on 11KV Line AB Switch Insulator & Insulator broken at Karthikeya Nagar Bondal Gadda	-
5		Vinayak Nagar	RK Nagar	11KV	Sainikpuri	07.48	08.51	01.03		CTPT fail at Cini Police Anandbagh Chaurastha (AE)	-
6		Anandbagh	PB Colony	11KV	Sainikpuri	17.45	19.15	01.30		11Kv Pin Insuletor fail at PB Colony Mercy Model School (AE)	-
7		Vasanthapuri	Old Mirzalaguda	11KV	Sainikpuri	18.22	20.20	01.58		11Kv Pin Insuletor fail at Old Mirzalaguda Main Road (AE)	-
1	HYD N	I.I.C.T	Deccan	11KV	V	18.18	19.30	01.12	EL	Tree branches fallen on lines at Kumba Karna Restaurent	
2		Osm. University	Osm. University	11KV	V	18.45	19.55	01.10	EL	No Visible Fault	
3		H.M.T	Chinthal	11KV	VI	18.50	20.00	01.10	EL	Sparkings on AB Cable at Chinthal	
4		Hakeempet	Allenby Lines	11KV	C-VI	18.50	20.40	01.50	EL	Tree branches fallen on lines near SS	
5		I.D.P.L	Shivalayam	11KV	VI	19.10	21.00	01.50	EL,OL-Rph	Pin Insulator flash over at 2nd Line AB Switch	
6		Gymkhana	Tadbun Temple	11KV	C-VI	19.30	22.00	02.30	EL,OL-Y&Bph	Tree branches fallen on lines at Tadbun Temple	
7		Gunrock	Lal Bazar	11KV	C-VI	19.34	21.58	02.24	EL	---	
8		Gunrock	Vaishnavi Matha	11KV	C-VI	21.00	22.56	01.56	EL	Disc Insulator flash over at Satya Petrol Pump	
9		Macha Bollaram	Ayyappa Nagar	11KV	C-VI	17.32	22.40	05.08	A/R tripped	3Nos. Disc Insulators flash over at Pancha Sheela Colony	
1	HYD C	A.C Guards	Shanthi Nagar	11KV	VII	13.30	14.36	01.06	EL,OL-Rph	AB Cable fault at Shanthi Nagar	
2		A.C Guards	N.M.D.C	11KV	VII	18.35	20.07	01.32	EL	R.M.U Insulator flash over near N.M.D.C	
3		Mothi Mahal	Company Bagh	11KV	VII	23.15	00.42	01.27	EL,OL-R&Yph	Jumper cut at Gym Garden & Stick fallen on lines at Qayum PT	
4		Bathkammakunta	Ahobilmutt	11KV	II	23.43	01.02	01.19	EL	Pin Insulator flash over at Golden Towers	
5		Vittalwadi	Basanth Colony	11KV	II	23.56	01.06	01.10	EL	Tree branches fallen on lines at Venkateshwara Theater	