

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		4		4		4			
6	RR(N)	54	550	2	23	2	23	2	23			
7	RR(E)	168	403		14		14		14			
8	Hyd	194	1044		31		31		31			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>72</b>	<b>2</b>	<b>72</b>	<b>2</b>	<b>72</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	10	4	10	4	10	4			
2	NLG	144	988	1	24	1	24	1	24			
3	MDK	107	933	3	18	3	18	3	18			
4	SDPT			0	35	0	35	0	35			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>14</b>	<b>81</b>	<b>14</b>	<b>81</b>	<b>14</b>	<b>81</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>16</b>	<b>153</b>	<b>16</b>	<b>153</b>	<b>16</b>	<b>153</b>	<b>0</b>	<b>0</b>	

## Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	11.18	14.35	03.17	EL	Y Phase Disc insulator failed at Palamoor univarsity and Y Phase LA failed at Bandamidipally		Alternate Supply Taken From 33KV Kodur feeder
2		Makthal	Jaklair	33KV	Narayanapet	07.05	13.55	06.50	EL	Tree Removing on Line Near Pole No 44 Near Makthal Chervu Back Side.		Alternate Supply Taken From Bijwar
3		Marikal	Eklaspur	33KV	Narayanapet	02.50	06.10	03.20	EL	No Visible fault		AB Switch Opened towards Waddeman SS
4		Maddur	Vepoor	33KV	Narayanapet	18.25	21.05	02.40	EL	Due to 33KV Line Fault & Back Feeding Supply Taken to 132 KV SS Mahabubnagar		Back Feeding Supply Taken to 132 KV SS Mahabubnagar
5		Wanaparthy	Buddaram	33KV	Wanaparthy	01.27	12.30	11.03	EL	Flash Over Disc Replacement		
6		Ghanapur	Solipur	33KV	Wanaparthy	13.14	14.46	01.32	EL	Pole Damage		Loads Diversion Purpose From 132KV SS Wanaparthy
7		Chinnamaroor	Velgonda	33KV	Wanaparthy	05.30	08.00	02.30	EL	Insulator failed and replacement		Alternate Supply Arranged From 33KV Ayyawaripally SS at 8:00Hrs.
8		Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	15.15	15.52	00.37	OL	Tree branch follen on the line		Peddakarpamula AB Switch open at PeddaKothapally SS
9		Achampet	Amrabad	33KV	Nagarkurnool	02.20	09.30	07.10	OL	Tree branch follen on the line		-
10		Kothur	Thimmapur	33KV	Shadnagar	03.15	16.30	13.15	E/L&O/L	3No Disc Insulator Failed and Replacemet and Jumper reconection		-
1	NLG	Narkatpally	Nakkalapally	33KV	Nalgonda	08.24	10.52	02.28	E/L	Y-Ph Insulator failed		-
1	MDK	Pashamailaram	SOL	33KV	Sangareddy	11.30	13.55	02.25		B/D due to Jumpet cut		-
2		Sadasivapet	Koheer	33KV	Sangareddy	05.30	08.15	02.45		B/D due to Tree branches fallen on the line		-
3		Borapatla	Covalent	33KV	Jogipet	07.34	12.42	05.08		B/D due to Tree branches fallen on the line & Jumper cut		-
1	RR N	132KV Medchal	33KV Steel Mills	33KV	Medchal	04.47	17.10	12.23		Tree fallen on the 33KV Line and 33KV Line cut and replaced at Kandlakoya Main Road		-
2		132KV Medchal	33KV Keshavaram	33KV	Medchal	04.40	05.50	01.10		Tree fallen on the 33KV Line at Green Villa, Munirabad		-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 26.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Mothiganpur	Madigadda thanda	11KV	Jadcherla	09.30	14.30	05.00		11KV Disc Fail near Cheruvu back side.	-
2		Kavarmapet	Bandamidipally	11KV	Jadcherla	07.10	09.45	02.35		11KV Wire Cut near Bandamidipally	-
3		Pollepally	Udandapur	11KV	Jadcherla	03.44	10.37	06.53		11KV Wire Cut near Udandapur.	-
4		Pollepally	Pollepally	11KV	Jadcherla	04.04	12.37	08.33		11KV Insulater Fail near Pollepally.	-
1	NLG	Pamanagundla	Yerasanigudem	11KV	Nalgonda	03.00	12.55	09.55	E/L	11KV line cut	-
2		Pamanagundla	Pittampally	11KV	Nalgonda	06.00	07.50	01.50	E/L	11 KV Jumper cut	
3		Ch.Annaram	Garlabaigudem	11KV	Nalgonda	04.00	13.43	09.43	E/L	11 KV Jumper cut	
4		Naratpally	Mandra	11KV	Nalgonda	07.40	09.00	01.20	E/L	11 KV Jumper cut	
5		Akaram	Shanthinagar	11KV	Nalgonda	06.00	14.00	08.00	E/L	11KV line cut	
6		Kethepally	Gudiwada	11KV	Nalgonda	08.00	10.30	02.30	E/L	11 KV Jumper cut	
7		Indugula	Kothagudem	11KV	Nalgonda	08.00	14.50	06.50	E/L	11KV Disc failed	
8		Koppole	Turkapally	11KV	Nalgonda	07.30	16.30	09.00	E/L	11KV Disc failed	
9		Aitipamula	Rasoolgudem	11KV	Nalgonda	12.30	15.30	03.00	E/L	HT/LT line melting	
10		Mudigonda	Gottimukala	11KV	Devarakonda	07.40	10.00	02.20	E/L	Movement Fault	
11		Padamatipally	Thurupupally	11KV	Devarakonda	07.30	09.45	02.15	E/L	11 KV Insulator failed	
12		Chitriyala	Chitriyala	11KV	Devarakonda	08.00	14.00	06.00	E/L	11 KV Line Cutt	
13		Chinthapally	H.M.pally	11KV	Devarakonda	15.30	16.05	00.35	E/L	1-ph DTR Failed in H.M.Pally Village	
14		Nampally	Vadepally	11KV	Devarakonda	06.40	09.30	02.50	E/L	11 KV Insulator failed	
15		Chepuru	Theratigudem	11KV	Devarakonda	06.30	08.55	02.25	E/L	Movement Fault	
16		Nuthankal	Polumalla	11KV	Suryapet	03.40	09.45	06.05	E/L	Jumper cut	
17		T Giri	Thonda	11KV	Suryapet	06.25	13.00	06.35	E/L	Tree branch fallen on the line	
18		B Chandupatla	Vk Pahad	11KV	Suryapet	00.00	12.50	12.50	E/L	Insulator failed	-
19		Mukundapuram	Somaram	11KV	Huzurnagar	06.00	08.45	02.45	EL	11 KV LINE SNAPPED	-
20		Palakeedu	Nagireedygudem	11KV	Huzurnagar	05.00	07.35	02.35	EL	11 KV LINE SNAPPED	-
21		Munagala	Bharakathgudem	11KV	Huzurnagar	08.55	11.05	02.10	EL	11 KV JUMPER CUT	-
22		Rajapeta	Renikunta Agl	11KV	Bhongir	10.30	11.50	01.20	EL/OL	11 kv Insulator failed near Begumpet village	-
23		Addagudur	Kotamarthy	11KV	Bhongir	08.20	11.30	03.10	EL/OL	11 kv Disc failed at Cotton mill near kotamarthy village	-
24		Redlarepaka	Dasireddygudem	11KV	Choutuppal	06.40	07.20	00.40	EL/OL	11 kv Disc failed at Neelareddy well near Dasireddygudem village	-
1	MDK	Sangareddy Town-II	No.-III	11KV	Sangareddy	08.25	09.45	01.20		B/D due to Tree branches fallen on the line	-
2		Sangareddy Rural	Balaji	11KV	Sangareddy	16.20	18.43	02.23		B/D due to Insulator failed	
3		Cheryal	Dulichand	11KV	Sangareddy	04.40	09.30	04.50		B/D due to Tree branches fallen on the line	
4		Cheryal	Cheryal	11KV	Sangareddy	11.00	14.00	03.00		B/D due to Conductor snapped	
5		Fasalwadi	Rythunagar	11KV	Sangareddy	12.45	14.25	01.40		B/D due to Conductor snapped	
6		Isnapur	Widia	11KV	Sangareddy	06.15	12.15	06.00		B/D due to Insulator failed	
7		Munipally	kammampally	11KV	Sangareddy	07.20	11.01	03.41		B/D due to Tree branches fallen on the line	
8		EPIP-I	Chitrakoot	11KV	Sangareddy	12.50	13.45	00.55		B/D due to Conductor snapped	
9		EPIP-III	Tychy Diecast	11KV	Sangareddy	01.15	06.15	05.00		B/D due to Insulator failed	
10		Bollaram-I	Soubhagya	11KV	Patancheru	11.05	14.15	03.10		B/D due to Jumper cut	
11		Bollaram-I	Kythan	11KV	Patancheru	08.45	14.25	05.40		B/D due to Jumper cut	-
12		Dundigal	Annaram	11KV	Patancheru	13.03	18.00	04.57		B/D due to Insulator failed	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
13		Inole	Bayers Corp	11KV	Patancheru	07.42	15.00	07.18		B/D due to Insulator failed & Tree branches fallen on the line	-	
14		Pati	Shalimar	11KV	Patancheru	06.15	09.55	03.40		B/D due to Tree branches fallen on the line	-	
15		Patancheru Town	MIA-II	11KV	Patancheru	03.10	08.30	05.20		B/D due to Conductor snapped	-	
16		Patancheru Town	Town Indl.	11KV	Patancheru	14.15	15.15	01.00		B/D due to Tree branches fallen on the line	-	
17		Patancheru Town	Santhi Nagar	11KV	Patancheru	09.50	11.20	01.30		B/D due to Tree branches fallen on the line	-	
18		Gummadidala	Bell Remedies	11KV	Patancheru	08.35	13.15	04.40		B/D due to Tree branches fallen on the line & Jumper cut	-	
1	SDPT	Guruvannapet	Thapasally	11KV	Husnabad	00.10	05.20	05.20		3-Ph Break Down		
2		Bekkal	Thornala	11KV	Husnabad	01.00	11.50	10.50		Tree branch fell on line		
3		Chityala	Dommata	11KV	Husnabad	00.00	13.20	13.20		No problem		
4				Chityala	11KV	Husnabad	00.00	12.15	12.15		Jumper open	
5		Potharam	Nagaram	11KV	Husnabad	00.00	06.35	06.35		11 kv pole damage		
6		Akkanapet	Fakeernayakthanda	11KV	Husnabad	07.30	10.10	02.40		Line Cut		
7		Gandipally	Ramavaram Xpress	11KV	Husnabad	00.00	09.35	09.35		Tree fell on line		
8		Thotapally	Devakkapally	11KV	Husnabad	08.30	12.30	04.00		Jumper Cut		
9		Raghavapur	Ravurukula	11KV	Siddipet	06.20	13.30	07.10		B/D 11kv Disk Fail lc no. 11898		
10		Pulluru	Pulluru	11KV	Siddipet	06.10	13.10	07.00		B/D 11kv Disk Fail		
11		Thornala	Appanapally	11KV	Siddipet	10.45	12.20	01.35		B/D		
12		Thornala	Thornala	11KV	Siddipet	10.50	13.45	02.55		B/D		
13		Vittapur	Vittapur	11KV	Siddipet	06.00	11.00	05.00		B/D 11kv insulator fail		
14		Dubbak IPDS	Chervapur	11KV	Siddipet	09.45	11.02	01.17		B/D		
15		Gambeerpur	Shilajinagar	11KV	Siddipet	10.20	15.30	05.10		B/D 11kv disk fail lc no. 28770		
16		Indoor	Old Bustand	11KV	Siddipet	14.50	15.25	00.35		B/D		
17		Mustabad X Road	Raghavendranagar	11KV	Siddipet	12.25	12.40	00.15		B/D 11kv disk Fail lc no. 2191		
18		Mustabad X Road	Raghavendranagar	11KV	Siddipet	14.15	14.35	00.20		B/D		
19		Mirdoddy	Mirdoddy Town	11KV	Siddipet	11.15	13.35	02.20		B/D Tree Fall lcno. 24170		
20		GAJWEL	GAJWEL	11KV	Gajwel	7:00	11:30	04.30		11KV DISC FAILED		
21		PREGNAPUR	KODAKANDLA	11KV	Gajwel	4:32	8:50	04.18		11KV DISC FAILED		
22		MARKOOK	ERRAVALLY	11KV	Gajwel	22:27	23:59	01.32		11KV DISC FAILED		
23		MARKOOK	GANESHPALLY	11KV	Gajwel	10.00	11.50	01.50		11KV DISC FAIALED		
24		GOWRARAM	NIMTOOR	11KV	Gajwel	11.50	13.10	01.20		11KV DISC FAILED		
25		GOWRARAM	GOWRARAM	11KV	Gajwel	00.30	12.00	11.30		11KV DISC FAILED		
26		MULUGU	TUNKI BOLLARAM	11KV	Gajwel	00.00	11.20	11.20		11DISC FIALED		
27		MULUGU	KOKKONDA	11KV	Gajwel	00.00	09.15	09.15		11DISC FIALED		
28		MULUGU	ADIVIMAJEEDPALLY	11KV	Gajwel	13.45	15.35	01.50		11DISC FIALED		
29		MULUGU	MULUGU	11KV	Gajwel	15.45	16.30	00.45		11KV JUMPER CUT		
30		RAIPOLE	BEGAMAPET	11KV	Gajwel	14.45	17.45	03.00		INSULATER FAILED		
31		DOULTHABAD	DOWLTHABAD	11KV	Gajwel	06.33	11.49	05.16		INSULATER FAILED		
32		DOULTHABAD	DOWLTHABAD	11KV	Gajwel	15.12	15.44	00.32		CORE INSULATER FAILED		

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
33		DUDEEDA	KONDAPAKA	11KV	Gajwel	05.00	12.00	07.00		11KV INSULATER FAILED AND JUMPER CUT	
34		DUDEEDA	KONDAPAKA	11KV	Gajwel	05.00	11.10	06.10		11KV INSULATER AND DISC FAILED	
35		DUDEEDA	MARPADAGA	11KV	Gajwel	11.35	12.45	01.10		11KV DISC FAILED	
1	RR S	Manikonda	Laxminagar	11KV	Ibrahimbagh	16.20	17.50	01.30		11 KV Isulator fail at Opp Sub Station	-
2		IIIT	IVRCL	11KV	Gachibowli	10.24	11.26	01.02		11kv Jumper Replacement in Sub-station (EPTRI CT/PT Moisture)	-
3		JNTU	BS Nagar	11KV	Gachibowli	10.35	12.35	02.00		11kv Line Melted near plot no 516 at BS nagar.	-
4		Kothaguda	Izzath Nagar	11KV	Kondapur	03.10	04.40	01.30		11kv Polymer Disc failed Opposite Adithya Apartment.	-
1	RR N	vijaya nagar	Jayanagar	11KV	Kukatpally	05.10	07.10	02.00		Tree branches fall on the 11kv line at Road:6, Vijaya nagar	-
2		Prashanth Hills	Lake View colony	11KV	Jeedimetla	06.50	08.50	02.00		11kv line Cut at Plot:1458, Pragathinagar	
3		Jeedimetla-IV	Axiess	11KV	Jeedimetla	12.00	14.00	02.00		11kv Jumper Cut, AB Cable Endkit failed at Opp:SS	
4		Dppally	IDA-II	11KV	Jeedimetla	16.40	19.34	02.54		11kv line AB Cable Failed at ORR Ring Road	
5		Dppally-II	Tech Mahendra	11KV	Jeedimetla	11.59	14.19	02.20		11kv line PinInsulater failed at Ahalada Company tech mahendra Raod	
6		Petbasheerabad	Vaishnavi Enclave	11KV	Medchal	05.54	08.04	02.10		100KVA DTR Pin Insulator Cut at SMR Developers	
7		HMT	Qutubullapur	11KV	Medchal	07.40	09.15	01.35		Tree fallen on the 11KV Line at HMT Main Road	
8		HMT	Gandhi Nagar	11KV	Medchal	08.18	09.23	01.05		Tree Fallen on the 11KV Line at HMT Wall	
9		UMCC	Crusher	11KV	Medchal	05.00	05.55	00.55		11KV Pin Insulator failed at Kaisar Nagar	
10		Subhash Nagar	Ramraj Nagar	11KV	Medchal	09.14	10.07	00.53		11KV Pin Insulator failed at Alwal Road, Sundaram Block	
11		Gowdavelly	Basaragadi	11KV	Medchal	06.30	10.30	04.00		25KVA T/F Pin Insulator failed at near SS Backside	
12		Medicity	Pudur	11KV	Medchal	06.25	10.19	03.54		11KV Line Cut and replaced at Yellamma Temple, Ganapur Village	
13		Athiwelly	IDA Athiwelly	11KV	Medchal	12.50	15.50	03.00		Tree fallen on the 11KV Line at Dabeerpur Chowrasta	
14		Kandlakoya	KV Reddy Nagar	11KV	Medchal	02.30	05.25	02.55		Tree fallen on the 11KV Line at Kaveri Seeds	
15		Kandlakoya	Saigeetha Asramam	11KV	Medchal	05.30	08.00	02.30		No Fault	
16		Rajabollaram	Rajabollaram Thanda	11KV	Medchal	13.10	15.37	02.27		Tree fallen on the 11KV line at Rajabollaram Thanda	
17		Thumkunta	Thumkunta	11KV	Medchal	07.40	09.42	02.02		11KV Disc failed at Mandaipally Road	
18		Athiwelly	SPIC	11KV	Medchal	02.00	04.00	02.00		Tree fallen on the 11KV Line at Near Rekula Bhavi	-
19		Gowdavelly	IDA	11KV	Medchal	00.00	01.45	01.45		Tree Branches fallen on the at Basaragadi Village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
20		Kandlakoya	Kandlakoya	11KV	Medchal	07.20	09.00	01.40		11KV Line AB Switch sparked at Gubba Cold Storage	-
21		Shameerpet	Anthaipally	11KV	Medchal	08.45	10.25	01.40		11KV Jumper Opened at Prajay Homes(1 T/F Off)	-
22		Kistapur	Kistapur	11KV	Medchal	08.30	09.50	01.20		11KV Pole Bend & Rectified at near SS	-
23		Aliabad	HBL	11KV	Medchal	06.30	07.30	01.00		Tree fallen the 11KV Line at HBL Company )	-
1	RR E	Uppal Bhagath	Sathya Nagar	11KV	Habsiguda	02.03	03.30	01.27		Line Patrolling but no visible Fault & 11KV line AB Switch opened at L&T Pillar Manufacturing Unit & Back feeding supply taken from 11KV Asian Theatre feeder	-
2		Uppal	RTA	11KV	Habsiguda	02.30	03.30	01.00		Tree branches fallen on 11KV line at Survey Colony	-
3		IDA Uppal	Ram Reddy Nagar	11KV	Habsiguda	23.57	00.47	00.50		11KV Disc failed at Vasavi Nagar St.No.02	-
4		Polytechnic	Srinivasapuram	11KV	Habsiguda	01.47	04.37	02.50		11KV Disc failed at Babu Rao Hotel	-
5		Techpark	GVK	11KV	Habsiguda	01.09	02.15	01.06		CTPT Failed at Classic Tiles Company	
6		Techpark	Srikrishna	11KV	Habsiguda	08.39	09.45	01.06		CTPT Fault & Jumper cut at dual Rings Company	
7		Street no 8	Laxmi nagar	11KV	Habsiguda	09.10	10.22	01.12		100KVA DTR fail at Old shivalayam temple	
8		Anandbagh	Krupanand	11KV	Sainikpuri	22.55	02.15	03.20		Breaker Problem due to Krupanand Load Add on Tankbund Feeder	
9		Vasanhapuri	Sai Ram	11KV	Sainikpuri	03.24	04.56	01.32		11Kv Pin Insulator fail at Geetha Nagar Gouthami School (AE)	
10		Kushaiguda	Mahesh Nagar	11KV	Sainikpuri	06.05	08.20	02.15		Tree branches fallen on 11KV line at Mashesh Nagar (LM Srinivas)	-
11		Sainikpuri	Eshwarpuri	11KV	Sainikpuri	08.45	09.55	01.10		Tree branches fallen on 11KV line at Out colony (LM Anil)	-
12		Narapally	Industrie	11KV	Keesara	02.30	05.30	03.00		11KV Line cut & tree fallen on 11kv line at Agarvamshi	-
13		peerzathigda	RTC	11KV	Keesara	10.00	10.44	00.44		Jumper cut at Balaji Function hall	-
14		Balaji nagar	Santosh nagar	11KV	Keesara	01.00	02.45	01.45		Tree fallen on 11kv line at BJR nagar	-
1	HYD N	Gunrock	Surya Enclave	11KV	C-VI	01.22	02.40	01.18	EL,OL	Tree branches fallen on lines at backside SS	-
2		Madhapur	Vedam	11KV	X	02.15	04.20	02.05	EL,OL-Rph	under Breakdown	Arranged B/F on 11KV APIIC-II fdr
3		Zamistanpur	S.P College	11KV	V	04.50	07.53	03.03	EL	Disc Insulator flash over at Pulse Hospital	-
4		Gymkhana	Pared Ground	11KV	C-VI	05.20	06.50	01.30	All Indication	Tree branches fallen on lines at Pared Grounds	-
5		Bansilalpet	Viceroy	11KV	V	05.50	07.15	01.25	All Indication	R.M.U fault at Opp:Viceroy	-
6		Yellareddyguda	Maruthi Nagar	11KV	X	05.54	09.00	03.06	EL	HT Line snapped at Vishal Tower & Tree branches fallen on lines at Ganapathi Complex	-
7		H.A.L	Sri Rama	11KV	VI	07.25	09.58	02.33	EL	Cable fault	Arranged B/F on 11KV India Rubber fdr
8		I.D.P.L	Vijaya Electrical	11KV	VI	08.25	09.50	01.25	EL	DTR fault at IDPL HT Service	
9		I.D.P.L	Wonder Plast	11KV	VI	08.30	11.15	02.45	EL	CT PT fault at Plot No.6 & 7	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
10		Hakeempet	Allenby Lines	11KV	C-VI	08.35	10.40	02.05	Tripped AR	Tree branches fallen on lines at Goals School	
11		Bowenpally	Plassy Line	11KV	VI	08.40	10.17	01.37	All Indication	O/G AB Switch Jumper cut at SS	
12		Prashanth Nagar	Andhra Jyothi	11KV	VI	08.40	10.26	01.46	EL	No Visible Fault	
13		Osm. University	Keshav Nagar	11KV	V	13.35	16.40	03.05	EL	Conductor snapped at School DTR	
14		Road No.22	M.C.R	11KV	X	17.18	18.36	01.18	EL,OL	Cable fault at Road No.36	
15		Macha Bollaram	Chinthal Bazar	11KV	C-VI	20.20	21.30	01.10	EL,OL-Bph	Kept off 4No DTR's due to 2No Poles damaged at Vivekananda Statue near Bhoo Laxmi Temple	-
1	HYD S	Kandikal Gate	Patel Nagar	11KV	III	05.40	06.58	01.18	EL,OL	Cable fault	Arranged B/F on 11KV Tanaji Nagar feeder
2		Asmangadh	Tirumala Hills	11KV	VIII	07.05	08.12	01.07	EL	DTR fault at Janda PT	-
1	HYD C	Fever Hospital	Sri Ram Nagar	11KV	II	00.00	07.45	07.45	EL	DTR fault at Nala	-
2		N.I.M.S	Naveen Nagar	11KV	I	02.10	03.20	01.10	EL	No Visible Fault	-
3		Hyderguda	Urdu Hall	11KV	I	02.20	03.50	01.30	EL,OL-Bph	HG fuse burntout at Panchayath Raj Office	-----
4		Langer House	Military Hospital	11KV	VII	02.25	04.00	01.35	EL,OL-Bph	Tree branches fallen on lines at Floor Mill	-----
5		Vittalwadi	Gandhi Kuteer	11KV	II	03.35	05.17	01.42	EL	Tree branches fallen on lines at Telugu Desam PT	-----
6		Golconda	Narayanamma College	11KV	VII	03.55	10.10	06.15	EL,OL-Yph	UG Cable End Kit failed at Sandhya Hotel	Arranged B/F on 11KV Brindavan Colony fdr
7		Nampally	V.N.C	11KV	VII	04.06	07.35	03.29	EL,OL-Rph	-----	Partial fdr charged at 05:33 Hrs, Remaining arranged B/F on 11KV Zaheera Masjid feeder
8		Indira Park	Talla Basti	11KV	I	04.35	13.50	09.15	EL	No Visible Fault	At 07:50 Hrs Partial feeder arranged B/F on 11KV Goshala feeder
9		I.T.I Mallepally	Afzal Sagar	11KV	VII	06.18	07.38	01.20	EL	No Visible Fault	
10		I.T.I Mallepally	Afzal Sagar	11KV	VII	08.05	10.31	02.26	EL	Pin Insulator flash over at Afzal Sagar Nala	
11		Golconda	Shaikpet Water Works	11KV	VII	08.10	09.20	01.10	EL,OL-Y&Bph	No Visible Fault	
12		Chilalguda	Parsigutta	11KV	II	09.12	10.45	01.33	EL,OL-Rph	Tree branches fallen on lines at Kaladhar Nagar	
13		Golconda	Shaikpet Water Works	11KV	VII	09.30	13.30	04.00	EL	Pin Insulator flash over at Shaikpet	
14		A.C Guards	Niloufer	11KV	VII	04.42	05.55	01.13	EL	Tree branches fallen on lines at Opp: PTI Building (CWC DTR Kept Off)	-----