

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		5		5		5			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		11		11		11			
	Total	606	3055	0	19	0	19	0	19	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		5		5		5			
3	MDK	107	933		3		3		3			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	11	0	11	0	11	0	0	
	Grand Total	1082	6468	0	30	0	30	0	30	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.09.2020

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RR S				NIL							-
5	RR N				NIL							-
6	RR E				NIL							-
7	HYD				NIL							-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 29.09.2020

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Rajupeta	Rajupeta	11kv	Nalgonda	07.10	09.10	02.00	E/L	11 KV Jumper Cut	-
2		Thummadam	Vallabapuram	11kv	Miryalaguda	10.50	13.30	02.40	E/L	11KV Jumper Cut at Kakkaigudem Agl DTR	-
3		Nuthankal	Errapahad	11kv	Suryapet	06.40	08.30	01.50	E/L	Tree branch fallen on the line	-
4		Repala	N.S.Gudem	11kv	Huzurnagar	08.25	10.25	02.00	EL	11 KV LINE SNAPPED	-
5		Peddakandukur	Peddakandukur	11kv	Bhongiri	15.01	15.42	00.41	EL	11 kv Insulator failed near Peddakandukur village	-
1	MDK	33/11 KV NARSAPUR SS	11 KV AVANCHA FEEDER	11kv	MEDAK	13.40	17.00	03.20		11KVA DISC FAIL	-
2		33/11 KV Lingapoor SS	11 KV LINGAPUR FEEDER	11kv	MEDAK	12.49	16.35	03.46		11KVA JUMPER FAIL	-
3		Gummadidala	Bell Remedies		Patancheru	17.00	18.15	01.15		B/D due to Jumper cut	
1	SDPT	Narmetta	Narmetta	11kv	SDPT	01.40	07.57	06.17		B/D (Tree branches falen on the 11 KV Line)	-
2		Raghavapur	Peddalingareddypally	11kv	SDPT	15.10	18.22	03.12		B/D (Jumper wire cutting, LCNO 11813)	-
3		Dubbak	Chellapur	11kv	SDPT	13.52	15.40	01.48		B/D (Heavy Rain)	-
1	RR N	Gagillapur	F-2	11kv	Jeedimetla	18.12	19.45	01.33		Tree fall on the 11kv linenear chruh at Gagillapur village	-
2		Kandlakoya	KV Reddy Nagar	11kv	Medchal	11.05	11.50	00.45		Tree fallen on the 11KV Line at GVK-108	-
3		Bandamadaram	Srirangavaram	11kv	Medchal	18.00	19.10	01.10		2Nos 11KV Poles Damaged at Pochamma Temple, Bandamadaram	-
4		Bandamadaram	Rocksand	11kv	Medchal	18.00	19.10	01.10		Tree fallen on the 11KV Line at Pochamma Temple	-
5		Vikas	Kendriya Vihar	11kv	Kukatpally	17.52	19.40	01.48		Tree branchesh Fallen the 11kv line at Mayurinagar,Pencial Park	-
1	RR E	Balaji Nagar	Santhosh Nagar		Keesara	16.34	17.50	01.16		11KV Line AB Switch & Jumper cut at Chennapuram Chourastha	-
2		Narapally	Narapally Indl		Keesara	15.30	16.20	00.50		11Kv Pin Insulator failed at Narapally Bawarchi Hotel	-
3		Nagaram	P S Rao Nagar		Keesara	15.28	16.14	00.46		11KV Male Insulator failed at LNR Colony	-
1	HYD N	Marredpally	R.K.Puram	11kv	C-VI	10.30	13.05	02.35	EL	Breaker problem at SS	Arranged B/F on 11KV A.O.C fdr
2		Osm. University	Keshava Nagar	11kv	V	10.35	12.20	01.45	EL,OL-R&Yph	W/C Rph Lug burntout at SS	----
3		Bhudevi Nagar	Ram Raj Nagar	11kv	VI	11.17	13.25	02.08	EL	No Visible Fault	Arranged B/F on 11KV Kalinga Enclave fdr
4		Tirumalagiri	Kiran Talkies	11kv	C-VI	15.06	16.24	01.18	EL	Brass Patti cut at Railway Gate	----
5		Chinna Thokatta	Park View Enclave	11kv	VI	17.10	18.12	01.02	EL,OL-R&Yph	Tree branches fallen on lines at Thirumala Apts	----
6		New Bowenpally	Raju Colony	11kv	VI	17.15	18.59	01.44	EL	Pin Insulator flash over at Gaddi Chenu	----
1	HYD C	S.D.Hospital	Khadi Bandar	11kv	VII	17.31	19.04	01.33	EL	HT Jumper cut at Moon Rock Atps	----
2		Golconda	Brindavan Colony	11kv	VII	17.35	19.20	01.45	EL,OL-Bph	Faulty loads of 11KV Narayanamma College feeder	----
3		Golconda	Narayanamma College	11kv	VII	17.36	21.50	04.14	EL,OL-Bph	Cable fault at Vaternary Colony	Arranged B/F on 11KV Brindavan Colony fdr
4		Langer House	Military Area	11kv	VII	17.45	19.24	01.39	All Indication	Tree branches fallen on lines at Military Area	----
5		Mothi Mahal	Company Bagh	11kv	VII	17.48	19.01	01.13	EL,OL	Tree branches fallen on lines at Company Bagh	----