

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	0	5	0	5	0	5	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Repala	N S Gudem	11KV	Huzurnagar	05.00	07.15	02.15	EL	11 KV LINE SNAPPED	-
2		Gudipally	S.L.B.C	11KV	Devarakonda	07.40	08.56	01.16	EL	Moment fault	-
3		B.Ramaram	Hajipur	11KV	Bhongir	08.05	10.00	01.55	EL	11 KV Pin Insulator failed near Darmareddy gudem village.	-
1	HYD C	Golconda	Shaikpet Water Works	11KV	VII	03.25	04.36	01.11	EL,OL-R&Yph	Poled felldown at Vinayak Nagar due to JCB hit	Partial fdr charged & Remaining fdr arranged B/F on 11KV O.U Colony fdr
2		Bathkammakunta	Saibaba Temple	11KV	II	04.00	05.33	01.33	OL-R&Bph	Breaker problem at SS	Arranged B/F on 11KV C.E Colony fdr