

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	2	1	2	1	2			
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>1</b>	<b>7</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 04.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Thirumalaipally	Veltoor	33KV	Wanaparthy	01.52	02.50	00.58		Due to Y Phase CT Stud Replacement towards line side	Veltoor	Alternate Supply Arranged from 33KV Janampet SS

## TSSPDCL - LMRC / Corporate office

Date: 04.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Sampally	11KV	Narayanapet	08.00	09.18	01.18		11KV Pin Insulator damaged Near Kosgi	No
2		Pedda Revally	Chinna Revally	11KV	Jadcherla	07.35	11.10	03.35		BD DTR Problem near Kondareddypally	No
1	NLG	Rajapet	Rajapet	11KV	Nalgonda	13:50	14:50	1:00	EL	Insulator failed	No
2		Chamapur	Indl	11KV	Bhongir	08.25	10.30	02.05	EL	11 KV Insulator failed at Poultry farm near Singaram village.	No
3		Malkapur	Malkapur Indl	11KV	Choutuppal	04.32	06.25	01.53	EL	11KV Line snapped near Malkapur village	No
1	RR N	Jeedimetla-IV	Tagoure	11KV	Jeedimetla	14:15	15:20	1:05	EL/OL	End kit failed at opp:Tagoure Company	No
1	HYD S	Falaknuma	Falaknuma OH	11KV	III	07.55	09.07	01.12	EL	Cable End Kit failed at Falaknuma Palace	No