

Status Report on Breakdowns (Urban / Rural)**Urban**

| S.No | Circle | No.of Feeders Existing Urban | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 18 | 107 | | | | | | | | | |
| 2 | NLG | 22 | 358 | | | | | | | | | |
| 3 | MDK | 97 | 359 | | | | | | | | | |
| 4 | SDPT | | | | | | | | | | | |
| 5 | RR(S) | 53 | 234 | | | | | | | | | |
| 6 | RR(N) | 54 | 550 | | 1 | | 1 | | 1 | | | |
| 7 | RR(E) | 168 | 403 | | | | | | | | | |
| 8 | Hyd | 194 | 1044 | | 1 | | 1 | | 1 | | | |
| | Total | 606 | 3055 | 0 | 2 | 0 | 2 | 0 | 2 | 0 | 0 | |

Rural

| S.No | Circle | No.of Feeders Existing Rurals | | Breakdowns occurred during the day | | Attended during the day | | Time taken for restoring the supply | | | | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|-----------|-------------------------|-----------|-------------------------------------|-----------|--------------------------------|----------|-------------------|
| | | 33KV | 11KV | 33KV | 11KV | 33KV | 11KV | Rectified (Within 24 Hours) | | Not Rectified (Above 24 Hours) | | |
| | | | | | | | | 33KV | 11KV | 33KV | 11KV | |
| 1 | MBN | 107 | 849 | | 3 | | 3 | | 3 | | | |
| 2 | NLG | 144 | 988 | | 3 | | 3 | | 3 | | | |
| 3 | MDK | 107 | 933 | | 1 | | 1 | | 1 | | | |
| 4 | SDPT | | | 1 | 5 | 1 | 5 | 1 | 5 | | | |
| 5 | RR(S) | 58 | 396 | | | | | | | | | |
| 6 | RR(N) | 38 | 114 | | | | | | | | | |
| 7 | RR(E) | 22 | 133 | | | | | | | | | |
| | Total | 476 | 3413 | 1 | 12 | 1 | 12 | 1 | 12 | 0 | 0 | |
| | Grand Total | 1082 | 6468 | 1 | 14 | 1 | 14 | 1 | 14 | 0 | 0 | |

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 05.04.2021

| S.No | Circle | Name of 132/33KV SS | Name of 33 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Sub Stations Effected | Alternate Supply Arranged |
|------|--------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|-----------------------------|-----------------------|---------------------------|
| 1 | SDPT | GAJWEL | KDA | 33Kv | Gajwel | 13.40 | 03.36 | 02.12 | | Due to pin insulator failed | KDA | - |

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 05.04.2021

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|---|---------------------------|
| 1 | MBNR | Makthal | Khanapur | 11KV | Narayanapet | 07.45 | 08.30 | 00.45 | | Due to 11KV Jumper cut at Karni Village | - |
| 2 | | Midjil | Munnanur | 11KV | Jadcherla | 06.30 | 12.00 | 05.30 | | 11KV Wire cut near Munnanur | - |
| 3 | | Karkonda | Rudraram | 11KV | Jadcherla | 08.20 | 08.55 | 00.35 | | 11KV Wire cut near Rudraram | - |
| 1 | NLG | Phanigir | Etoor | 11KV | Suryapet | 09.35 | 10.45 | 01.10 | E/L | 11Kv Insulator failed | - |
| 2 | | Alair | Ikkurthy | 11KV | Bhongir | 03.15 | 05.45 | 02.30 | EL/OL | 11kv Insulator failed at Mamidi thota near Bahadurpeta (V) | - |
| 3 | | Paladugu | Duppelly | 11KV | Bhongir | 10.35 | 14.30 | 03.55 | EL/OL | 11kv Insulator failed at Chinthala cherla near Duppelly (V) | - |
| 1 | MDK | Patancheru Town | Santhi Nagar | 11KV | Patancheru | 14.30 | 16.25 | 01.55 | | B/D due to Conductor snapped | - |
| 1 | SDPT | Ensanpally | Ensanpally | 11KV | SDPT | 11.30 | 11.54 | 00.24 | | B/D for AB Switch spark | - |
| 2 | | Chellapur | Chellapur | 11KV | SDPT | 06.58 | 10.03 | 03.05 | | B/D for 11KV Conductor cut LC No.16388 | - |
| 3 | | Chellapur | Chellapur | 11KV | SDPT | 15.03 | 16.35 | 01.32 | | B/D for Middle pole damage LC No.16389 | - |
| 4 | | Cherial Town | Cherial-Town | 11KV | Husnabad | 19.50 | 21.30 | 01.40 | | Insulator failure same rectified | - |
| 5 | | Gagillapur | Vallampatla | 11KV | Husnabad | 13.44 | 15.52 | 02.08 | | Bird fall on line, same rectified | - |
| 1 | RR N | Shameerpet | Anthaipally | 11KV | Medchal | 14.20 | 16.20 | 02.00 | BD | 11KV Pole damaged by Vehicle(11KV Jumper Opened near Usharpally 25KVA 3Nos DTR No Supply) | - |

| S.No | Circle | Name of 33/11KV SS | Name of 11 KV Feeder | Vol | Name of the Division | From | To | Duration | Relay Indication | Cause of Breakdown | Alternate Supply Arranged |
|------|--------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--------------------|--|
| 1 | HYD C | Langer House | Prashanth Nagar | 11KV | VII | 02.36 | 04.04 | 01.28 | EL,OL-Bph | Cable fault | 02:36 Hrs Partial feeder Charged & Remaining loads added on 11KV Langer House Cable feeder |