

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>4</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	14	1	14	1	14			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>1</b>	<b>16</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>1</b>	<b>20</b>	<b>1</b>	<b>20</b>	<b>1</b>	<b>20</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 06.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Madugulapally	Vishaka ( Indust)	11KV	Miryalaguda	11.45	17.55	06.10	EL	33KV Insulator failure		-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 06.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Damarcherla	Bothalapalem	11KV	Miryalaguda	10.07	11.35	01.28	EL	DTR failure	-
2		Kasarabadha	Express feeder	11KV	Suryapet	06.30	09.05	02.35	EL	Insulator failed	-
3		Dirsincherla	Yallapuram	11KV	Huzurnagar	00.00	06.00	06.00	EL	Automatic stand.Rectified Supply Restored	-
4		Gaddipally	Kuthubshapuram	11KV	Huzurnagar	21.00	08.45	11.45	EL	Insulator failed	-
5		Munagala	Town	11KV	Huzurnagar	23.55	01.00	01.05	EL	11 kv jumper cut	-
6		Munagala	Indl	11KV	Huzurnagar	01.15	09.30	09.15	EL	11 KV LINE SNAPPED	-
7		Nadigudem	B V Puram	11KV	Huzurnagar	01.20	14.40	14.20	EL	HT\LT work	-
8		Akupamula	K R Puram	11KV	Huzurnagar	04.00	06.50	02.50	EL	AB Switch fault.Rectified Supply Restored	-
9		Repala	Kalakova	11KV	Huzurnagar	06.00	10.00	04.00	EL	HT\LT work	-
10		Munagala	Barakathgudem	11KV	Huzurnagar	23.20	09.30	10.10	EL	11 KV LINE SNAPPED	-
11		Akupamula	Indl	11KV	Huzurnagar	21.50	08.10	10.20	EL	11 KV LINE SNAPPED Rectified Supply	-
12		Kodad town	HNR X ROAD	11KV	Huzurnagar	22.06	23.15	01.21	EL	11 KV LINE SNAPPED	-
13		Ananthagiri	V R puram	11KV	Huzurnagar	21.30	15.00	18.30	EL	11 kv jumper cut	-
14		Maryala	Chowderpally	11KV	Bhongiri	00.20	07.00	06.40	EL/OL	11 kv line snapped near Chowderpally village	-
1	SDPT	Wargal	Chawderpally	11KV	Gajwel	10.40	13.20	02.40		11KV Jumper cut	-
2		Akkannapet	PNK Thanda	11KV	Husnabad	10.40	11.35	00.55		Brass Patti cut	-
1	RR N	HMT	Venkanna Hills	11KV	Medchal	11.04	11.30	00.26		11KV Line AB Switch Opened at Bhoomi Reddy Colony(No Fault)	-
2		Aliabad	Majeedpur	11KV	Medchal	10.40	11.35	00.55		No Fault	-
3		Devarayamjal	Pothaipally	11KV	Medchal	11.35	13.05	01.30		11KV Conductor Snapped and replaced at NTR Statue, Devarayamjal	-
1	RR E	Uppal	Chilaka Nagar	11KV	Habsiguda	15.00	16.10	01.10		11KV UG Cable failed at SBI ATM Beerappagadda due to JCB Water works	-