

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		7		7		7			
8	Hyd	194	1044	1	21	1	21	1	21			
	Total	606	3055	1	28	1	28	1	28	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988									
3	MDK	107	933	3		3		3				
4	SDPT			1	7	1	7	1	7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	4	7	4	7	4	7	0	0	
	Grand Total	1082	6468	5	35	5	35	5	35	0	0	

TSSPDCL - LMRC / Corporate office

Date: 12.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	RC Puram	Girdhar Ispat	33KV	Patancheru	14:00	16:00	2:00		Conductor Snapped	Girdhar Ispat	No
2		Gummadidala	Gummadidala	33KV	Patancheru	14.00	16.50	02.50		Insulator Falure	Gummadidala	No
3		Borpatla	Covalent	33KV	Jogipet	14.00	17.00	03.00		Insulator Falure	Covalent	No
1	SDPT	Thukkapur	Dommata	33KV	Gajwel	15:30	17:45	2:15		Insulator Falure	Dommata	No
1	HYD N	Gunrock	Alwal	33KV	Nehrunagar	15.10	15.18	00.08		Pin insulator faied	Alwal	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDPT	Bejgama SS	Bejgama	11KV	Gajwel	16:34	19:02	3:28		Tree branch fallen on the line	No
2		Pregnapur SS	Akkaram	11KV	Gajwel	18.58	19.25	00.27		Tree branch fallen on the line	No
3		Koadakandla SS	Rayavaram	11KV	Gajwel	12.35	14.33	01.58		11 KV Insulator failed	No
4		Medinipur SS	Mangol	11KV	Gajwel	15.00	18.00	03.00		Tree branch fallen on the line	No
5		MD shapur SS	MD shapur	11KV	Gajwel	17.15	18.53	01.38		11 KV Line Face to Face	No
6		Doulthabad SS	Lingarajaply	11KV	Gajwel	17.57	18.50	00.53		11 KV Insulator failed	No
7		Mettu SS	Masanaply	11KV	Gajwel	16:50	19:40	2:50		No visible fault	No
1	RR E	Moula-Ali	Jawahar Nagar	11KV	Sainikpuri	14:45	16:35	1:50		Tree branches fall on 11Kv line at Vibhav Apt Jawahar Nagar	No
2		AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	14.48	15.48	01.00		Ganni Bag fall on 11Kv line at MJ Colony Street No 4	No
3		AS Rao Nagar	Gokul Nagar	11KV	Sainikpuri	15.25	16.20	00.55		End Kit fail on Burnt at Goodluck Hotel	No
4		VP Nagar	Officers Colony	11KV	Sainikpuri	14.45	16.30	01.45		Tree branches fall on LT Pole Dammage at Geetha Nagar	No
5		Vayupuri	JK Colony	11KV	Sainikpuri	14.48	15.51	01.03		No visible fault	No
6		Ghatkesar	HPCL	11KV	Keesara	15.30	16.30	01.00		Tree branches fallen on 11KV line at Warangal Highway Main Road	No
7		Nagaram	S.N Colony	11KV	Keesara	15:26	16:56	1:30		Tree branches fallen on the 11KV line at Rampally 'X' Road	No
1	HYD N	Gunrock	Bowenpally	11KV	C-VI	08.40	10.15	01.35	EL	No Visible Fault	No
2		Tirumalagiri	Khanajiguda	11KV	VI	14:35	16:50	2:15	EL,OL	HT Jumper cut at Ambedkar Nagar	No
3		Addagutta	Ganesh Temple	11KV	C-VI	14:46	16:00	1:14	EL,OL	No Visible Fault (Due to Rain)	No
4		Addagutta	Polytechnic	11KV	C-VI	14:46	16:55	2:09	EL	No Visible Fault (Due to Rain)	No
5		Tirumalagiri	Officers Colony	11KV	C-VI	14:46	15:56	1:10	EL	No Visible Fault (Due to Rain)	No
6		Patigadda	Rasoolpura	11KV	C-VI	14:52	17:40	2:48	EL,OL	No Visible Fault (Due to Rain) (From 16:10 to 17:02 Hrs I/C supply failed to 33KV Patigadda SS)	No
7		Chinna Thokatta	Central Excise	11KV	VI	14:52	16:01	1:09	All Indication	No Visible Fault (Due to Rain)	No
8		Patigadda	Rani Gunj	11KV	V	14:53	18:37	3:44	EL	Due to Rain	Arranged B/F on 11KV Botany School feeder
9		Chinna Thokatta	Hasmathpet	11KV	VI	14:54	16:23	1:29	EL,OL	No Visible Fault (Due to Rain)	No
10		Addagutta	Ambedkar Nagar	11KV	C-VI	14:55	16:20	1:25	EL	Kite Sticks & Kite threads on lines at Ambedkar Nagar	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
11		Chinna Thokatta	Old Bowenpally	11KV	VI	15:00	16:14	1:14	EL,OL	No Visible Fault (Due to Rain)	No
12		Bowenpally	I.A.F.	11KV	VI	15:00	16:50	1:50	EL,OL	Tree branches fallen on lines at IAF Gate	No
13		I.D.P.L.	Tipcon	11KV	VI	15:00	16:05	1:05	EL,OL	No Visible Fault (Due to Rain)	No
14		Patigadda	Sindhi Colony	11KV	V	15:00	17:30	2:30	EL,OL	No Visible Fault (Due to Rain) (From 16:10 to 17:02 Hrs I/C supply failed to 33KV Patigadda SS)	No
15		Chilkaiguda	Dandu Pentaiah	11KV	V	15:05	16:10	1:05	EL	AB Switch fault at Saibaba Temple	No
16		Chinna Thokatta	Park View Enclave	11KV	VI	15:06	16:11	1:05	OL	No Visible Fault (Due to Rain)	No
17		Gunrock	Tirumalagiri	11KV	C-VI	15:10	17:10	2:00	EL	LT Line snapped at Biryani Dharbar	No
18		Marredpally	Jyothi Nagar	11KV	C-VI	15:30	17:05	1:35	EL	Tree branches fallen on lines at AOC Gate	No
19		Tirumalagiri	Chinna Kamela	11KV	C-VI	15:35	17:20	1:45	EL	Jumper cut at Lal Bazar FOC Office	No
20		Patigadda	Zeera	11KV	V	18.45	20.13	01.28	All Indication	CT PT failed at Zeera	Partial fdr charged & remaining loads added on 11KV Hyder Basthi feeder
1	HYD S	Miralam	Mustafa Nagar	11KV	III	00.22	01.58	01.36	EL,OL	Pin Insulator flash over at 17 Malgi & DTR fault at Join Functional Hall	Arranged B/F on 11KV Shaik-E-Masjid feeder