

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	6	1	6	1	6	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 17.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Nawabpet	33KV	Mahabubnagar	15.40	16.02	00.22	O/L	33KV Cable Burn at Railway Crossing	Nawabpet	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 17.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Kosgi	11KV	Narayanapet	11.45	12.15	00.30		Due to HT/LT Near Raghavendra DTR Kosgi Town	-
1	NLG	Velgupally	A.R.Gudem	11KV	Nalgonda	05.40	11.00	05.20	EL	Tree Fallen on the 11 KV Line	-
2		Palem	Bopparam	11KV	Nalgonda	11.35	12.50	01.15	EL	11 KV Line Melt	-
1	SDPT	Akkannapet	Pakilnayak Thanda	11KV	Husnabad	12.33	13.17	00.44		Brass Patty cutting	-
2		PREGNAPUR	PREGNAPUR TOWN	11KV	Gajwel	06.40	07.34	00.54		CONDUCTOR SNAPPED	-
3		MULUGU	MULUGU AGL	11KV	Gajwel	14:02	18:10	04.08		INSULATOR FAILED	-
1	RR N	Shameerpet	Nalsar	11KV	Medchal	06.50	09.20	02.30	BD	Breaker Mechanical Problem in SS	-
1	HYD C	Industrial Area	Adikmet	11KV	II	10.15	11.35	01.20	EL	DCM Van dashed to line AB Switch at Nala	