

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403									
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	10	3	10	3	10			
2	NLG	144	988		4		4		4			
3	MDK	107	933	3	1	3	1	3	1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	15	6	15	6	15	0	0	
	Grand Total	1082	6468	6	22	6	22	6	22	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 19.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Palkonda	Janampet	33KV	Mahabubnagar	02.12	03.18	01.06	EL	Line Petroling No Visble Fault	Janampet	AB Switch Open at Bolkampally Gate
2		Kosgi	Kosgi	33KV	Narayanapet	01.55	03.10	01.15	EL	Line Petroling No Visble Fault	Kosgi	-
3		Puttapahad	Nancherla	33KV	Narayanapet	12.25	15.30	03.05	EL&OL	Disc Insulator Failed at Mukarlabad Dhaba	Nancherla	-
1	MDK	Pashamailaram	SOL	33KV	Sangareddy	14.55	17.45	02.50		BD Due to Tree Fallen on line	SOL	-
2		Pashamailaram	Manjeera	33KV	Sangareddy	14.56	18.40	03.44		BD Due to Tree Fallen on line	Manjeera	-
3		Gummadidala	GPSS-1	33KV	Patancheru	14.47	16.25	01.38		BD Due to Conductor Snapped	GPSS-1	-

TSSPDCL - LMRC / Corporate office

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 19.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gundumal	Amlikunta	11KV	Narayanapet	02.40	04.10	01.30		Break down due to Heavy Gale and wind	-
2		Kosgi	Sampally	11KV	Narayanapet	06.20	07.20	01.00		Break down due to Tree Branch fallen on 11KV line	-
3		Maddur	Dorepally	11KV	Narayanapet	06.16	08.20	02.04		Break down due to 11KV Disc faile Near Jadaraopally vg	-
4		Pallerla	Nandipad	11KV	Narayanapet	05.00	12.45	07.45		Break down due to 11KV insulator burnt Near Chinthlagattu Tanda	-
5		Salkarpet SS	Salkarpet	11KV	Narayanapet	02.00	08.00	06.00		Break down due to 11KV Disc faile at Rangareddypally vg	-
6		Salkarpet SS	Pagdiyal	11KV	Narayanapet	11.10	14.35	03.25		Break down due to 11KV insulator faile at Balsulgonda vg	-
7		NARAYANPET	JALALPUR	11KV	Narayanapet	13.40	15.10	01.30		Break down due to 11kv cable fault at bairam konda vlg	-
8		MARIKAL	P.C.KUNTA	11KV	Narayanapet	00.02	05.50	05.48		Break down due to bird fallen on DTR at venkatapur vlg	-
9		MARIKAL	TILERU	11KV	Narayanapet	01.08	01.58	00.50		Break down due to rain fall	-
10		Mothiganapur	Medigaddatanda	11KV	Jadcherla	11.00	13.00	02.00		11Kv Jumper Cut Near Medigaddatanda Side.	-
1	NLG	Kudakuda	MG Nagar Thanda	11KV	Suryapeta	06.00	12.16	06.16	EL	Conductor snapped	-
2		Palem	Ogudu	11KV	Nalgonda	05.55	09.30	03.35	EL	11KV Jumper cut Under	-
3		Thummadam	Narammagudem	11KV	Miryalaguda	15.45	19.20	03.35	EL	11KV Jumper cut and fallen on another phase	-
4		Damarcherla	Bothalapalem	11KV	Miryalaguda	08.30	09.28	00.58	EL	Insulator failure	-
1	MDK	Isnapur	Wedia	11KV	Sangareddy	14.05	16.52	02.47		BD due to Flexi & Street light Pole fallen on line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Bachupally	Praneeth	11KV	Kukatpally	10.50	12.30	01.40	EL/OL	AB Cable failed at Praneeth Antiliya Road	-
2		Subhash Nagar	Meenakshi	11KV	Medchal	12.35	13.17	00.42	EL	11KV Line AB Switch Opened at Meenakshi (11KV Line Cut & Replaced Subhash Reddy House, Meenakshi)	-
3		Athiwelly	SPIC	11KV	Medchal	02.50	07.15	04.25	EL	Breaker Limb Problem (Alternate Supply arranged from 11KV Somaram feeder)	-
4		Genome Vally	Patel Kunta	11KV	Medchal	11.40	12.30	00.50	EL	11KV Line Cut & Replaced at Kolthur	-
1	HYD N	Road No.2	Lumbini Mall	11KV	X	13.40	15.10	01.30	EL	Jumper cut at Bachpan School	Partial fdr charged & Ramaing loads added on 11KV Kamalapuri Colony fdr
2		Road No.22	UCO Bank	11KV	X	13.42	14.58	01.16	EL,OL-Rph	Jumper cut & Disc Insulator flash over at Road No.22	-----
1	HYD S	Malakpet	Noorkhan Bazar	11KV	VIII	00.02	01.12	01.10	EL	No Visible Fault	Arranged B/F on 11KV Chadarghat fdr