

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	7	1	7	1	7			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		4		4		4			
	Total	606	3055	1	14	1	14	1	14	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5		5		5				
2	NLG	144	988	1	16	1	16	1	16			
3	MDK	107	933		1		1		1			
4	SDPT			1	14	1	7	1	7		7	7 Nos 11KV feeder till BD
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	7	31	7	24	7	24	0	7	
	Grand Total	1082	6468	8	45	8	38	8	38	0	7	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 22.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Palkonda	Janampet	33KV	Mahabubnagar	18.10	19.10	01.00	E/L&O/L	Tree Fallen on the Line		
2		Ghanapur	Lattupally	33KV	Wanaparthi	20.56	22.53	01.57	E/L	Alternate Supply Taken to 33KV Bijinapally Feeder at 22:53Hrs (Due to 33KV Line Fault)		Alternate Supply Taken to 33KV Bijinapally Feeder at 22:53Hrs
3		Singotam	Kudikilla	33KV	Nagarkurnool	01.12	13.18	12.06	O/L	Tree Branch Fallen on the line and Tree Cutting		
4		Achampet	Veltoor	33KV	Nagarkurnool	20.45	21.45	01.00	O/L	Veltoor Feeder Loads Tag on to 33KV Uppunuthala Feeder (Due to Tree Fallen on the Line)		Veltoor Feeder Loads Tag on to 33KV Uppunuthala Feeder at 21:45Hrs
5		Alampur	Shanthiagar-I	33KV	Gadwal	20.51	21.55	01.04	E/L	Tree Fallen on the Line		
1	NLG	Wadapally	A.D. Pally	33KV	Miryalguda	11.20	14.40	03.20	O/L	33Kv Jumper Cut		-
1	SDPT	Gajwel	KDA	33KV	Gajwel	19.30	4.30 (23.04.21)	09.00		Conductor Snap		-
1	RR N	132KV LGM Pet	33KV Aliabad	33KV	Medchal	18.22	19.55	01.33	BD	Tree fallen on the 33KV Line at Laxmapur Road		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 22.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged	
1	NLG	Koppole	Bheemaram	11KV	Nalgonda	06.00	08.47	02.47	E/L	11KV Jumper cut	-	
2		Eduloor	Munukuntla	11KV	Nalgonda	02.10	06.45	04.35	E/L	11KV Jumper cut	-	
3		CH.Annaram	G.B.Gudem	11KV	Nalgonda	03.35	06.50	03.15	E/L	11KV Jumper cut		
4		Reddygudem	Kothagudem	11KV	Suryapet	07.30	10.55	03.25	E/L	11Kv Conductor snapped		
5		T Singaram	Mood thanda	11KV	Suryapet	06.50	09.00	02.10	E/L	11Kv Insulator flashover		
6		Dhupahad	New Banjarahills thanda	11KV	Suryapet	06.20	09.05	02.45	E/L	11KV Insulator failed		
7		Kasarabadha	Circle peta	11KV	Suryapet	08.55	11.56	03.01	E/L	Tree fallen on the 11Kv line and Insulator failed		
8		Kalmalcheruvu	Kalmalcheruvu	11KV	Huzurnagar	16.50	18.00	01.10	E/L	11Kv Conductor snapped		
9		Mukundapuram	Dacharam	11KV	Huzurnagar	07.35	09.00	01.25	E/L	11KV Jumper cut		
10		Bethavolu	Bethavolu	11KV	Huzurnagar	18.20	20.00	01.40	E/L	Tree fallen on the 11Kv line and Insulator failed	-	
11		Timmareddy gudem	Ganapavaram	11KV	Huzurnagar	18.20	20.20	02.00	E/L	Tree fallen on the 11Kv line and Insulator failed	-	
12		Keethavarigudem	K K Thanda	11KV	Huzurnagar	04.00	07.15	03.15	E/L	11Kv Disk failed	-	
13		Raghnathpur	Challuru Agl	11KV	Bhongir	03.00	08.15	05.15	E/L	11Kv Insulator failed near Challuru (V)	-	
14		Datherpally	Jangampally	11KV	Bhongir	06.00	08.47	02.47	E/L	11Kv Line snapped at Balreddy well near jangamapally (V)	-	
15		Addagudur	Dharmaram	11KV	Bhongir	02.00	09.10	07.10	E/L	11kv Snapped near Laxmidavi kaluva (V)	-	
16		Athmakur	Thukkapur	11KV	Bhongir	04.00	08.30	04.30	E/L	11kv Line snapped near Kamunigudem (V)	-	
1	MDK	Bollaram-II	Rupa	11KV	Patancheru	18.55	20.08	01.13		B/D due to Disk failed	-	
1	SDPT	Jangapally	Jangapally	11KV	Siddipet	17.35	till			B/D Still now continue	-	
2		Peddachikode	Achumaipally	11KV	Siddipet	20.20	till			B/D Still now continue	-	
3		Gajwel SS	Mutrajpally feeder	11KV	Gajwel	19.35	20.40	01.05		Due to Tree fallen on line		
4		Gajwel SS	Mutrajpally feeder	11KV	Gajwel	21.15	22.25	01.10		Due to Tree fallen on line		
5		BV PUR SS	Industrial feeder	11KV	Gajwel	19.20	20.20	01.00				
6		Jagadevapur SS	Industrial feeder	11KV	Gajwel	19.43	21.13	01.30				
7		Pregnapur SS	Gundannapally AGL Feeder	11KV	Gajwel	22.00	till					
8		Markook SS	Mmarkook Town Feeder	11KV	Gajwel	19.30	20.35	01.05				
9		Markook SS	Bhavandapur Feeder	11KV	Gajwel	09.30	till				-	
10		Ganeshpally SS	Angadikistapur Feeder	11KV	Gajwel	19.40	till				-	
11		Pamulaparthi SS	Express feeder	11KV	Gajwel	20.00	till				-	
12		Gowraram SS	Mailaram Feeder	11KV	Gajwel	19.45	till				-	
13		Husnabad	Thotapally	11KV	Husnabad	08.05	08.37	00.32			Insulator Fail	-
14		Arjunpatla	Kamlaipally	11KV	Husnabad	12.00	13.14	01.14			The STORK Fell on the line	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	HMT	Ganesh Nagar	11KV	Medchal	19.02	20.05	01.03	EL	Tree fallen on the 11KV Line at Cherukupally Colony	-
2		Subhash Nagar	Gayatri Nagar	11KV	Medchal	20.11	20.37	00.26	EL	Breaker Mechanical Problem in SS and backfeeding arranged from 11KV Jeedimetla feeder	-
3		Kistapur	IDA Hanuman	11KV	Medchal	09.50	10.50	01.00	EL	11KV Line Cut & Replaced at near SS	-
4		Kistapur	IDA Hanuman	11KV	Medchal	19.30	21.40	02.10	EL	11KV Line cut and replaced at Jayadarshini Venture	-
5		ICICI	Bharath Biotech	11KV	Medchal	18.10	21.30	03.20	EL/OL	11KV Line cut and replaced at HP Petrol Pump	-
6		Aliabad	Jaganguda	11KV	Medchal	19.15	22.30	03.15	EL	11KV Pin Insulator failed at Essar Petrol Pump	-
7		Ravalkole	Cheruvukatta	11KV	Medchal	18.38	22.50	04.12	EL/OL	11KV Disc failed at Lokesh Company	-
1	RR E	Uppal Bhagath	Sathya Nagar	11KV	Habsiguda	19.25	21.02	01.37		11KV Pin Insulator failed at Shanthi Nagar	-
2		Narapally	Prathap Singaram	11KV	Keesara	20.05	20.50	00.45		Tree branches fallen on 11kv line at Korremula	-
3		Narapally	Narapally Indl	11KV	Keesara	20.05	21.20	01.15		Tree branches fallen on 11kv line at Mc Donalds Narapally	-
1	HYD N	Gymkhana	Balamrai	11KV	C-VI	21.30	23.01	01.31	EL	Coconut tree branch fallen on lines at Paigah Colony	-
2		Macha Bollaram	Ayyappa Nagar	11KV	C-VI	21.50	22.55	01.05	EL	Pin Insulator flash over at Asha Jyothi Colony	-
3		Clock Tower	Natraj	11KV	V	22.49	00.24	01.35	EL	Faulty loads of 11KV S.P.Road fdr	-
1	HYD C	I.T.I Mallepally	V.B.R.I	11KV	VII	07.27	08.34	01.07	EL	DTR fault at back side of SS	-