

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403									
8	Hyd	194	1044		7		7		7			
	Total	606	3055	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	4	3	4	3	4	3			
2	NLG	144	988	20	36	20	36	20	36			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT			1	11	1	11	1	11			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	27	51	27	51	27	51	0	0	
	Grand Total	1082	6468	27	62	27	62	27	62	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 23.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Jaklair	33KV	Mahabubnagar	00.45	01.30	00.45	E/L	Due to No Visible fault Heavy Wind Gale & Rain	Jaklair	Alternate Supply Arranged From 33KV Dhanwada
2		Makthal	Krishna	33KV	Mahabubnagar	03.35	09.25	05.50	E/L	for 2Nos Pin Insulator Replaced	Krishna	-
3		Nagarkurnool	Peddakothapally	33KV	Nagarkurnool	17.57	19.25	01.28	E/L	Due to Heavy Wind Gale & Rain	Peddakothapally	Alternate Supply Arranged From 132KV Wanaparthy
4		Gadwal	Alampur	33KV	Shanthinagar1	18.38	18.44	00.06	E/L	Due to Heavy Wind Gale & Rain	Alampur	Alternate Supply Arranged From 33KV Shanthinagar 2
1	NLG	Aitipamula	Aitipamula	33KV	Nalgonda	23.52	07.20	07.28	E/L	Moment Fault		-
2		Aitipamula	Arlagaddagudem	33KV	Nalgonda	23.04	19.15	20.11	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
3		Nalgonda	Pajjur	33KV	Nalgonda	23.00	09.30	10.30	E/L	Line touched the iron pole		-
4		Madugulapally	Thipparthi	33KV	Nalgonda	23.30	13.45	03.36	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
5		Kangal	Kopal	33KV	Nalgonda	22.10	08.03	09.53	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
6		Kangal	Phagidimarri	33KV	Nalgonda	22.04	11.50	13.46	E/L	2 Insulators Failed		-
7		Gudapur	Chikatimamidi	33KV	Nalgonda	23.00	11.00	12.00	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
8		K.M.Pally	Devarakonda	33KV	Devarakonda	23.00	18.25	19.25	E/L	DCM Lorry damaged the DP Structure		-
9		Madugulapally	Agamothkur	33KV	Miryalguda	23.30	10.30	11.00	E/L	Tree fallen on the line		-
10		Madugulapally	Laxmidevi gudem	33KV	Miryalguda	23.50	18.50	19.00	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
11		Madugulapally	Thadakamalla	33KV	Miryalguda	23.50	09.25	09.35	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
12		Madugulapally	Seethya Thanda	33KV	Miryalguda	23.50	16.15	16.25	E/L	Pin Insuleters Failed & Tree branches fallen on the line		-
13		Madugulapally	Vissaka (Indl)	33KV	Miryalguda	23.50	12.50	13.00	E/L	Insulator failed near Pothireddy land		-
14		Yerrabally	Mupparam	33KV	Miryalguda	21.30	10.35	13.05	E/L	Pin Insuleter Failed & Tree branches fallen on the line		-
15		Wadapally	Mission Bhagiradha	33KV	Miryalguda	23.50	13.30	13.40	E/L	33KV TOP CLEAT TOUCH V Crossarm		-
16		Wadapally	YTPSL	33KV	Miryalguda	23.50	10.55	11.05	E/L	Crossarm bend & phase to phase touched		-
17		Wadapally	A.D.Pally	33KV	Miryalguda	23.50	12.10	12.20	E/L	Moment Fault		-
18		Miryalguda	Huzurnagar	33KV	Miryalguda	23.45	16.20	16.35	E/L	Insulator failed Due to lighting		-
19		Suryapet	Nuthankal	33KV	Suryapet	22.30	12.15	13.45	EL	1 No Insulator flashover		-
20		Thungathurthy	Annaram	33KV	Suryapet	23.30	10.30	11.00	EL	2 Nos Insulator failed		-
1	SDP	Shanigaram	Ramchandrapur	33KV	Husnabad	16.05	18.10	02.05		Top insulator repalced near Thimmaipally (V)	Ramchandrapur	-
1	MDK	Zaheerabad	Jharasangam	33KV	Zaheerabad	18.20	21.10	02.50		B/D Due to Jumper cut	Jharasangam	-
2		Zaheerabad	Old Allana	33KV	Zaheerabad	18.21	20.15	01.54		B/D Due to Jumper cut	Old Allana	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 23.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	NARAYANPET	NARAYANPET TOWN (CIVIL)	11KV	NARAYANPET	00.20	02.36	02.16		11kv line cut near bus depot	-
2		MADDUR	PEDIRIPAD	11KV	NARAYANPET	10.15	12.00	01.45		11kv line cut and fallen on channel pediripad vlg	-
3		PALLERLA	PARSAPUR	11KV	NARAYANPET	09.45	11.18	01.33		11kv line cut padya tanda	-
1	NLG	Rajupeta	Rajupeta	11KV	Nalgonda	00.00	13.35	13.35	E/L	Tree branch fallen on 11KV line	-
2		Rajupeta	Jonnagaddalagudem	11KV	Nalgonda	00.00	13.35	13.35	E/L	Tree branch fallen on 11KV line	-
3		Mushampally	Mushampally AGL	11KV	Nalgonda	23.20	12.00	12.40	E/L	Tree fallen on 11KV line	-
4		Eduloor	Munkuntla	11KV	Nalgonda	05.45	09.35	03.50	E/L	Tree branch fallen on 11KV line	-
5		Ch.Annaram	Ch.Annaram	11KV	Nalgonda	05.45	09.00	03.15	E/L	11KV Insulator failed	-
6		Panagal	RWS	11KV	Nalgonda	23.00	08.00	09.00	E/L	Tree branch fallen on 11KV line	-
7		Aitipamula	Rasoolgudem	11KV	Nalgonda	07.30	16.40	09.10	E/L	11KV line cut at near Srimannarayana bavi	-
8		Aitipamula	Indl	11KV	Nalgonda	07.30	12.20	04.50	E/L	11KV disc failed	-
9		Pazzur	Peddaturaram	11KV	Nalgonda	21.35	12.10	15.35	E/L	Tree fallen on 11KV line	-
10		Kethepally	Korlapahad	11KV	Nalgonda	06.45	18.00	11.15	E/L	Tree fallen on 11KV line	-
11		Kasarabadha	Kesaram	11KV	Suryapet	04.00	07.00	03.00	EL	Insulator flashover	-
12		Ravulapally	Ravulapally	11KV	Suryapet	05.30	09.00	03.30	EL	Disk failed	-
13		P.D.Pally	Gajalapuram	11KV	Miryalaguda	08.20	13.35	05.15	EL	AGL DTR jumper cut near Gajalapuram (V)	-
14		Nidmanoor	Shakapuram	11KV	Miryalaguda	05.10	09.10	04.00	EL	Tree branches fallen	-
15		Mupparam	Vootkur	11KV	Miryalaguda	10.30	12.22	01.52	EL	Conductor Phase to Phase	-
16		Shettipalem	Vemulapally Agl	11KV	Miryalaguda	07.00	09.35	02.35	EL	Conductor snapped	-
17		Shettipalem	Shettipalem-1	11KV	Miryalaguda	07.00	08.15	01.15	EL	Conductor snapped	-
18		Kamareddygudem	Brundavanpuram	11KV	Miryalaguda	06.00	09.00	03.00	EL	Tree branches fallen	-
19		Kamareddygudem	Pusalapadu	11KV	Miryalaguda	07.30	09.40	02.10	EL	Conductor Phase to Phase	-
20		Agamothkur	Bommakal	11KV	Miryalaguda	10.01	12.00	01.59	EL	Tree branches fallen	-
21		Agamothkur	Agamothkur	11KV	Miryalaguda	10.00	15.00	05.00	EL	Conductor snapped	-
22		Nunavath tanda	Kondrapole	11KV	Miryalaguda	16.10	18.20	02.10	EL	Tree branches fallen	-
23		Kothagudem	Laxmipuram	11KV	Miryalaguda	06.00	16.20	10.20	EL	Tree branches fallen	-
24		MR.Gudem	Baswapur	11KV	Bhongir	06.30	09.00	02.30	EL/OL	11 KV Insulator failed near Baswapur village	-
25		MR.Gudem	Gangasanipally	11KV	Bhongir	06.30	08.30	02.00	EL/OL	11 kv Insulator failed at Durga .Prasad thota near Gangasanipally village	-
26		Raigir	Jammapur indl	11KV	Bhongir	21.00	10.10	13.10	EL/OL	11kv Insulator Failed near Jammapur Villaage	-
27		Ch.Laxmapur	Ch.Laxmapur	11KV	Bhongir	07.00	11.00	04.00	EL/OL	11kv Insulator Failed near Potti marri Thanda	-
28		B.Ramaram	Hajipur	11KV	Bhongir	22.00	10.10	12.10	EL/OL	11 kv Top insulator failed at Model school back side near Hajipur village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
29	NLG	Datherpally	Mallapuram	11KV	Bhongir	06.05	09.20	03.15	EL/OL	11 kv cable failed at Devankula Marri near mallapuram village	-
30		Chamapur	Chamapur	11KV	Bhongir	07.45	09.20	01.45	EL/OL	11 kv Line snapped at Yelamala. Sanjeeva reddy well near Chamapur village	-
31		Pallerla	Siddapuram	11KV	Bhongir	05.30	08.10	02.40	EL/OL	2 no's 11 kv poles damages near Siddapuram village	-
32		Ramannapet	Ramannapet town	11KV	Choutuppal	21.38	00.34	02.56	EL/OL	11 kv Insulator failed at Mother teresa school near ramannapet town	-
33		Panhangi	Areygudem Indl	11KV	Choutuppal	05.18	07.51	02.33	EL/OL	11 kv Line snapped at VVR Company near Areygudem village	-
34		Juloor	Peddagudem	11KV	Choutuppal	06.10	11.00	04.50	EL/OL	11 KV disc & 11 kv Insulator failed near Peddagudem village	-
35		Jublakpally	Indl	11KV	Choutuppal	22.55	07.45	08.50	EL/OL	11 KV Insulator failed near jublakpally village.	-
36		MT.pally	Thimmapur	11KV	Choutuppal	22.20	13.55	15.45	EL/OL	11kv Disc Failed near Thimmapur Village	-
1	MDK	EPIP-I	GENSINTH	11KV	Sangareddy	20.08	21.38	01.30		B/D Due to Conductor Snapped	-
1	SDP	Gurjakunta	Vechareni	11KV	Husnabad	05.00	11.50	06.50		Tree fallen in line	-
2		Mirdoddy	Jangapally	11KV	Siddipet	00.00	08.45	08.45		B/D AGL DTR Male Femele Problem	-
3		Jagadevpur SS	Jagadevpur	11KV	Gajwel	00.10	11.02	10.52		11 KV conductor Snapped	-
4		Pregnapur SS	Akkaram	11KV	Gajwel	07.30	08.35	01.05		Conductor Snapped	-
5		Pamulaprttyhy SS	Indiranagar	11KV	Gajwel	06.00	15.40	09.40		11 KV line Snapped	-
6		Erravally SS	Narsannapeta	11KV	Gajwel	10.26	11.32	01.06		Disk Fail	-
7		Erravally SS	Erravally Town	11KV	Gajwel	17.45	18.25	00.40		Insulator Fail	-
8		Wargal SS	Wargal AGL	11KV	Gajwel	00.10	13.05	12.55		Trees Fallen and poles broken	-
9		Mulugu SS	Nagireddypally	11KV	Gajwel	00.10	11.35	11.25		11 KV Poles Broken	-
10		Mulugu SS	Narsampally	11KV	Gajwel	09.00	14.50	05.50		11 KV line Cut & Indulator Fail	-
11		Wantimamidi SS	Chinnathimmapur	11KV	Gajwel	00.10	11.55	11.45		LT Line & 11 Line Touch	-
1	RR N	Bowrapet	junrm	11KV	Jeedimetla	15.15	16.17	01.02		11kv endy Kit Failure At Kritool School	-
2		Kandlakoya	KV Reedy Nagar	11KV	Medchal	22.50	23.40	00.50		Tree fallen on the 11KV Line at Mypee Villas	-
3		UMCC	Crusher	11KV	Medchal	22.15	22.55	00.40		11KV Pin Insulator failed at Zoom Room	-
4		Laxmapur	IDA Laxmapur	11KV	Medchal	13.20	14.13	00.53		CT failed in SS	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD N	Macha Bollaram	Radha Sath Sang	11KV	C-VI	13.00	14.15	01.15	EL,OL-Rph	Breaker fault at SS	Arranged B/F on 11KV ARK Homes fdr
2		Gymkhana	Balamrai	11KV	C-VI	22.30	23.45	01.15	EL,OL	No Visible Fault	-----
3		Seethaphal Mandi	Srinivasa Nagar Colony	11KV	V	22.50	00.40	01.50	EL,OL	No Visible Fault	-----
4		Seethaphal Mandi	Namalagundu	11KV	V	22.55	02.15	03.20	EL,OL	End Kit failed at Venkateshwara Apts	23:15Hrs partial loads added on 11KV Srinivasa Nagar Colony fdr & partial loads added on 11KV Warasiguda fdr
5		I.D.P.L.	Samatha Nagar	11KV	VI	23.05	00.20	01.15	EL	Tree branches fallen on lines at Samatha Nagar	-----
1	HYD C	Indira Park	Gagan Mahal	11KV	I	11.05	14.40	03.35	EL,OL-Rph	Pole damaged by Unknown Vehicle	-
2		Asif Nagar	Avalon	11KV	VII	22.41	00.10	01.29	EL	Tree branches fallen on lines at Karol Bagh	-