

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		5		5		5			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		6		6		6			
2	NLG	144	988		23		23		23			
3	MDK	107	933	1		1		1				
4	SDPT			1	1	1	1	1	1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	30	2	30	2	30	0	0	
	Grand Total	1082	6468	2	41	2	41	2	41	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Zaheerabad	Hadnoor	33KV	Zaheerabad	8:20	11:30	3:10		Insulator failed	Hadnoor	No
1	SDPT	Angadikistapur	Wardarajpur	33KV	Gajwel	0:53	12:50	11:07		Breaker limb failed	Wardarajpur	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Krishna	CHEGUNTA	11KV	Narayanapet	10.50	11.50	01.00		11kv line fault at chegunta vlg	No
2		CHINNAJATRAM	LAXMIPUR	11KV	Narayanapet	06.35	08.40	02.05		tree branch fallen on 11kv line at boinpally vlg	No
3		MARIKAL	APPAMPALLY	11KV	Narayanapet	17.30	19.28	01.58		cable pin binding broken at appampally vlg	No
4		MARIKAL	P.C.KUNTA	11KV	Narayanapet	16.45	17.35	00.50		11kv line pole fallen at venkatapur vlg	No
5		EKLASPUR	CHITTANUR	11KV	Narayanapet	15:20	17:30	2:10		11kv jumper touched to pole at chittanur vlg	No
6		PALLERLA	NADIPAD	11KV	Narayanapet	11.35	11.50	00.15		DTR repair at nandipad vlg	No
1	NLG	Mushampally	Mutyalamma	11KV	Nalgonda	6:05	11:00	28.55	EL	Poles Damaged	No
2		Nakrekal	Police Station	11KV	Nalgonda	0:20	8:00	8:20	EL	Poles Damaged and Trees Fallen on the Line	No
3		Madgulapally	Madgulapally	11KV	Nalgonda	23:50	1:00	1:50	EL	2 Nos. Poles Damaged and Trees Fallen on the Line	No
4		Madgulapally	Dacharam	11KV	Nalgonda	23:50	11:00	11:50	EL	Poles Damaged	No
5		Madgulapally	Indugula	11KV	Nalgonda	23:50	12:00	12:50	EL	Poles Damaged	No
6		Madgulapally	Kukkadam	11KV	Nalgonda	23:50	1:00	1:50	EL	12 Nos. Poles Damaged and Trees Fallen on the Line	No
7		Anneparthy	Cherlapally AGL	11KV	Nalgonda	23:30	10:30	11:00	EL	Poles Damaged	No
8		P.D.Pally	Gajalapuram	11KV	Miryalaguda	8:20	13:35	5:15	EL	AGL DTR jumper cut near Gajalapuram (V)	No
9		Nidmanoor	Shakapuram	11KV	Miryalaguda	5:10	9:10	4:00	EL	Tree branches fallen	No
10		Mupparam	Vootkur	11KV	Miryalaguda	10:30	12:22	1:52	EL	Conductor Phase to Phase	No
11		Shettipalem	Vemulapally Agl	11KV	Miryalaguda	7:00	9:35	2:35	EL	Conductor snapped	No
12		Shettipalem	Shettipalem-1	11KV	Miryalaguda	7:00	8:15	1:15	EL	Conductor snapped	No
13		Kamareddygudem	Brundavanpuram	11KV	Miryalaguda	6:00	9:00	3:00	EL	Tree branches fallen	No
14		Kamareddygudem	Pusalapadu	11KV	Miryalaguda	7:30	9:40	2:10	EL	Conductor Phase to Phase	No
15		Agamothkur	Bommakal	11KV	Miryalaguda	10:01	12:00	1:59	EL	Tree branches fallen	No
16		Agamothkur	Agamothkur	11KV	Miryalaguda	10:00	15:00	5:00	EL	Conductor snapped	No
17		Nunavath tanda	Kondrapole	11KV	Miryalaguda	16:10	18:20	2:10	EL	Tree branches fallen	No
18		Kothagudem	Laxmipuram	11KV	Miryalaguda	6:00	16:20	10:20	EL	Tree branches fallen	No
19		Phanigiri	Anantharam	11KV	Suryapet	9:00	13:30	4:30	EL	Conductor snapped	No
20		Mukundapuram	Mukundapuram	11KV	Suryapet	4:30	6:56	2:26	EL	Insulator failed	No
21		Bollepally	Jampally	11KV	Bhongir	8:00	10:00	2:00	EL	11 kv Line snapped near Madaram village	No
22		Golankonda	Matoor	11KV	Bhongir	0:55	8:45	7:50	EL	11 kv Line snapped near rai kunta pally village.	No
23		Mothkur	Mothkur rural	11KV	Bhongir	9:30	12:30	3:00	EL	11KV Line Snapped near Mothkur Village	No
1	SDPT	Gowraram	Gowraram Town 2	11KV	Gajwel	8:28	9:30	1:02		Insulator failed	No
1		Dppally-SS- I	AGL Gagillapur	11KV	Jeeditmetla	8:00	11:00	3:00		11kv Pin Insulator Failure At Nagalura	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
2	RR N	Subhash Nagar	Meenakshi	11KV	Medchal	12.35	13.17	00.42		11KV Line AB Switch Opened at Meenakshi(11KV Line Cut & Replaced Subhash Reddy House, Meenakshi)	No
3		Athiwelly	SPIC	11KV	Medchal	02.50	07.15	04.25		Breaker Limb Problem	Alternate Supply arranged from 11KV Somaram feeder
4		Genome Vally	Patel Kunta	11KV	Medchal	11.40	12.30	00.50		11KV Line Cut & Replaced at Kolthur	No
1	RR E	Street no 8	Greenhills	11KV	Habsiguda	23:04	0:37	1:33		Tripped on EL/OL Due to wind & Rain AB cable falt & given B/F load from ISI feeder	No
2		Uppal	Navbharath	11KV	Habsiguda	23.10	00.40	01.30		Tripped on EL/OL due to wind & rain but no visiable fault found	No
3		Uppal	Bank colony	11KV	Habsiguda	23.10	00.50	01.40		Tree branches fallen on 11KV line & LUG cut at LFJC	No
4		Uppal Bhagath	Saraswathi nagar	11KV	Habsiguda	23.07	00.21	01.24		Tripped on EL/OL due to Wind & rain Aline AB swicth open shilpa ramam	No
5		AS Rao Nagar	MJ Colony	11KV	Sainikpuri	1:52	2:58	1:06		11Kv Pin Insulator fail at near Flora Hotel	No
1	HYD C	Asif Nagar	N.S.F Colony	11KV	VII	04.47	07.00	02.13	EL	AB Cable End Kit fault at Mirza Colony	06:22 Hrs Partial loads added on 11KV M.D Lines feeders
2		Osm. University	Boudha Nagar	11KV	II	12.10	13.15	01.05	EL,OL-Bph	Tree branches on lines at Boudha Nagar Community Hall	No