

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988	2	10	2	10	2	10			
3	MDK	107	933									
4	SDPT				1		1		1			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>14</b>	<b>3</b>	<b>14</b>	<b>3</b>	<b>14</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>16</b>	<b>3</b>	<b>16</b>	<b>3</b>	<b>16</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 30.04.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Dharoor	33KV	Gadwal	04.45	10.10	05.25	EL	Jumper cut near Narsandoddi	Dharoor	No
1	NLG	Suryapet	HPCL	33KV	Suryapet	0:00	7:20	7:20	EL	2 Nos Insulators failed	HPCL	No
2		Kusumanchi	Mamillagudem	33KV	Huzurnagar	22.30	07.20	08.50	EL/OL	33 kv line Tree fallen	Mamillagudem	No

## TSSPDCL - LMRC / Corporate office

Date: 30.04.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Konded	Chinna Adirala	11KV	Jadcherla	12.00	15.00	03.00		11Kv Jumper Cut Near Thupragadda Tanda Side.	No
2		Kodgal	Kodgal Agl	11KV	Jadcherla	06.30	10.25	03.55		Tree Follen On The 11Kv Line Near Kodgal (Vi)	No
3		CHINNAJATRAM	CHINNAJATARAM	11KV	Narayanapet	14.03	14.38	00.35		Tree branch fallen on 11kv line at chinnajatram vlg	No
1	NLG	Gurrampode	Chepuru	11KV	Devarakonda	5:35	8:15	2:40	EL	11KV Jumper Cutt & HT/HT	No
2		Gurrampode	Chamaled	11KV	Devarakonda	05.45	08.45	03.00	EL	Capur Patti Cut Thouch The Channel	No
3		B Chandupatla	Beemlathanda	11KV	Suryapet	06.00	10.00	04.00	EL	Insulator flashover	No
4		Phanigiri	Malipuram	11KV	Suryapet	03.20	06.50	03.30	EL	Pin insulator failed	No
5		Mukundapuram	Mukundapuram	11KV	Huzurnagar	05.30	07.30	02.00	EL	11 KV LINE SNAPPED	No
6		Dirsincherla	Dirsincherla	11KV	Huzurnagar	05.30	07.00	01.30	EL	11 KV LINE Tree Fallen	No
7		Munagala	Industrial	11KV	Huzurnagar	03.00	06.40	03.40	EL	11 KV LINE SNAPPED	No
8		Sirikonda	Balluthanda	11KV	Huzurnagar	05.00	08.40	03.40	EL	11 KV LINE Tree Fallen	No
9		Ananthagiri	Mogalaikota	11KV	Huzurnagar	06.00	07.45	01.45	EL	11 KV JUMPER CUT	No
10		Maryala	Mailaram	11KV	Bhongir	12:00	13:35	1:35	EL/OL	11 KV Line snapped near Maryala village	No
1	SDPT	Dommata	Dommata Industrial	11KV	Gajwel	12:55	14:44	1:49		11KV Insulator failed	No
1	HYD S	Kandikal Gate	Indira Nagar	11KV	III	15.45	18.15	02.30	EL,OL-R&Bph	Cable damaged by GHMC Wing	15:50Hrs partial fdr charged after 3Nos. 500KVA DTRs kept off & remaining loads added on 11KV Gazimillath feeder
1	HYD C	Asif Nagar	Market Yard	11KV	VII	11.34	12.58	01.24	EL,OL-Bph	Conductor snapped at Padmanabha Nagar	No