

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	0	1	0	1	0	1			
6	RR(N)	54	550									
7	RR(E)	168	403	0	1	0	1	0	1			
8	Hyd	194	1044	0	1	0	1	0	1			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	0	2	0	2	0	2			
2	NLG	144	988	0	4	0	4	0	4			
3	MDK	107	933	0	1	0	1	0	1			
4	SDPT			0	3	0	3	0	3			
5	RR(S)	58	396									
6	RR(N)	38	114	2	1	2	1	2	1			
7	RR(E)	22	133									
	Total	476	3413	2	11	2	11	2	11	0	0	
	Grand Total	1082	6468	2	14	2	14	2	14	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 03.08.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	Medchal (RRN)	132KV Chintal	33KV Subhash Nagar	33KV	Medchal	12.48	16.30	03.42		No Fault (Backfeeding arranged from 33KV Kompally Feeder 12:56)		
2		132KV LGM Pet	33KV Aliabad	33KV	Medchal	11.02	12.13	01.11		Bird fallen on the 11KV Line at Cheruvu, Aliabad		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.08.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Habsiguda	Uppal	Navabharath	11 KV	Habsiguda	11.58	14.30	02.32		Saftey Purpose Due to 33KV Line Cut at Cini Poloce and Load Added to 11KV Metro Feder	
1	Mahabubnagar	Gangapur	Alwanpally	11 KV	Jadcherla	09.00	10.00	01.00		Tree Follen On The 11Kv Line Near Tangellapally (Vi)	
2		Jaklair	Jaklair	11 KV	Narayanpet	08.50	11.40	02.50		insulator fail and dead fault at gudigandla agl	
1	Medchal (RRN)	VIKAS	VIKAS	11 KV	Kukatpally	10.10	11.30	01.20	EL/OL	Pole bending & HT/LT line was jamed at Sai krishna hills,opp vikas	
1	Nalgonda	Nakrikal	Nomula	11 KV	Nalgonda	11.58	12.45	00.47	E/L	Tree Flowen on the 11Kv Line	
2		Angadipeta	P.A.Pally Rural	11 KV	Devarakonda	12.40	13.40	01.00	E/L	11Kv Jumper Cut	
1	Siddipet	Doulthabad SS	Lingarajpally Feeder LC.No.14744	11 KV	Gajwel	14.07	15.55	01.48		11KV Line Cut	
2		GAGILLAPUR	GAGILLAPUR	11 KV	Husnabad	15.08	16.42	01.34		BREAK DOWN WORK	
3		CHERIAL TOWN	SUNDRAIAH NAGAR	11 KV		11.45	12.10	00.25		BREAK DOWN WORK	
1	Sangareddy	Sangareddy Town-I	Nalsabgadda	11 KV	Sangareddy	21.55	23.10	01.15		B/D due to Jumper cut	
1	Hyd (Central)	Industrial Area	V.S.T. (Dedicated fdr)	11 KV	Azamabad	01.15	11.50	10.35	All Indication	Cable damaged by L&T wing near SS	
1	CYBER CITY	Rain Tree Park	Station I & Station II	11 KV	KONDAPUR	21.36	22.40	01.04	EL	UG Cable Failed at Malaysian Township , LAB Switch open at Malaysian Township	
1	Yadadri	Alair	Alair town	11 KV	Bhongir	07.30	08.30	01.00		11 kv Pin insulator failed Saigudem road Alair	
2		Suddala	Bramhanapally	11 KV	Bhongir	01.00	09.00	08.00		11 kv Insulator failed at SS-9 near Paru pally village	