

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	0	3	0	3	0	3			
6	RR(N)	54	550	0	2	0	2	0	2			
7	RR(E)	168	403	0	6	0	6	0	6			
8	Hyd	194	1044	0	2	0	2	0	2			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>13</b>	<b>0</b>	<b>13</b>	<b>0</b>	<b>13</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	0	1	0	1	0			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	0	1	0	1	0	1			
4	SDPT			0	5	0	5	0	5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>21</b>	<b>2</b>	<b>21</b>	<b>2</b>	<b>21</b>	<b>0</b>	<b>0</b>	

**TSSPDCL - LMRC / Corporate office**

**Date: 15.08.2021**

**Circle-wise 33KV Breakdowns**

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Chinnamaroor	33KV	Wanaparthi	18.35	19.12	00.37		Showing Two Phase Only		Alternate Supply Arranged From 33KV Velagonda Feeder From 132KV SS Chinnamaroor at 19:12Hrs.
2	NLG	Haliya	Alwala	33KV	Miryalguda	07.50	08.50	01.00		33Kv Line Melting face to face		

**TSSPDCL - LMRC / Corporate office**

**Circle-wise 11KV Breakdowns**

**Date: 15.08.2021**

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Nagaram	S N Colony	11KV	Keesara	00.43	02.33	01.50		11KV Line Cut at Near Surya Bai Function Hall	
2	Siddipet	Damarakunta SS	Damarakunta feeder LC.No.879	11KV	Gajwel	17.20	18.30	01.10		11LV line has fallened by bird	
3		Vantimamidi SS	Ch.Thimmapur feeder LC.No.24340	11KV		08.18	09.15	00.57		Pole damedged work	
4		Medinipur SS	Kukunoorpally Feeder LC.No.195	11KV		07.20	08.35	01.15		11KV pin insulator faile	
5		Mettu SS	Masanpally feeder LC.No.6841	11KV		07.20	08.30	01.10		HT/LT line work	
6		RAMCHANDRAPUR	VARIKOLU	11KV	Husnabad	14.30	14.50	00.20		11KV INSULATOR FAIL	
7	Sangareddy	Sangareddy Town-II	Ayyappa	11KV	Sangareddy	15.45	16.28	00.43		B/D Due to Insulator Failure	
8	Suryapet	Nuthankal	Polumalla	11KV	SURYAPET	04.25	07.10	02.45		Insulator failed	
9	Yadadri	Nandanam	Nagireddypally	11KV	Bhongir	01.10	06.15	05.05		11KV Line Snapped near Nagireddypally Village	
10	Hyd South	CRPF	Balapur	11KV	Charminar	03.10	04.20	01.10		Replacement of dist insulator	
11	Hyd Central	Narayanguda	Preventive Medicine	11KV	Azamabad	03.12	06.00	02.48		Tripped on EL/OL, No visible fault	
12	SAROOR NAGAR	Kothapet	Pushpa Garden	11KV	SAROOR NAGAR	03.15	04.32	01.17	EL/OL	11KV Post of Insulator failed and rectified at Huda colony, Pushpa Garden	
13	SAROOR NAGAR	Auto nagar	Alkapuri	11KV	SAROOR NAGAR	21.57	23.25	01.28	EL	11KV Pin Insulator failed and rectified at Road no 5, RK Puram	
14	Cybercity	Gachibowli	Kalajyothi	11KV	KONDAPUR	03.45	05.00	01.15	EL/OL	11KV Pin Insulator failed, 11KV Jumper Burst and rectified at Kalajyothi Building	
15	HABSIGUDA	Uppal	Nava bharath	11KV	HABSIGUDA	08.43	09.50	01.07	EL/OL	Tree branches fallen on line at NRP company,IDA Uppal	
16	HABSIGUDA	IDA Uppal	Sri Sri nagar	11KV	HABSIGUDA	23.40	01.05	01.25	EL/OL	11KV Insulator failed and rectified at SBI bank backside	
17	HABSIGUDA	IDA Uppal	Veg Market	11KV	HABSIGUDA	23.55	01.20	01.25	EL/OL	Tree fallen on 11KV line and removed at Bodrai	
18	MEDCHAL	Nizampet	Journalist colony	11KV	KUKATPALLY	09.00	10.06	01.06	OL	11KV Pole damaged at Double bedroom	
19	MEDCHAL	Nizampet	Journalist colony	11KV	KUKATPALLY	10.57	12.46	01.49	OL	11KV Pole damaged & replaced at Double bedroom	
20	RAJENDRA NAGAR	Kismathpur	Rockchurch	11KV	RAJENDRA NAGAR	22.40	00.00	01.20	EL	11KV Insulator failed and rectified at NRI Township	
21	RAJENDRA NAGAR	Rajedra nagar	Rajendra nagar	11KV	RAJENDRA NAGAR	23.00	01.00	02.00	EL/OL	Due to Heavy rain, No Visible fault found	