

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	Failed near wire	11KV	
1	MBN	18	107							Failed near wire Cut near Mallapur		
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	0	4	0	4	0	4			
6	RR(N)	54	550	0	3	0	3	0	3			
7	RR(E)	168	403	0	4	0	4	0	4			
8	Hyd	194	1044	0	1	0	1	0	1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	0	4	0	4	0	4			
4	SDPT			0	7	0	7	0	7			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>16</b>	<b>2</b>	<b>16</b>	<b>2</b>	<b>16</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>2</b>	<b>28</b>	<b>2</b>	<b>28</b>	<b>2</b>	<b>28</b>	<b>0</b>	<b>0</b>	

**TSSPDCL - LMRC / Corporate office**

**Date: 18.08.2021**

**Circle-wise 33KV Breakdowns**

<b>S.No</b>	<b>Circle</b>	<b>Name of 132/33KV SS</b>	<b>Name of 33 KV Feeder</b>	<b>Vol</b>	<b>Name of the Division</b>	<b>From</b>	<b>To</b>	<b>Duration</b>	<b>Relay Indication</b>	<b>Cause of Breakdown</b>	<b>Sub Stations Effected</b>	<b>Alternate Supply Arranged</b>
1	Mahabubnagar	Chinnamaroor	Jetprole	33KV	Wanaparthy	19.04	22.05	03.01	E/L	for CT Problem at 132KV Chinnamaroor SS		
2	Suryapet	Reddygudem	Reddygudem	33KV	Suryapet	02.40	07.10	04.30	E/L	11KV Disc Failed near Gollapally (v)		

11KV Wire Cut near Mallapur (v)

**TSSPDCL - LMRC / Corporate office**

**Circle-wise 11KV Breakdowns**

**Date: 18.08.2021**

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Mahabubnagar	Kandoor	Choudaipally	11KV	Jadcherla	13.32	15.20	01.48		11KV Line Phase to Phase near Vaddepally (v)	
2	Mahabubnagar	Gangapur	Gollapally	11KV	Jadcherla	08.16	12.40	04.24		11KV Disc Failed near Gollapally (v)	
3	Mahabubnagar	Midjil	Kothur	11KV	Jadcherla	07.30	10.30	03.00		11KV Wire Cut near Mallapur (v)	
4	MEDCHAL	Subash Nagar	Suchitra	11KV	MEDCHAL	03.05	03.45	00.40		No Fault	
5	MEDCHAL	Subash Nagar	Jairam Nagar	11KV	MEDCHAL	04.10	04.40	00.30		11KV Line AB Switch Opened at JK Nagar, Petrol Bunk(Disc failed at Hanuman Temple, JK Nagar)	
6	MEDCHAL	Subash Nagar	Suchitra	11KV	MEDCHAL	04.00	04.20	00.20		11KV Line AB Switch Opened at Meenakshi Estate(Pin Insulator failed at Bommarillu)	
7	Siddipet	GAJWEL PREGNAPUR SS	HOUSING BOARD FEEDER	11KV	GAJWEL	03.18	04.53	01.35		DISK FAILED	
8	Siddipet	ERRAVALLY SS	PS FEEDER (LC.NO.25826) LAXMAN LM	11KV		22.15	10.40	12.25		DISK FAILED	
9	Siddipet	METTU SS	INDUSTARIAL FEEDER (LC.NO.6846) NAGARAJU JLM	11KV		01.30	08.00	06.30		INSULATOR FAILED	
10	Siddipet	RAMPUR SS	RAMPUR FEEDER (LCNO.10221.) RAVINDER CL	11KV		06.40	07.30	00.50		INSULATOR FAILED	
11	Siddipet	Raghavapur	Bachaipally	11KV		07.30	09.20	01.50		B/D disk fail Lc no 17485	
12	Siddipet	Guruvannapet	Tapaspally	11KV		00.00	02.24	02.24		B.D, Due to Heavy Rain	
13	Siddipet	Guruvannapet	Tapaspally	11KV		02.24	12.00	09.36		B.D, Due to Heavy Rain	
14	Yadadri	Choutuppal	Town 1	11KV	Choutuppal	09.15	11.30	02.15		11kv Line phase to phase near BC Colony	
15	Yadadri	Varkatpally	Gokaram	11KV	Choutuppal	13.34	14.50	00.58		11kv Insulator Failed near Gakaram Cheruvu	
16	Hyd (North)	Chintal	Caption Gas	11KV	Bowenpally	02.10	03.20	01.10	EL	Conductor snapped at Ocean Pharma Company	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
17	Sangareddy	EPIP-I	Chitrakoot	11KV	Sangareddy	07.51	10.06	02.15		B/D Due to Conductor Snapped	
18	Sangareddy	Patancheru Town	Shanthinagar	11KV	Patancheru	02.10	03.15	01.05		B/D Due to tree branch fallen the line	
19	Sangareddy	Bollaram	Town -I	11KV	Patancheru	05.00	06.50	01.50		B/D Due to Insulator Failure	
20	Sangareddy	Sadasivpet	TSM	11KV	Sangareddy	06.00	10.42	04.42		B/D Due to Insulator Failure	
21	RR (South)	Indira Gandhi Housing society	Payal Food	11KV	RAJENDRA NAGAR	00.10	02.11	02.01	EL	11KV Insulator failed and rectified at Payal Food	
22	RR (South)	Mallapur	Bismillah colony	11KV	KANDUKUR	02.17	06.02	03.45	EL	11KV LAB Switch Post of insulator failed and rectified at Bismillah colony	
23	RR (South)	Manikonda	Lalamma Garden	11KV	IBRAHIMBAGH	04.15	05.20	01.05	EL OL	Two disc failed and rectified at Prerana Hospital, Lalamma Garden	
24	RR (South)	Vattinagulapally	Aparna	11KV	IBRAHIMBAGH	15.15	16.40	01.25	OL	11KV Line cut and rectified at Movie tower Gutta, Aparna	
25	RR (East)	Cherlapally-5	Rampally	11KV	KEESARA	04.04	05.20	01.16	EL	No Visible fault found, Due to Heavy rain	
26	RR (East)	Bandlaguda	Chanikyapuri	11KV	SAROOR NAGAR	12.10	13.50	01.40	EL OL	11KV GSI feeder pole fallen on 11KV chanikyapuri feeder line at 132KV Bandlaguda SS	
27	RR (East)	Bandlaguda	GSI	11KV	SAROOR NAGAR	12.10	13.50	01.40	EL OL	11KV GSI feeder pole fallen on 11KV chanikyapuri feeder line at 132KV Bandlaguda SS (Pole damaged)	
28	RR (East)	Bhagath sing nagar	Shivapuri colony	11KV	SAROOR NAGAR	17.38	19.05	01.27	EL	11KV HT/LT Line cut touched to 11KV line and removed at Kakatiya Colony, Road no 3	