

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0			
2	NLG	22	358	0	0	0	0	0	0			
3	MDK	97	359	0	0	0	0	0	0			
4	SDPT			0	0	0	0	0	0			
5	RR(S)	53	234	0	2	0	2	0	2			
6	RR(N)	54	550	0	3	0	3	0	3			
7	RR(E)	168	403	0	1	0	1	0	1			
8	Hyd	194	1044	0	2	0	2	0	2			
	Total	606	3055	0	8	0	8	0	8	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	0	0	0	0	0	0			
2	NLG	144	988	0	3	0	3	0	3			
3	MDK	107	933	0	0	0	0	0	0			
4	SDPT			1	0	1	0	1	0			
5	RR(S)	58	396	0	0	0	0	0	0			
6	RR(N)	38	114	0	0	0	0	0	0			
7	RR(E)	22	133	0	0	0	0	0	0			
	Total	476	3413	1	3	1	3	1	3	0	0	
	Grand Total	1082	6468	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 21.08.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	Siddipet	Palamakula	Baddipadaga	33KV	Siddipet	16.34	19.56	03.22		B/D for 33KV pin insulator fail		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 21.08.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Medchal	Subhash Nagar	Jeedimetla	11KV	MEDCHAL	14:25	15:20	0:55		11KV Disc Insulator failed at Green Park	
2		Kandlakoya	Godrej IDA	11KV	MEDCHAL	13.14	14.05	00.51		11KV Pin Insulator failed at Poly Plaster Company	
3		Aliabad	Gubba	11KV	MEDCHAL	13.50	14.20	00.30		Bird fallen on the 11KV Line at ESR Petrol Bunk	
4	Nalgonda	Devarkonda	Y.G.Pally	11KV	Devarkonda	06.10	07.35	01.25		11Kv Conductor Snapped	
5		Devarkonda	Erraguntapally	11KV	Devarkonda	08.30	10.00	01.30		11Kv Pin insulator failed	
6		Nalgonda	Ugunavelly	11KV	Nalgonda	09.00	11.35	02.35		11Kv Jumper Cut	
7	Secunderabad	Addagutta	Ganesh Temple	11KV	Paradise	08.58	10.05	01.07	EL,OL-Bph	Disc Insulator flash over at Ganesh Temple	
8		Gunrock	Gymkhana	11KV	Bowenpally	14.13	15.40	01.27	EL	Pin Insulator falsh over at Sector-B, AWHO Colony	
9	RAJENDRA NAGAR	Mallpaur	Bismillah colony	11KV	KANDUKUR	05.39	07.42	02.03	EL	CT/PT Failed & Rectifed RR Atta Company	
10	RAJENDRA NAGAR	Gaganapahad	Meenakshi	11KV	RAJENDRA NAGAR	06.35	11.50	05.15	EL	Pin Insulator Failed & Replaced at BE Industry	
11	SAROOR NAGAR	Prashanth nagar	Jahangeer nagar	11KV	CHAMPAPET	17.35	18.59	01.24	EL	11KV Line snapped & rebinded at Amma Hospital	