

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	14	0	14	0	14	0	14	
6	RR(N)	54	550	0	2	0	2	0	2	0	2	
7	RR(E)	168	403	0	2	0	2	0	2	0	2	
8	Hyd	194	1044	0	4	0	4	0	4	0	4	
	Total	606	3055	0	22	0	22	0	22	0	22	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	0	2	0	2	0	2	0	2	
2	NLG	144	988	0	10	0	10	0	10	0	10	
3	MDK	107	933	0	5	0	5	0	5	0	5	
4	SDPT			1	8	1	8	1	8	1	8	
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	0	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	Total	476	3413	1	25	1	25	1	25	1	25	
	Grand Total	1082	6468	1	47	1	47	1	47	1	47	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 26.08.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	Siddipet	Siddipet	Mittapally		Siddipet	12.20	13.55	01.35	BD LA Balast	BD(LA Blast)		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 26.08.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Habsiguda	Anand Bagh	Krupaanad	11KV	Sainikpuri	06.50	08.15	01.25		Post of Insuletor fail at East Anandbgah Lalitha Nilayam Apt (Artisan/Raju)	
2	Habsiguda	Cherlapally-V	Pedda Cherlapally	11KV	Sainikpuri	18.30	19.50	01.20		11Kv Pin Insuletor fail at Pedda Cherlapally Chourastha (AE/OP)	
3	Mahabubnagar	Boothpur	Boothpur town	11KV	Jadcherla	10.50	12.00	01.10		BD due to 11 KV insulater fail near Sharepally (V)	
4	Mahabubnagar	Gudeballore	KOTHAPALLY	11KV	Narayanpet	02.00	06.30	04.30		Breakdown due to rain and wind	
5	Medak	Chegunta	Chegunta	11KV	Toopran	23.20	03.30	04.10		B/D	
6	Medchal	Devarayamjal	Pothaipally	11KV	Medchal	06.30	07.50	01.20		11KV Pin Insulator Failed at Pothaipally Village backside	
7	Medchal	Kandlakoya	KV Reddy Nagar	11KV	Medchal	07.00	08.40	01.40		Tree Fallen on 11KV Line at Modi Xerox	
8	Nalgonda	Aitipamula	Pamanagundla	11KV	Nalgonda	06.00	08.30	02.30	EL	11KV Line Jumper Cut	
9	Nalgonda	Narketpally	Pothinenipally	11KV	Nalgonda	05.00	07.00	02.00	EL	11KV Line Jumper Cut	
10	Nalgonda	Narketpally	Juvigudem	11KV	Nalgonda	05.30	08.15	02.45	EL	11KV Line Jumper Cut	
11	Nalgonda	Agamothku	Agamothkur	11KV	Miryalaguda	06.10	13.10	07.00	EL	Free branch Fallen on 11 KV Line at Gurrpagudem	
12	Nalgonda	Marriguda	Marriguda	11KV	Devarakonda	10.12	12.00	01.48	EL	HT/LT Wire melt	
13	Sangareddy	Patancheru Town	Town	11KV	Patancheru	06.30	09.10	02.40		B/D Due to tree branch fallen on the line	
14	Sangareddy	Patancheru Town	Town Indl.	11KV	Patancheru	06.00	09.10	03.10		B/D Due to tree branch fallen on the line	
15	Sangareddy	Patancheru Town	Allwyn	11KV	Patancheru	06.45	09.40	02.55		B/D Due to Jumper Cut	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
16	Sangareddy	Inole	Indresham	11KV	Sangareddy	05.20	08.50	03.30		B/D Due to tree branch fallen on the line	
17	Siddipet	Mirdoddy	Mirdoddy	11KV	Siddipet	15.58	17.30	01.32		B/D	
18	Siddipet	Jakkapur	Goplapur	11KV	Siddipet	06.00	11.05	05.05		B/D Disc Fail	
19	Siddipet	Laxmidivipally	Izlampur	11KV	Siddipet	05.00	13.00	08.00		B/D Insulater Fail	
20	Siddipet	Raghothampally	Gosanpally	11KV	Siddipet	15.10	19.00	03.50		B/D Insulater Fail	
21	Siddipet	Pedda Cheekode	Arepally	11KV	Siddipet	16.00	17.15	01.15		B/D	
22	Siddipet	ANAJIPUR	ANAJIPUR	11KV	Gajwel	17.53	18.46	00.53		TREE BRANCH FALL OVER 11KV	
23	Siddipet	Dharmaram	Nandaram	11KV	Husnabad	07.46	11.20	03.34		LT Line joint	
24	Siddipet	Bejjanki	Kallepally	11KV	Husnabad	11.55	16.05	04.10		Tree fallen in line	
25	Suryapet	RAVULAPALLY	Manapuram	11KV	SURYAPET	03.30	06.25	02.55		Jumper cut	
26	Suryapet	Raghunadapalem	Gundlapally	11KV	Huzurnagar	04.00	07.30	03.30		11 kv line snaped	
27	Yadadri	Peddathanda	Pallephad	11KV	Bhongir	06.00	12.20	06.20		11KV Insulator Failed near Ramulthanda Village	
28	Yadadri	Gurraladandi	Raviphad	11KV	Bhongir	05.00	11.20	06.20		2no's 11kv Disc Failed at Gollagudem Village & Raviphad Village	
29	Yadadri	Voligonda	Voligonda Town	11KV	Choutuppal	13.30	14.06	00.36		3no's 11kv Poles Line Snapped near Voligonda Market Yard	
30	Hyd (South)	Miralam	Zoo Park	11KV	Charminar	05.35	07.52	02.17	EL,OL	Tree branches fallen on lines at Mandir	
31	Hyd (North)	Muffakamza College	Nandi Nagar	11KV	Banjara Hills	06.05	07.24	01.19	EL,OL	Pin Insulator flash over at Zaheera Nagar	
32	Hyd (North)	I.D.P.L	Wonder Plast	11KV	Bowenpally	08.05	09.50	01.45	EL,OL	Disc Insulator flash over at HP Petrol Pump	
33	Hyd (Central)	Toli Chowki	Ameena Masjid	11KV	Mehdipatnam	06.50	08.20	01.30	EL,OL-Rph	2No. Disc Insulators flash over at Ameena Masjid	

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
34	RAJENDRA NAGAR	Green Witch	Rehmath colony	11KV	RAJENDRA NAGAR	05.10	06.10	01.00	EL/OL	Due to Rain	
35	RAJENDRA NAGAR	Green Witch	Laxmiguda	11KV	RAJENDRA NAGAR	05.15	07.10	01.55	EL	Due to Rain & 11KV Insulator Failed and Replaced at Aurora College	
36	RAJENDRA NAGAR	APPA	Himayathsagar	11KV	RAJENDRA NAGAR	05.35	07.35	02.00	EL	Due to Rain & 11KV Disc Insulator Failed at APPA Junction	
37	RAJENDRA NAGAR	NPA	Sai Baba nagar	11KV	RAJENDRA NAGAR	05.05	06.20	01.15	EL/OL	Due to Rain	
38	RAJENDRA NAGAR	Upperpally Indoor	Sahara Homes	11KV	RAJENDRA NAGAR	06.20	07.40	01.20	EL	Due to Rain & Tree Branch Fallen on Line at Setwin	
39	RAJENDRA NAGAR	NPA	Babul Reddy Nagar	11KV	RAJENDRA NAGAR	07.05	09.10	02.05	EL/OL	11KV Jumper Cut & Replaced at Lakdikatal	
40	RAJENDRA NAGAR	Mallapur	Balaji Nagar	11KV	KANDUKUR	05.30	07.41	02.11	EL/OL	Due to Rain	
41	RAJENDRA NAGAR	Mallapur	Bismillah Colony	11KV	KANDUKUR	06.09	08.42	02.33	EL/OL	Tree Branch Fallen on Line & Removed at Mallapur	
42	RAJENDRA NAGAR	IGHS	Trishul Metal	11KV	RAJENDRA NAGAR	06.01	10.26	04.25	EL	Due to Rain & 11KV Insulator Failed and Replaced at Mothilal Street	
43	RAJENDRA NAGAR	NPA	Babul Reddy nagar	11KV	RAJENDRA NAGAR	15.45	17.05	01.20	EL/OL	11KV Pin Insulator failed at Fation Plastic	
44	RAJENDRA NAGAR	NPA	Sai Baba nagar	11KV	RAJENDRA NAGAR	15.40	17.35	01.55	EL/OL	11KV Insulator failed at Yallaiah Street	
45	RAJENDRA NAGAR	ICAR	Naram	11KV	RAJENDRA NAGAR	15.44	17.28	01.44	EL	Due to Rain	
46	RAJENDRA NAGAR	Indiragandhi Housing Society	Indira Shivashakthi	11KV	RAJENDRA NAGAR	15.40	17.50	02.10	OL	Tree branches fallen on line at Charminar Brush company & Loads normal	
47	RAJENDRA NAGAR	Indiragandhi Housing Society	Shivaji nagar	11KV	RAJENDRA NAGAR	15.35	18.50	03.15	EL	11KV Disc puncher at Sidhartha Plastic company	