

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	2	0	2	0	2	0	0	
6	RR(N)	54	550	0	8	0	8	0	8	0	0	
7	RR(E)	168	403	0	10	0	10	0	10	0	0	
8	Hyd	194	1044	0	4	0	4	0	4	0	0	
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>24</b>	<b>0</b>	<b>24</b>	<b>0</b>	<b>24</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	0	2	0	2	0	0	0	
2	NLG	144	988	0	13	0	13	0	13	0	0	
3	MDK	107	933	1	0	1	0	1	0	0	0	
4	SDPT			2	0	2	28	2	28	0	0	0
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	28	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>5</b>	<b>41</b>	<b>5</b>	<b>41</b>	<b>5</b>	<b>41</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>65</b>	<b>5</b>	<b>65</b>	<b>5</b>	<b>65</b>	<b>0</b>	<b>0</b>	

**TSSPDCL - LMRC / Corporate office****Circle-wise 33KV Breakdowns****Date: 30.08.2021**

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	Mahabubnagar	Midjil	Velgomula	33KV	Jadcherla	05.40	09.15	03.35	E/L	Tree branch fallen on the line		
2	Mahabubnagar	Narayanpet	Chinnajetram	33KV	Narayanpet	04.50	06.45	01.55	E/L	LA Fail at 33KV Chinnajetram SS		
3	Sangareddy	Kandi	SKOL	33KV	Sangareddy	14.45	18.05	03.20		BD due to Insulator failure		
4	Siddipet	Palamakula	Baddipadaga	33KV	Siddipet	04.40	11.00	06.20		B/D - Insulator fail		
5	Siddipet	Mustyala	Cheriyal	33KV	Husnabad	05.10	18.20	13.10		B/D - Insulator fail		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 30.08.2021

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Habsiguda	Uppal Khalasa	Shanthi Nagar	11KV	Habsiguda	23:15	0:35	1:20		Pin insulator failed at Darbar Bar due to Heavey Rain	
2	Habsiguda	Mallapur	Standard Tiles	11KV	Habsiguda	03.15	05.05	01.50		Tree Fallen 11KV Line at SBI Bank due to Heavey Rain	
3	Habsiguda	Peerazadiguda	Peerazadiguda	11KV	Keesara	20.28	00.20	03.52		11KV Insulator failed at Govt School Back Side	
4	Habsiguda	Nagaram	Bandalguda	11KV	Keesara	03.00	06.26	03.26		2 No's Pin Insulator failed at RGK & Sai garaden	
5	Habsiguda	Keesara	Colector office	11KV	Keesara	09.00	10.30	01.30		Disk Insulator failed at Collector office	
6	Habsiguda	Narapally	Industrial	11KV	Keesara	03.25	04.20	00.55		Copper patty failed at Brundavan Colony	
7	Habsiguda	Narapally	P singaram	11KV	Keesara	10.00	10.45	00.45		Tree fallen 11KV Line at Koremulla Road	
8	Medchal	HMT	Gandhi Nagar	11KV	Medchal	00.01	00.30	00.29		11KV Line AB Switch Opened at Ranga Nagar(11KV Line Cut at Chandra Nagar)	
9	Medchal	Kompally	Nuziveedu Seeds	11KV	Medchal	22.05	23.10	01.05		11KV Jumper Opened at Nuziveedu Bus Stop(2 T/F Off)	
10	Medchal	Sampanbole	Jaganguda	11KV	Medchal	00.34	01.22	00.48		No Fault (Due to Rain)	
11	Medchal	ICICI	Bharath Biotech	11KV	Medchal	01.50	03.50	02.00		No Fault (Due to Rain)	
12	Medchal	Genome Vally	Nectar	11KV	Medchal	04.00	06.00	02.00		11KV Jumper Cut & Replaced in SS	
13	Medchal	Shameerpet	Nalsar	11KV	Medchal	03.40	05.15	01.35		Tree Branches fallen on 11KV Line at Celebraty Resort	
14	Medchal	Kandlakoya	Kandlakoya	11KV	Medchal	01.40	03.20	01.40		No Fault	
15	Nalgonda	B.Banda	Kothapally	11KV	Nalgonda	05.30	08.35	03.05		11 KV Disc Failed	
16	Nalgonda	B.Banda	Thakkalapahad	11KV	Nalgonda	05.00	08.40	03.40		11 KV Jumper Cut	
17	Nalgonda	Pamanagundla	Pittampally	11KV	Nalgonda	06.00	08.39	02.39		11 KV Jumper Cut	
18	Nalgonda	Ch.Annaram	Ch.Annaram	11KV	Nalgonda	00.00	11.00	11.00		11 KV Jumper Cut , 1 no Disc , 1 no Pin Insulator failed & Tree branches fall on the line	

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
19	Nalgonda	Thimmapuram	Kallepally	11KV	Miryalaguda	06.00	09.00	03.00		11KV Jumper cut and touched to crossarm at Kallepally	
20	Nalgonda	Kamareddygudem	Konthalapally	11KV	Miryalaguda	05.00	08.30	03.30		11KV poles fallen due to rain	
21	Yadadri	Bollepally	Jampally	11KV	Bhongir	06.00	10.20	04.20		11kv Line Snapped near Jampally Village Due to Rain	
22	Yadadri	Bondugula	Parupally	11KV	Bhongir	05.00	07.00	02.00		11kv Jumper Snapped near Parupally Village Due to Rain	
23	Yadadri	Raghunathpur	Raghunathpur Indl	11KV	Bhongir	02.00	09.30	07.30		25kva DTR ground Fallen Raghunathpur Village Due to Rain	
24	Yadadri	Manaikunta	Veldavi	11KV	Bhongir	04.00	07.20	03.20		11kv Disc Failed near Veldavi Village Due to Rain	
25	Yadadri	Paladugu	Duppally	11KV	Bhongir	05.55	12.40	06.45		25kva DTR Failed near Datthappagudem Due to Rain	
26	Yadadri	Panthnagi	Panthnagi Indl	11KV	Chaoutuppal	12.15	14.00	01.45		11kv Insulator Failed near Lingoigudem Line Due to Rain	
27	Yadadri	Voligonda	Mandapuram	11KV	Chaoutuppal	11.25	12.30	01.05		11kv Insulator Failed near Madhapur Village Due to Rain	
28	Hyderabad Central	ITI Mallepally	Iliyas Road	11KV	Mehidipatnam	02.20	04.50	02.30	EL,OL	Breaker problem at SS	At 03:15 Hrs partial feeder charged
29	Hyderabad Central	Jawahar Nagar	Ashok Nagar	11KV	Saifabad	02.35	04.50	02.15	EL,OL-Rph	DTR Male Insulator flash over at Paris Gate	At 03:15 Hrs partial feeder charged
30	Banjarahills	H.P.S	Suryoday Complex	11KV	Green Lands	03.09	04.28	01.19	OL-Rph	Double feeding Point Cable fault at Nalli Silks	-----
31	Banjarahills	Kundanbagh	Topaz Building	11KV	Green Lands	07.36	08.58	01.22	All Indication	Breaker problem at SS	Arranged B/F on 11KV Hindu fdr
32	HABSIGUDA	Mallapur-1	Standard Tiles	11KV	HABSIGUDA	03.50	05.05	01.15	EL OL	Tree fallen on 11KV line and removed at SBI Bank Opposite	
33	SAROOR NAGAR	Bairamalguda	Janaki enclave	11KV	CHAMPAPET	00.30	02.10	01.40	EL	Tree branch fallen on line & removed at Janapriya apartment backside	
34	RAJENDRA NAGAR	Kattedan-1	Kattedan-V	11KV	RAJENDRA NAGAR	15.41	16.45	01.04	OL	No visible fault	
35	MEDCHAL	Miyapur X Road	E-Seva	11KV	KUKATPALLY	22.25	23.45	01.20	EL	Pin Insulator failed at Widia Colony	
36	RAJENDRA NAGAR	ICAR	Green Walk	11KV	RAJENDRA NAGAR	23.56	01.33	01.37	EL	Due to heavy Rain	
37	SAROOR NAGAR	RR Court	Kila Maisamma	11KV	SAROOR NAGAR	23.54	01.22	01.28	EL OL	Due to heavy Rain, 11KV Line twisted at NTR nagar	
38	Siddipet	Narsapur	Narsapur		Siddipet	03.10	23.59	20.49		B/D poles fallen down	
39	Siddipet	Nangnoor	Siddannapet		Siddipet	12.30	16.30	04.00		B/D - Poles fallen down	

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
40	Siddipet	Chinnagundavelly	Rampur		Siddipet	02.45	09.00	06.15		B/D - Tree branches fallen on the line	
41	Siddipet	Chinnagundavelly	Chinnagundavelly		Siddipet	04.20	12.30	08.10		B/D - Disk fail	
42	Siddipet	Laxmidivipally	Laxmidivipally		Siddipet	12.25	14.30	02.05		B/D - Bird fallen on the line, 19122	
43	Siddipet	Narayanraopet	Beerappagudi		Siddipet	09.45	14.30	04.45		B/D - Poles fallen down	
44	Siddipet	Kammarlapally	Kammarlapally		Siddipet	08.41	10.46	02.05		B/D - Poles fallen down	
45	Siddipet	Chellapur	Chellapur		Siddipet	00.00	10.00	10.00		B/D - Insulator fail	
46	Siddipet	Peddacheekode	Achmaipally		Siddipet	04.00	12.00	08.00		B/D - Tree branches fallen on the line	
47	Siddipet	Peddacheekode	Achmaipally		Siddipet	12.50	18.20	05.30		B/D - 11KV insulator fail	
48	Siddipet	Gajwel SS	Gajwel Town-I feeder LC.No.9070		Gajwel	6:50	8:10	01.20		Insulator File	
49	Siddipet	BV Pur SS	Industrial Feeder LC.No.9403		Gajwel	11:30	12:49	01.19		11KV line cut	
50	Siddipet	Singatam SS	Anatharao Pally Feeder LC.No. 6261		Gajwel	04.45	12.45	08.00		Disk file	
51	Siddipet	Preganapur SS	Industrial Feeder LC.No.9839		Gajwel	11.40	12.10	00.30		Disk file	
52	Siddipet	Kodakandla SS	Rayawaram Feeder LC.No.9303		Gajwel	14.18	15.41	01.23		HT/LT line Damage tree has fallen	
53	Siddipet	Singatam SS	Singatam Feeder LC.No.6260		Gajwel	6:40	11:30	04.50		HT/LT line Damage tree has fallen	
54	Siddipet	Erravelly SS	Erravelly AGL Feeder LC.25833		Gajwel	12.45	14.12	01.27		Disk file	
55	Siddipet	Gowraram SS	Mailaram Feeder LC.NO.		Gajwel	03.00	23.59	20.59		1-Ph Running (Gowraram SS 7382615668)	
56	Siddipet	Thunki Kalsa SS	Amberpet Feeder LC.No.		Gajwel	12.20	13.05	00.45		only 1 DTR off total feeder Normal for rectification purpose towmmarow LC work well be taken	
57	Siddipet	Nacharam SS	Nacharam Feeder LC.No.11306		Gajwel	07.05	08.00	00.55		11KV line cut	
58	Siddipet	Nacharam SS	Madharam Feeder LC.No.11307		Gajwel	14.50	15.06	00.16		Disk file	
59	Siddipet	Vantimamidi SS	Vantimamidi Feeder LC.No.24367		Gajwel	09.39	13.23	03.44		Tree has fallen on line	
60	Siddipet	Thimmaredypally SS	Mathpally feeder LC.No.9956		Gajwel	15.30	17.30	02.00		11KV pole damaged	
61	Siddipet	Dommata SS	Dommata Feeder LC.No.		Gajwel	08.15	09.30	01.15		Tree branches has fallen on 11KV line	
62	Siddipet	Mubharapur SS	Mubharapur Feeder LC.No.14580		Gajwel	03.00	08.20	05.20		HT/LT line	
63	Siddipet	Mettu SS	Mettu feeder LC.No.6857		Gajwel	09.10	11.50	02.40		11KV Disk fail & Tree has fallen by 11 KV line	
64	Siddipet	Rampur SS	Rampur Feeder LC.No.102262		Gajwel	11.20	12.00	00.40		Jumper Cut	

<b>S. No</b>	<b>Circle</b>	<b>Name of 33/11KV SS</b>	<b>Name of 11 KV Feeder</b>	<b>Vol</b>	<b>Name of the Division</b>	<b>From</b>	<b>To</b>	<b>Duration</b>	<b>Relay Indication</b>	<b>Cause of Breakdown</b>	<b>Alternate Supply Arranged</b>
65	Siddipet	BASVAPUR	BASVAPUR		Husnabad	1:00	13:45	12.45		Jumper Cut	