

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	1	2	1	2	1			
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	2	1	2	1	2	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	SDPT			1	6	1	6	1	6			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	10	1	10	1	10	0	0	
	Grand Total	1082	6468	3	11	3	11	3	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.02.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	Habsipur	Peddacheekodu	33KV	Siddipet	08.05	09.20	01.15		BD (Line probloem)	Peddacheekodu	-
1	RRN	132KV Medchal	33KV Kompally	33KV	Medchal	02.30	08.53	06.23		No Fault(Backfeeding arranged from 33KV Petbasheerabad feeder Time 02:43)	33KV Kompally	-
2		132KV Medchal	33KV GP Pally-II	33KV	Medchal	02.30	09.16	06.46		No Fault(Backfeeding arranged from 33KV Maisammaguda feeder(132KV DP Pally) Time 02:55)	33KV GP Pally-II	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 02.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Repala	Repala	11KV	Huzurnagar	06.45	08.00	01.15	E/L	11Kv Line Snapped	-
2		G.T Giri	G.T Giri Agl	11KV	Suryapet	06.10	07.20	01.10	E/L	11Kv Insulator failed	-
3		Pamanagundla	Erasanigudem	11KV	Nalgonda	08.05	10.00	01.55	E/L	Tree branch fallen on 11Kv line	-
4		Eduloor	Parada	11KV	Nalgonda	10.00	11.40	01.40	E/L	11KV Disc failed	-
1	SDP	Jakkapur	Jakkapur	11KV	Siddipet	07.50	08.15	00.25		B/D - Bird fallen on the line, LC No. 16879	-
2		Habshipur	Habshipur	11KV	Siddipet	15.51	16.15	00.24		B/D - Lt/Lt Line Touch, LC No. 15108	-
3		GANESHPALLY	GANESHPALLY TOWN	11KV	Gajwel	07.05	08.28	01.23		11KV LINE WORK	-
4		THUKKAPUR	THUKKAPUR TOWN	11KV	Gajwel	05.20	12.40	07.20		POLE DAMAGED	-
5		DOULTHABAD	LINGARAJPALLY	11KV	Gajwel	13.30	14.05	00.35		HT / LT	-
6		Chityala	Thadoor	11KV	Husnabad	03.45	07.20	03.35		OL/EL	-
1	RRN	Aleap	Pragathinagar	11KV	Jeedimetla	13.40	15.10	01.30		11kv AB Cable Endkit failed at Monkey Stach,Pragathinagar	-