

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988									
3	MDK	107	933									
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>0</b>	



## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 06.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	SDP	BEJUGAMA	BEJUGAMA	11KV	Gajwel	09.00	11.30	02.30		AB SWITCH COPPER PATTY CUT	-
2		JAGADEVPUR	ALL FEEDERS	11KV	Gajwel	13.40	14.26	00.46		PAD CLAMPS FAILED	-
3		MD SHAPUR	LINGAYPALLY THANDA	11KV	Gajwel	08.08	14.20	06.12		11 KV LINE CUT	-
4		Potharam	Vangaramayapally	11KV	Husnabad	14.40	15.40	01.00		Insulator fail	-
5		Gagillapur	Vallampatla	11KV	Husnabad	11.57	13.02	01.05		Line problem	-
1	RRN	Yellampet	IDA Yellampet	11KV	Medchal	14.17	15.55	01.38	BD	11KV Pole damaged By Car at Sangam Health Care	-
2		Kandlakoya	KV Reddy Nagar	11KV	Medchal	14.40	15.30	00.50	BD	Tree Branches touched on the 11KV Line at Bio Seeds	-