

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	3	1	3	1	3			
3	MDK	107	933	1		1		1				
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>3</b>	<b>5</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 09.02.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	lthole	33KV	Nagarkurnool	00.20	01.50	01.30	OL	AB Switch Opening of Mega Service Due to Conductor Snapped of Mega Service		NO
1	NLG	Miryalaguda	Avanthipuram	33KV	Miryalaguda	05.10	11.00	05.50	E/L	Jumpar Cut and Disc failure		-
1	MDK	Gummadidala	Bonthapally	33KV	Patancheru	20.05	21.45	01.40		BD due to Jumper cut at 132KV SS		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 09.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Madugulapally	Madugulapally Town	11KV	Nalgonda	04.00	07.50	03.50	EL	11KV Insulator Failed	-
2		Narketpally	Mandra	11KV	Nalgonda	05.30	09.00	03.30	EL	11KV Jumper Cut	-
3		Ponugodu	Ponugodu	11KV	Huzurnagar	05.15	08.00	02.45	EL	11 KV LINE SNAPPED	-
1	SDPT	MULUGU SS	NARSAMPALLY AGL	11KV	Gajwel	11.00	13.56	02.56		11KV LINE CUT	-
2		Akkannapet	Pakilnayak Thanda	11KV	Husnabad	08.50	10.30	01.40		Line snapped	-