

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988									
3	MDK	107	933									
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	6	0	6	0	6	0	0	
	Grand Total	1082	6468	0	9	0	9	0	9	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 10.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kosgi	Bhogaram	11KV	Narayanapet	10.00	13.10	03.10		Lorry hitting the poles at Kosgi	-
2		Kosgi	Chennaram	11KV	Narayanapet	12.30	13.20	00.50		Phase to Phase	-
3		Pallerla	Parsapur	11KV	Narayanapet	10.20	11.30	01.10		11KV line cut at Venti Hanuman Tanda	-
1	SDP	Jagadevpur SS	Alirajpet LC: 5795 Narsingarao LI	11KV	Gajwel	00.00	15.10	15.10		Poles Damaged	-
2		Kokkonda SS	Baswapur Industrial	11KV	Gajwel	18.25	21.35	03.10		Tree Cutting	-
3		Lingapur SS	Venkatraopet LC: 20060 Rajesham LM	11KV	Gajwel	09.26	12.10	02.44		11 KV Line Cutting	-
1	RR N	Kolthur	Kolthur	11KV	Medchal	02.40	07.35	04.55	BD	11KV Pole Damged by Car at water plant, Kolthur Village	-
2		GP Pally	GP Pally	11KV	Medchal	06.25	10.30	04.05	BD	Tree Branch fallen & Jumper Cut & Replaced at Ayodhya Chowrast & Veerappagadda	-
1	RR E	St.No.08	Laxmi Nagar	11KV	Habsiguda	12.30	13.25	00.55		11KV UG Cable failed at SS Nagar & B/F supply taken from 11KV Dooradarshan feeder	-