

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		1		1		1			
3	MDK	107	933		1		1		1			
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 12.02.2021

Circle-wise 33KV Breakdowns

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthy	Narsaipally	33KV	Wanaparthy	12.02	13.53	01.51	E/L	33KV Jumper Cut near Kasem Nagar	Narsaipally	-
1	SDPT	Husnabad	Thotapally	33KV	Husnabad	07.17	09.05	01.48	Jumper Cut	B/D due to Jumper Cut	Thotapally	-
1	RR N	132KV Medchal	33KV Athiwelly	33KV	Medchal	10.30	12.05	01.35	BD	Limb failed in SS	33KV Athiwelly	-

## TSSPDCL - LMRC / Corporate office

## Circle-wise 11KV Breakdowns

Date: 12.02.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Sarjakhpet	Thogapur	11KV	Narayanapet	16.18	18.12	01.54		Due to Crow Fallen on 11KV line	-
1	NLG	Kopple	Kopple	11KV	Nalgonda	10.30	12.35	02.05	EL	DTR AB Switch Problem	-
1	MDK	Cheryal	Kandi	11KV	Sangareddy	15.40	17.40	02.00		B/D Due to Jumper cut	-
1	SDPT	Potharam	Potharam Town	11KV	Husnabad	09.36	07.12	12.00		B/D due to line cut	-
2		Bejjanki	Kallepally	11KV	Husnabad	00.00	04.48	04.48		B/D due to Tipper vehicle breaked 4 poles	-
1	RR E	IDA Uppal	Ram Reddy Nagar	11KV	Habsiguda	06.04	06.50	00.46		11KV Cable failed near SS Yard Outside & B/F Supply taken from 11KV Sri Nagar Colony feeder	-
1	HYD N	Alwal	Retreat Colony	11KV	C-VI	14.20	16.10	01.50	EL,OL-Rph	Faulty 4Nos. DTRs at Retreat Colony	